

FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3801 LAKESIDE DR Apt A206 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3801 LAKESIDE DR Apt A206 RICHMOND, CA 94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.8	General Health and Safety/Elevators	O
	1. elevator permit expired	
	2. cover for top of elevator missing, exposed wires, repair	
8.7	General Health and Safety/Other Interior Hazards	O
	1. install CO detector	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3801 LAKESIDE DR Apt A109 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3801 LAKESIDE DR Apt A109 RICHMOND, CA 94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.8 General Health and Safety/Elevators 1. permit expired Tenant/Owner O

2. cover for top of elevator missing, exposed wires, rerpair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3801 LAKESIDE DR Apt A213 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3801 LAKESIDE DR Apt A213 RICHMOND, CA 94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.8 General Health and Safety/Elevators 1. permit expired Tenant/Owner O

2. cover on top of elevator is missing, exposed wires, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3801 LAKESIDE DR Apt B202 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3801 LAKESIDE DR Apt B202 RICHMOND**, CA **94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.8 General Health and Safety/Elevators 1. permit expired

2. cover for top of elevator missing, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3801 LAKESIDE DR Apt B204 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3801 LAKESIDE DR Apt B204 RICHMOND**, CA **94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.8 General Health and Safety/Elevators 1. permit expired Tenant/Owner O

2. cover for top of elevator missing, exposed wires, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3801 LAKESIDE DR Apt B305 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3801 LAKESIDE DR Apt B305 RICHMOND, CA 94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.8 General Health and Safety/Elevators 1. permit expired

2. cover for top of elevator missing, exposed wires, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3811 LAKESIDE DR Apt C105 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3811 LAKESIDE DR Apt C105 RICHMOND, CA 94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.11	Bathroom/Fixed Wash Basin or Lavatory in Unit	O
	tub diverter not working as designed	
3.12	Bathroom/Tub or Shower	O
	1. tub diverter not working as designed, repair	
	2. tub stopper not working as designed, repair	
8.8	General Health and Safety/Elevators	0
0.0	safety permit expired, repair	O



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3811 LAKESIDE DR Apt C107 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3811 LAKESIDE DR Apt C107 RICHMOND, CA 94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.8 General Health and Safety/Elevators safety permit expired, update

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3811 LAKESIDE DR Apt C309 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3811 LAKESIDE DR Apt C309 RICHMOND, CA 94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.13	Bathroom/Ventilation	O
	ventilation fan not working as designed, repair	
8.8	General Health and Safety/Elevators	O
	safety permit expired, update	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3811 LAKESIDE DR Apt C311 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3811 LAKESIDE DR Apt C311 RICHMOND**, CA **94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.8 General Health and Safety/Elevators safety permit expired, update

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3815 LAKESIDE DR Apt E301 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3815 LAKESIDE DR Apt E301 RICHMOND, CA 94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

8.8 General Health and Safety/Elevators
safety permit expired

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3815 LAKESIDE DR Apt E304 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3815 LAKESIDE DR Apt E304 RICHMOND, CA 94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.8 General Health and Safety/Elevators safety permit expired

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3815 LAKESIDE DR Apt E108 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3815 LAKESIDE DR Apt E108 RICHMOND**, CA **94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	<u>Tenant/Owner</u>
2.13	Kitchen/Space for Storage, Prep and Serving	O
	1. countertop trim pulling off	
	2. cabinet door facia peeling/det,repair	
1.8	Living Room/Floor Condition	O
	floor black,repair/replace	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3815 LAKESIDE DR Apt E209 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3815 LAKESIDE DR Apt E209 RICHMOND**, CA **94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.10 Kitchen/Stove or Range with Oven replace drip pans O

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3815 LAKESIDE DR Apt E111 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3815 LAKESIDE DR Apt E111 RICHMOND**, CA **94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/20/2024 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

8.8 General Health and Safety/Elevators

1/4/24 elevator safety permit expired

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3815 LAKESIDE DR Apt F108 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3815 LAKESIDE DR Apt F108 RICHMOND, CA 94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/22/2024 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.8	General Health and Safety/Elevators	O
	The elevator certificate is missing or expired; this represents a SAFETY	
	HAZARD which must be corrected.	
3.11	Bathroom/Fixed Wash Basin or Lavatory in Unit	О
	Handles have excessive corrosion / discoloration.	
	Remove black discoloration around vanity.	
4.2	Other Rooms/Electricity/Illumination	O
	Light fixture making a buzzing sound	
8.7	General Health and Safety/Other Interior Hazards	O
	Throughout unit, door hinges are rusting	

Correct evidence of moisture in unit



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780 Property: 3815 LAKESIDE DR Apt F211 RICHMOND, CA 94806-5744-

PropID:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3815 LAKESIDE DR Apt F211 RICHMOND**, CA **94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/22/2024 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

8.8 General Health and Safety/Elevators
elevator safety permit expired

Tenant/Owner

O

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Hilltop Group Lp VICTORIA CRITCHFIELD 14131 Yorba St Tustin, CA 92780

ry-
3815 LAKESIDE DR Apt F312
RICHMOND, CA 94806-5744-

PropID:

Property:

Client ID: 3800

Dear Owner/Agent,

This letter is to inform you that your property at **3815 LAKESIDE DR Apt F312 RICHMOND, CA 94806-5744 failed** the Housing Quality Standards (HQS) inspection on 01/04/2024.

A re-inspection has been scheduled for 02/22/2024 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.8	Kitchen/Floor Condition	O
	The floor condition poses a danger to the tenant of tripping or falling.	
3.8	Bathroom/Floor Condition	O
	The floor condition poses a danger to the tenant of tripping or falling.	
3.7	Bathroom/Wall Condition	O
	Correct peeling paint	
	Repair wall hole behind shower head	
3.4	Bathroom/Security	O
	Repair / replace damaged door frame	
3.12	Bathroom/Tub or Shower	O
	Bathroom tub or shower head has a leak.	
8.8	General Health and Safety/Elevators	O
	The elevator certificate is missing or expired; this represents a SAFETY	
	HAZARD which must be corrected.	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,