

FAILED INSPECTION NOTICE

Santos & Connie Lam 4851 El Grande Pl El Sobrante, CA 94803-3265 Property: 983 33RD ST RICHMOND, CA 94801-1105-

PropID:

Client ID: 10486

Dear Owner/Agent,

This letter is to inform you that your property at **983 33RD ST RICHMOND**, CA **94801-1105 failed** the Housing Quality Standards (HQS) inspection on 05/12/2025.

A re-inspection has been scheduled for 07/01/2025 between 11:00AM and 02:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.10	Kitchen/Stove or Range with Oven	O
	Range hood has severe peeling paint/rust. replace	
	Front left burner inoperable, repair	
4.5	Other Rooms/Window Condition	T
	Window pane damaged, replace missing/damaged glass	
4.4	Other Rooms/Security	T
	Remove deadbolt from secondary door	
8.1	General Health and Safety/Access to Unit	O
	Rear exterior light inoperable, repair	
6.6	Building Exterior/Lead-Based Paint: Exterior Surfaces	O
	Rear/right exterior siding is dry rotted, repair or replace	
3.5	Bathroom/Window Condition	O
	Window wont stay open without prop, repair	
7.1	Heating and Plumbing/Adequacy of Heating Equipment	O
	Heater inoperable, repair	
2.12	Kitchen/Sink	O
	Dishwasher drains through air gap onto countertop, repair. Drain should go	
	through garbage disposal.	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Gendun Choephel 623 39Th St Richmond, CA 94805 Property: 4017 CLINTON AVE RICHMOND, CA 94805-

PropID:

Client ID: 19523

Dear Owner/Agent,

This letter is to inform you that your property at **4017 CLINTON AVE RICHMOND**, CA **94805 failed** the Housing Quality Standards (HQS) inspection on 05/12/2025.

A re-inspection has been scheduled for 07/01/2025 between 11:00AM and 02:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
6.3	Building Exterior/Condition of Roof and Gutters	O
	Ext. = Gutters Damaged.	
	Front gutter at entry to unit missing portion of downspout, replace	
2.10	Kitchen/Stove or Range with Oven	O
	Left burners not self lighting, repair	
4.4	Other Rooms/Security	O
	Remove sliding latch lock from interior of bedroom door	
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	Install carbon monoxide detector level 1	
3.12	Bathroom/Tub or Shower	T
	Tenant to remove personal items from bathroom on lower level, unable to	
	inspect stand up shower unit.	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Santos & Connie Lam 4851 El Grande Pl El Sobrante, CA 94803-3265 Property: 651 34TH ST RICHMOND, CA 94805-1751-

PropID:

Client ID: 10486

Dear Owner/Agent,

This letter is to inform you that your property at **651 34TH ST RICHMOND**, **CA 94805-1751 failed** the Housing Quality Standards (HQS) inspection on 05/12/2025.

A re-inspection has been scheduled for 07/01/2025 between 11:00AM and 02:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.5	Other Rooms/Window Condition	T
	Patio screen severely torn, repair	
4.4	Other Rooms/Security	T
	Patio screen severely torn, repair	
3.3	Bathroom/Electrical Hazards	O
	Install GFI receptacle above sink	
2.10	Kitchen/Stove or Range with Oven	O
	Front right burner not self lighting/inoperable. Repair	
1.5	Living Room/Window Condition	O
	Units will be required to have screens on one exterior window per room, if	
	the window is openable. The screens must be removable for egress in case	
	of an emergency.	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Cindy M Buff 5327 Sierra Ave Richmond, CA 94805 Property: 665 AMADOR ST RICHMOND, CA 94805-1956-

PropID:

Client ID: 9929

Dear Owner/Agent,

This letter is to inform you that your property at **665 AMADOR ST RICHMOND**, CA **94805-1956 failed** the Housing Quality Standards (HQS) inspection on 05/12/2025.

A re-inspection has been scheduled for 07/01/2025 between 11:00AM and 02:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner_
8.10	General Health and Safety/Site and Neighborhood Conditions	O
	Cut down brush on side of unit by side stairs	
8.1	General Health and Safety/Access to Unit	O
	Remove keyed deadbolt lock from interior on door leading to patio door	
	Remove keyed entry interior deadbolt on rear door leading to exterior	
3.3	Bathroom/Electrical Hazards	O
	Light inoperable, repair	
3.12	Bathroom/Tub or Shower	O
	shower head leaking, repair	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Manuel B & Gladys A Vera 2872 Howard St Richmond, CA 94804 Property: 3601 BISSELL AVE RICHMOND, CA 94805-2159-

PropID:

Client ID: 4507

Dear Owner/Agent,

This letter is to inform you that your property at **3601 BISSELL AVE RICHMOND**, **CA 94805-2159 failed** the Housing Quality Standards (HQS) inspection on 05/12/2025.

A re-inspection has been scheduled for 07/01/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 4.4 Other Rooms/Security Remove keyed lock from interior door.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Manuel B & Gladys A Vera 2872 Howard St Richmond, CA 94804 Property: 3603 BISSELL AVE RICHMOND, CA 94805-2159-

PropID:

Client ID: 4507

Dear Owner/Agent,

This letter is to inform you that your property at **3603 BISSELL AVE RICHMOND**, **CA 94805-2159 failed** the Housing Quality Standards (HQS) inspection on 05/12/2025.

A re-inspection has been scheduled for 07/01/2025 between 01:00PM and 04:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is inoperable or missing. All units must have at least one	
	operable smoke detector on each level. The smoke detector must be	
	placed according to package insturctions.	
4.5	Other Rooms/Window Condition	O
	Right window lock mechanism damaged, repair or replace	
8.1	General Health and Safety/Access to Unit	O
	Rear door missing both striker plates on door frame, install	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Manuel B & Gladys A Vera 2872 Howard St Richmond, CA 94804

Property:
3605 BISSELL AVE
RICHMOND, CA 94805-2159-

PropID:

Client ID: 4507

Dear Owner/Agent,

This letter is to inform you that your property at **3605 BISSELL AVE RICHMOND**, **CA 94805-2159 failed** the Housing Quality Standards (HQS) inspection on 05/12/2025.

A re-inspection has been scheduled for 07/01/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is inoperable or missing. All units must have at least one	
	operable smoke detector on each level. The smoke detector must be	
	placed according to package insturctions.	
4.3	Other Rooms/Elecrtical Hazards	О
	Cover plate on outlet under window damaged, replace	
2.10	Kitchen/Stove or Range with Oven	O
	Rear left burner inoperable, repair	
2.5	Kitchen/Window Condition	О
	Window lock missing, install	
5.4	Secondary Rooms/Other Potential Hazardous Features	O
	Front left nook from entry	

Window lock damaged, replace



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Bailey Property Investments, Inc. 1423 Willow St Oakland, CA 94607-1523 Property: 354 43RD ST RICHMOND, CA 94805-2347-

PropID:

Client ID: 8249

Dear Owner/Agent,

This letter is to inform you that your property at **354 43RD ST RICHMOND**, CA **94805-2347 failed** the Housing Quality Standards (HQS) inspection on 05/12/2025.

A re-inspection has been scheduled for 07/01/2025 between 01:00PM and 04:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.10	Other Rooms/Smoke Detectors	T
	Smoke detector is inoperable or missing. All units must have at least one	
	operable smoke detector on each level. The smoke detector must be	
	placed according to package insturctions.	
4.5	Other Rooms/Window Condition	T
	Window screen torn, repair	
1.8	Living Room/Floor Condition	O
	Carpet bunched up at entry, repair	
8.6	General Health and Safety/Interior Stairs and Common Halls	T
	Common area smoke detector/carbon monoxide detector removed.	
	Replace	
8.2	General Health and Safety/Exits	T
	Cut down brush at rear stairs that is preventing clear path exit to side gate.	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,