

FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt A106 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at **3535 EL PORTAL DR Apt A106 RICHMOND, CA 94806 failed** the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

| Area | REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS | Tenant/Owner |
|------|---|--------------|
| 3.12 | Bathroom/Tub or Shower | O |
| | caulking around tub deteriorating, recaulk around tub | |
| 3.8 | Bathroom/Floor Condition | O |
| | loose tiles .repair | |

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt A202 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at **3535 EL PORTAL DR Apt A202 RICHMOND**, **CA 94806 failed** the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.10 Kitchen/Stove or Range with Oven venthood light inoperable,

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt A308 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at **3535 EL PORTAL DR Apt A308 RICHMOND**, **CA 94806 failed** the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

| Area | REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS | Tenant/Owner_ |
|------|--|---------------|
| 2.10 | Kitchen/Stove or Range with Oven | O |
| | microwave light inop | |
| 3.12 | Bathroom/Tub or Shower | O |
| | tub not draining as designed,repair | |

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt B203 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at **3535 EL PORTAL DR Apt B203 RICHMOND**, **CA 94806 failed** the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit toilet loose in both bathrooms, reset toilets

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

| Creekview Associates L P |
|--------------------------|
| NANCY VERETTE |
| 3535 El Portal Dr |
| El Sobrante, CA 94803 |

Property: 3535 EL PORTAL DR Apt B204 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at **3535 EL PORTAL DR Apt B204 RICHMOND**, **CA 94806 failed** the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

| Area | REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS | Tenant/Owner |
|------|--|--------------|
| 1.8 | Living Room/Floor Condition | O |
| | loose tiles,repair | |
| 2.10 | Kitchen/Stove or Range with Oven | O |
| | microwave light inop | |
| 8.7 | General Health and Safety/Other Interior Hazards | O |
| | common area smoke detector is missing/inoperable. repair/install | |

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt B302 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at 3535 EL PORTAL DR Apt B302 RICHMOND, CA 94806 failed the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

| Area | REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS | Tenant/Owner |
|------|--|--------------|
| 7.4 | Heating and Plumbing/Water Heater | O |
| | hot water turns off and on, check water heater | |
| 3.10 | Bathroom/Flush Toilet in Enclosed Room in Unit | O |
| | toilet loose,reset toilet | |
| 4.10 | Other Rooms/Smoke Detectors | O |
| | Smoke detector is missing/inoperable. All units must have at least one | |
| | operable smoke detector in each bedroom and in a common area on each | |
| | level. | |



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

| Creekview Associates L P |
|--------------------------|
| NANCY VERETTE |
| 3535 El Portal Dr |
| El Sobrante CA 94803 |

Property: 3535 EL PORTAL DR Apt B304 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at **3535 EL PORTAL DR Apt B304 RICHMOND**, **CA 94806 failed** the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

| Area | REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS | Tenant/Owner |
|------|--|--------------|
| 8.7 | General Health and Safety/Other Interior Hazards | O |
| | common area smoke detector missing | |
| 3.10 | Bathroom/Flush Toilet in Enclosed Room in Unit | O |
| | toilet loose,reset toilet | |
| 1.4 | Living Room/Security | O |
| | door frame damaged,repair | |

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt C103 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at 3535 EL PORTAL DR Apt C103 RICHMOND, CA 94806 failed the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

| Area | REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS | Tenant/Owner |
|------|--|--------------|
| 2.12 | Kitchen/Sink | O |
| | strong odor in dishwasher, check dishwasher | |
| 4.10 | Other Rooms/Smoke Detectors | O |
| | Smoke detector is missing/inoperable. All units must have at least one | |
| | operable smoke detector in each bedroom and in a common area on each | |
| | level. | |

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt C201 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at 3535 EL PORTAL DR Apt C201 RICHMOND, CA 94806 failed the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit toilet seat is loose,repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt C206 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at **3535 EL PORTAL DR Apt C206 RICHMOND, CA 94806 failed** the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

| Area | REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS | Tenant/Owner |
|------|--|--------------|
| 2.3 | Kitchen/Electrical Hazards | O |
| | kitchen light bulbs inoperable,repair | |
| 2.12 | Kitchen/Sink | O |
| | faucet loose,repair | |

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt C308 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at 3535 EL PORTAL DR Apt C308 RICHMOND, CA 94806 failed the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.7 General Health and Safety/Other Interior Hazards unit is uninhabitable, damaged throughout

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt D103 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at **3535 EL PORTAL DR Apt D103 RICHMOND, CA 94806 failed** the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Other Rooms/Smoke Detectors Smoke detector is missing/inoperable. All units must have at least one operable smoke detector in each bedroom and in a common area on each level, front bedroom

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt D108 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at **3535 EL PORTAL DR Apt D108 RICHMOND, CA 94806 failed** the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Tenant/Owner

3.12 Bathroom/Tub or Shower

0

1. caulking is deteriorating/discolored,recaulk around tub.

2.tub diverter not working as designed, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

| Creekview Associates L P |
|--------------------------|
| NANCY VERETTE |
| 3535 El Portal Dr |
| El Sobrante CA 94803 |

| Troperty. | |
|--------------------------|----|
| 3535 EL PORTAL DR Apt D2 | 04 |
| RICHMOND, CA 94806- | |

PropID:

Property:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at **3535 EL PORTAL DR Apt D204 RICHMOND, CA 94806 failed** the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

| Area | REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS | Tenant/Owner |
|------|--|--------------|
| 2.10 | Kitchen/Stove or Range with Oven | O |
| | light over stove inoperable,repair | |
| 2.12 | Kitchen/Sink | O |
| | faucet loose, repair | |
| 4.10 | Other Rooms/Smoke Detectors | O |
| | Smoke detector is missing/inoperable. All units must have at least one | |
| | operable smoke detector in each bedroom and in a common area on each | |
| | level. | |
| 3.10 | Bathroom/Flush Toilet in Enclosed Room in Unit | O |
| | toilet loose, reset toilet | |



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 3535 EL PORTAL DR Apt D307 RICHMOND, CA 94806-

PropID:

Property:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at 3535 EL PORTAL DR Apt D307 RICHMOND, CA 94806 failed the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

| Area | REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS | Tenant/Owner |
|------|--|--------------|
| 8.7 | General Health and Safety/Other Interior Hazards | O |
| | common area smoke detector inoperable, repair | |
| 3.12 | Bathroom/Tub or Shower | O |
| | tub diverter not working as designed, repair | |

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt G202 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at 3535 EL PORTAL DR Apt G202 RICHMOND, CA 94806 failed the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

| Area | REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS | Tenant/Owner |
|------|--|--------------|
| 2.10 | Kitchen/Stove or Range with Oven | O |
| | light over stove inoperable,repair | |
| 3.11 | Bathroom/Fixed Wash Basin or Lavatory in Unit | O |
| | loo water pressure,repair | |

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt G301 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at **3535 EL PORTAL DR Apt G301 RICHMOND, CA 94806 failed** the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 3.3 Bathroom/Electrical Hazards Gfi outlet not working as designed,repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

| Creekview Associates L P |
|--------------------------|
| NANCY VERETTE |
| 3535 El Portal Dr |
| El Sobrante CA 94803 |

Property: 3535 EL PORTAL DR Apt G305 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at **3535 EL PORTAL DR Apt G305 RICHMOND, CA 94806 failed** the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

| Area | REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS | Tenant/Owner |
|------|--|--------------|
| 2.10 | Kitchen/Stove or Range with Oven | O |
| | light over stove inoperable | |
| 4.10 | Other Rooms/Smoke Detectors | O |
| | Smoke detector is missing/inoperable. All units must have at least one | |
| | operable smoke detector in each bedroom and in a common area on each | |
| | level. | |
| 1.4 | Living Room/Security | O |
| | sliding door sceen tattered,repair | |



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt F105 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at **3535 EL PORTAL DR Apt F105 RICHMOND, CA 94806 failed** the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 6.2 Building Exterior/Condition of Stairs, Rails, and Porches rear patio Gfi outlet inoperable, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt E102 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at **3535 EL PORTAL DR Apt E102 RICHMOND**, **CA 94806 failed** the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

| Area | REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS | Tenant/Owner |
|------|--|--------------|
| 3.10 | Bathroom/Flush Toilet in Enclosed Room in Unit | O |
| | toilet loose,reset toilet | |
| 3.12 | Bathroom/Tub or Shower | O |
| | caulking deteriorating, recaulk around tub | |

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt E204 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at 3535 EL PORTAL DR Apt E204 RICHMOND, CA 94806 failed the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 3.12 Bathroom/Tub or Shower Otub faucet loose,repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Creekview Associates L P NANCY VERETTE 3535 El Portal Dr El Sobrante, CA 94803 Property: 3535 EL PORTAL DR Apt E305 RICHMOND, CA 94806-

PropID:

Client ID: 6817

Dear Owner/Agent,

This letter is to inform you that your property at 3535 EL PORTAL DR Apt E305 RICHMOND, CA 94806 failed the Housing Quality Standards (HQS) inspection on 09/12/2023.

A re-inspection has been scheduled for 11/10/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 3.13 Bathroom/Ventilation Smoke smell coming from vent

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,