

# FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 625 BERK AVE Apt 1 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 625 BERK AVE Apt 1 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 12/02/2025.

A re-inspection has been scheduled for 01/13/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.



### **FAILED INSPECTION NOTICE**

#### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.4 General Health and Safety/Garbage and Debris
  - Remove excessive amount of personal items and furniture located outside of exterior front door and patio
- 8.7 General Health and Safety/Other Interior Hazards
  - Remove keyed entry lock from hall closet
- 3.12 Bathroom/Tub or Shower
  - Replace missing shower head
- 3.7 Bathroom/Wall Condition
  - Repair damaged wall by toilet
- 8.6 General Health and Safety/Interior Stairs and Common Halls

  Common area smoke detector/carbon monoxide detector inoperable, replace
- 4.10 Other Rooms/Smoke Detectors
  - Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions.
- 4.7 Other Rooms/Wall Condition
  - Repair peeling paint on wall by closet
- 4.4 Other Rooms/Security
  - Remove keyed lock from interior door.
- 4.5 Other Rooms/Window Condition
  - Clean discoloration on window and window seal
- 2.12 Kitchen/Sink
  - 1. Repair damaged sub flooring
  - 2. Garbage disposal inoperable, repair
  - 3. Dishwasher door damaged, repair.
  - 4. Dishwasher drains through air gap, repair as drain must go through garbage disposal.
- 2.10 Kitchen/Stove or Range with Oven
  - Replace missing burner knobs
- 1.4 Living Room/Security
  - Remove latch lock from front door



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 625 BERK AVE Apt 3 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 625 BERK AVE Apt 3 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/13/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.12 Bathroom/Tub or Shower Replace missing baseboard trim
- 3.6 Bathroom/Ceiling Condition
  Clean discoloration on bathroom ceiling
- 3.7 Bathroom/Wall Condition
  Repair peeling paint left of sink
- 4.7 Other Rooms/Wall Condition
  Closet door damaged, repair or remove



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 625 BERK AVE Apt 6 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 625 BERK AVE Apt 6 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/13/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.12 Bathroom/Tub or Shower
  - Resurface tub
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heaters inoperable, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 625 BERK AVE Apt 7 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 625 BERK AVE Apt 7 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/13/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 2.10 Kitchen/Stove or Range with Oven Right/Rear burner inoperable, repair
- 2.7 Kitchen/Wall Condition
  Patch holes on walls in kitchen pantry
- 3.12 Bathroom/Tub or Shower

Resurface tub

- 4.5 Other Rooms/Window Condition
  - Repair damaged window fram on interior side (left window)
- 7.2 Heating and Plumbing/Safety of Heating Equipment
  - Repair heater cover in living room, damaged
- 8.1 General Health and Safety/Access to Unit
  - Patio screen damaged, repair



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 625 BERK AVE Apt 10 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 625 BERK AVE Apt 10 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/13/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

3.12 Bathroom/Tub or Shower Resurface tub

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 625 BERK AVE Apt 12 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 625 BERK AVE Apt 12 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/13/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 2.11 Kitchen/Refrigerator
  - Door not closing as designed, repair
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heaters inoperable, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 635 BERK AVE Apt 1 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 635 BERK AVE Apt 1 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/13/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

4.5 Other Rooms/Window Condition
Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 635 BERK AVE Apt 2 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 635 BERK AVE Apt 2 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/13/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heaters inoperable, repair
- 8.7 General Health and Safety/Other Interior Hazards
  Electrical breaker panel (hall closet) missing lock, replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 635 BERK AVE Apt 6 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 635 BERK AVE Apt 6 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/13/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heaters inoperable, repair
- 8.3 General Health and Safety/Evidence of Infestation Exterminate for rats, mice.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 635 BERK AVE Apt 8 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 635 BERK AVE Apt 8 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/13/2026 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 2.12 Kitchen/Sink
  - 1. Repair leak under sink
  - 2. Dishwasher inoperable, repair
  - 3. Garbage disposal inoperable, repair
  - 4. Subflooring underneath sink damaged from active leak, repair
- 4.5 Other Rooms/Window Condition

Window screen damaged, repair

4.4 Other Rooms/Security

Remove keyed lock from interior door.

7.1 Heating and Plumbing/Adequacy of Heating Equipment

Heaters inoperable, repair

Thermostat cover missing, replace

- 8.1 General Health and Safety/Access to Unit
  - 1. Patio door lock missing, replace
  - 2. Patio door screen damaged, repair
- 8.3 General Health and Safety/Evidence of Infestation

Exterminate for roaches.



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 635 BERK AVE Apt 11 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 635 BERK AVE Apt 11 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/13/2026 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 635 BERK AVE Apt 12 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 635 BERK AVE Apt 12 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/13/2026 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

3.11 Bathroom/Fixed Wash Basin or Lavatory in Unit Bath Sink Cracked/Needs Repair/Replacement.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 645 BERK AVE Apt 3 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 645 BERK AVE Apt 3 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/13/2026 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 1.3 Living Room/Electrical Hazards
  Repair/Replace Wall Electrical Outlet.
  - Replace cracked outlet by patio door and underneath thermostat
- 3.12 Bathroom/Tub or Shower
  - Resurface tub, recalls inside of tub
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heaters inoperable, repair



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 620 S 37TH ST Apt 11 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 620 S 37TH ST Apt 11 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/14/2026 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 1.7 Living Room/Wall Condition hallway walls damaged repair/repaint
- 4.4 Other Rooms/Security bedroom door damaged repair/repalce
- 4.5 Other Rooms/Window Condition clear items/egress blocking window
- 4.10 Other Rooms/Smoke Detectors smoke detector missing
- 4.7 Other Rooms/Wall Condition hole in wall next door repair/replace
- 3.7 Bathroom/Wall Condition all walls in bathroom either damaged or has holes repair/repaint
- 2.13 Kitchen/Space for Storage, Prep and Serving cabinet door missing
- 2.10 Kitchen/Stove or Range with Oven all burners must self ignite



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 630 S 37TH ST Apt 2 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **630 S 37TH ST Apt 2 RICHMOND**, CA **94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/14/2026 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 630 S 37TH ST Apt 3 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **630 S 37TH ST Apt 3 RICHMOND**, CA **94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

### 2.12 Kitchen/Sink

dishwasher door handle damaged - repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 630 S 37TH ST Apt 4 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **630 S 37TH ST Apt 4 RICHMOND**, CA **94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 1.7 Living Room/Wall Condition large hole in wall behind entry door repair/replace
- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit master bedroom toilet base loose and not flushing properly repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 630 S 37TH ST Apt 6 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **630 S 37TH ST Apt 6 RICHMOND**, CA **94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 2.10 Kitchen/Stove or Range with Oven oven inop repair/replace all burners must self ignite repair/repalce
- 2.12 Kitchen/Sink dishwasher inop repair/replace
- 3.12 Bathroom/Tub or Shower shower wall peeling very badly repair/resurface/replace
- 4.10 Other Rooms/Smoke Detectors bedroom smoke inop repair/replace
- 4.4 Other Rooms/Security remove key door locks from all bedroom doors
- 4.2 Other Rooms/Electricity/Illumination bedroom closet light inop repair/replace



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 630 S 37TH ST Apt 7 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **630 S 37TH ST Apt 7 RICHMOND**, CA **94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.12 Bathroom/Tub or Shower faucet dripping repair
- 2.4 Kitchen/Security pantry door striker plate missing repair/replace
- 2.12 Kitchen/Sink hot water not getting hot

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 630 S 37TH ST Apt 8 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **630 S 37TH ST Apt 8 RICHMOND**, CA **94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit toilet base loose repair/replace
- 7.2 Heating and Plumbing/Safety of Heating Equipment water heater earthquake straps missing repair /replace close opening/access allowing birds to get in water heater closet health hazard

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 640 S 37TH ST Apt 3 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **640 S 37TH ST Apt 3 RICHMOND**, CA **94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.4 Other Rooms/Security clear egress from blocking window
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment heater inop repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 640 S 37TH ST Apt 5 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **640 S 37TH ST Apt 5 RICHMOND**, CA **94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

1.4 Living Room/Security patio door not locking properly - repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 640 S 37TH ST Apt 6 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **640 S 37TH ST Apt 6 RICHMOND, CA 94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 640 S 37TH ST Apt 7 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **640 S 37TH ST Apt 7 RICHMOND**, CA **94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 2.10 Kitchen/Stove or Range with Oven all burners must self ignite repair/replace
- 2.11 Kitchen/Refrigerator refrigerator leaking repair/replace
- 2.6 Kitchen/Ceiling Condition pantry ceiling water damaged repair/replace
- 3.11 Bathroom/Fixed Wash Basin or Lavatory in Unit leaking from underneath sink repair/replace
- 4.4 Other Rooms/Security
  remove egress from blocking window
  remove key door lock from bedroom door
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment heater inop repair/repalce
- 8.6 General Health and Safety/Interior Stairs and Common Halls hallway closet light not secured properly repair/replace



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 640 S 37TH ST Apt 8 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **640 S 37TH ST Apt 8 RICHMOND**, CA **94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

2.10 Kitchen/Stove or Range with Oven all burners must self ignite - repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 640 S 37TH ST Apt 9 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **640 S 37TH ST Apt 9 RICHMOND**, **CA 94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.4 Other Rooms/Security remove egress from blocking window
- 8.7 General Health and Safety/Other Interior Hazards hallway smoke/Co detector inop repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 640 S 37TH ST Apt 13 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **640 S 37TH ST Apt 13 RICHMOND**, **CA 94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

7.2 Heating and Plumbing/Safety of Heating Equipment install earthquake straps on water heater

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 640 S 37TH ST Apt 15 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **640 S 37TH ST Apt 15 RICHMOND**, **CA 94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

3.12 Bathroom/Tub or Shower tub peeling - repair/resurface

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 640 S 37TH ST Apt 16 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **640 S 37TH ST Apt 16 RICHMOND**, **CA 94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 2.5 Kitchen/Window Condition screen damaged repair/replace
- 3.12 Bathroom/Tub or Shower hallway tub peeling repair/resuface

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 650 S 37TH ST Apt 3 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **650 S 37TH ST Apt 3 RICHMOND**, CA **94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 2.12 Kitchen/Sink
  - dishwasher not working properly
- 3.11 Bathroom/Fixed Wash Basin or Lavatory in Unit large hole underneath master bedroom bathroom sink repair/replace
- 4.4 Other Rooms/Security remove all key door locks from all bedroom doors
- 4.7 Other Rooms/Wall Condition hole in master bedroom closet wall repair
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment heater inop
- 8.3 General Health and Safety/Evidence of Infestation roach infestation remove
- 8.7 General Health and Safety/Other Interior Hazards hallway smoke/Co detector inop -



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 650 S 37TH ST Apt 7 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **650 S 37TH ST Apt 7 RICHMOND**, CA **94804 failed** the Housing Quality Standards (HQS) inspection on 12/02/2025.

### A re-inspection has been scheduled for 01/15/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heat Not Working Properly. Provide Heat Source.
- 8.7 General Health and Safety/Other Interior Hazards hallway smoke/Co detector missing/inop
- 4.10 Other Rooms/Smoke Detectors bedroom smoke detector missing
- 4.4 Other Rooms/Security door striker plate damaged repair/replace



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,