

FAILED INSPECTION NOTICE

Rong Zhao 431 Matadero Ave Palo Alto, CA 94306-2835 Property: 418 S 18TH ST RICHMOND, CA 94804-2630-

PropID:

Client ID: 9593

Dear Owner/Agent,

This letter is to inform you that your property at **418 S 18TH ST RICHMOND, CA 94804-2630 failed** the Housing Quality Standards (HQS) inspection on 12/05/2025.

A re-inspection has been scheduled for 01/08/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.5 Other Rooms/Window Condition
 Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.
 - 2. Install quick release for security bars or remove
 - 3. Tenant to move items being stored on exterior side of window preventing exit (fire exit cant be blocked)
 - 4. Tenant to clean discoloration window seal



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 760 CARLSON BLVD Apt 3 RICHMOND, CA 94804-4128-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **760 CARLSON BLVD Apt 3 RICHMOND**, CA **94804-4128 failed** the Housing Quality Standards (HQS) inspection on 12/05/2025.

A re-inspection has been scheduled for 01/15/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

2.5 Kitchen/Window Condition screen missing

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804

760 CARLSON BLVD Apt 7 RICHMOND, CA 94804-4128-

PropID:

Property:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **760 CARLSON BLVD Apt 7 RICHMOND**, CA **94804-4128 failed** the Housing Quality Standards (HQS) inspection on 12/05/2025.

A re-inspection has been scheduled for 01/15/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 1.4 Living Room/Security patio screen door damaged repair/replace
- 1.8 Living Room/Floor Condition carpeting throughout unit badly worn repair/replace
- 2.10 Kitchen/Stove or Range with Oven all burners must self ignite
- 3.12 Bathroom/Tub or Shower

 Master bathroom tub and shower walls peeling resurface/repair



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 760 CARLSON BLVD Apt 9 RICHMOND, CA 94804-4128-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **760 CARLSON BLVD Apt 9 RICHMOND**, CA **94804-4128 failed** the Housing Quality Standards (HQS) inspection on 12/05/2025.

A re-inspection has been scheduled for 01/15/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.11 Bathroom/Fixed Wash Basin or Lavatory in Unit sink handle not properly secured repair/replace sink stopper missing repair/replace
- 3.12 Bathroom/Tub or Shower tub overflow drain plate missing repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 760 CARLSON BLVD Apt 10 RICHMOND, CA 94804-4128-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **760 CARLSON BLVD Apt 10 RICHMOND, CA 94804-4128 failed** the Housing Quality Standards (HQS) inspection on 12/05/2025.

A re-inspection has been scheduled for 01/15/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

4.8 Other Rooms/Floor Condition carpet damaged badly in front of bedroom door - repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 760 CARLSON BLVD Apt 12 RICHMOND, CA 94804-4128-

PropID:

Property:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **760 CARLSON BLVD Apt 12 RICHMOND, CA 94804-4128 failed** the Housing Quality Standards (HQS) inspection on 12/05/2025.

A re-inspection has been scheduled for 01/15/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.12 Bathroom/Tub or Shower tub peeling resurface/repair
- 3.13 Bathroom/Ventilation vent fan not working properly repair/replace
- 4.4 Other Rooms/Security
 bedroom door damaged repair/replace
 door knob not properly secured repair/replace



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,