

FAILED INSPECTION NOTICE

Patrick P & Nancy A Cheung 5720 Jefferson Ave Richmond, CA 94804-4865 Property: 3307 HUMPHREY AVE RICHMOND, CA 94804-1187-

PropID:

Client ID: 10009

Dear Owner/Agent,

This letter is to inform you that your property at **3307 HUMPHREY AVE RICHMOND**, CA **94804-1187 failed** the Housing Quality Standards (HQS) inspection on 05/09/2025.

A re-inspection has been scheduled for 07/17/2025 between 09:00AM and 12:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.5	Other Rooms/Window Condition	O
	Units will be required to have screens on one exterior window per room, if	
	the window is openable. The screens must be removable for egress in case	
	of an emergency.	
	Tenant to clean discoloration on window and window seal	
6.4	Building Exterior/Condition of Exterior Surfaces	O
	Exterior dryer vent missing cover, install	
5.3	Secondary Rooms/Electrical Hazards	O
	Garage GFI has hot/nuetral reverse, repair	
3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
	Bath Toilet not secured properly to floor.	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Jose Luis Ledesma 420 29Th St Richmond, CA 94804-1737 Property: 426 29TH ST RICHMOND, CA 94804-1737-

PropID:

Client ID: 13017

Dear Owner/Agent,

This letter is to inform you that your property at **426 29TH ST RICHMOND**, **CA 94804-1737 failed** the Housing Quality Standards (HQS) inspection on 05/09/2025.

A re-inspection has been scheduled for 07/17/2025 between 09:00AM and 12:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.12	Bathroom/Tub or Shower	O
	Glass shower doors missing safety guides, install	
	Tub spout missing, install	
	Tub knobs stripped, repair	
2.12	Kitchen/Sink	O
	Secure dishwasher to countertop	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Jose Luis Ledesma 420 29Th St Richmond, CA 94804-1737 Property: 428 29TH ST RICHMOND, CA 94804-1737-

PropID:

Client ID: 13017

Dear Owner/Agent,

This letter is to inform you that your property at **428 29TH ST RICHMOND**, **CA 94804-1737 failed** the Housing Quality Standards (HQS) inspection on 05/09/2025.

A re-inspection has been scheduled for 07/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	Interior common area smoke detector/carbon monoxide detector	
	inoperable, repair or replace	
7.1	Heating and Plumbing/Adequacy of Heating Equipment	O
	Heater inoperable, repair	
4.3	Other Rooms/Elecrtical Hazards	T
	No access to outlets for testing, excessive amount of items lined up on all	
	walls in room. Tenant to provide access to outlets for testing.	
4.5	Other Rooms/Window Condition	T
	No access to window, tenant to move items blocking window (fire exit)	
3.3	Bathroom/Electrical Hazards	O
	Install GFI outlet above sink	
2.10	Kitchen/Stove or Range with Oven	O
	Range hood light inoperable, repair	

Install range hood vent screen



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Linda L Daigre Po Box 70800 Richmond, CA 94804 Property: 311 S 17TH ST RICHMOND, CA 94804-2605-

PropID:

Client ID: 5627

Dear Owner/Agent,

This letter is to inform you that your property at **311 S 17TH ST RICHMOND**, CA **94804-2605 failed** the Housing Quality Standards (HQS) inspection on 05/09/2025.

A re-inspection has been scheduled for 07/17/2025 between 09:00AM and 12:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.7	Bathroom/Wall Condition	O
	Repair walls in bathroom, evidence of water damage causing peeling paint	
	and soft spots.	
4.10	Other Rooms/Smoke Detectors	T
	Smoke detector is inoperable or missing. All units must have at least one	
	operable smoke detector on each level. The smoke detector must be	
	placed according to package insturctions.	
7.1	Heating and Plumbing/Adequacy of Heating Equipment	O
	Heater inoperable, repair	
8.7	General Health and Safety/Other Interior Hazards	O
	Install common area smoke detector in front portion of unit.	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Robert Vardanega Po Box 13249 Oakland, CA 94661-0249 Property: 400 S 34TH ST RICHMOND, CA 94804-3122-

PropID:

Client ID: 7421

Dear Owner/Agent,

This letter is to inform you that your property at **400 S 34TH ST RICHMOND**, **CA 94804-3122 failed** the Housing Quality Standards (HQS) inspection on 05/09/2025.

A re-inspection has been scheduled for 07/17/2025 between 09:00AM and 12:00PM.



FAILED INSPECTION NOTICE

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.4	Other Rooms/Security	T
	Remove key entry lock from bedroom door	
4.5	Other Rooms/Window Condition	T
	Clean discoloration in bedroom window and closet window	
1.4	Living Room/Security	T
	Remove keyed entry lock from door that leads to living room	
1.3	Living Room/Electrical Hazards	O
	Receptacle next to heater has open grounds, repair	
2.10	Kitchen/Stove or Range with Oven	O
	Range hood light inoperable, repair	
	TENANT TO CLEAN GREASE SPLATTER ON STOVE AND	
	RANGE HOOD	
7.1	Heating and Plumbing/Adequacy of Heating Equipment	О
	Heater inoperable, repair	
4.3	Other Rooms/Elecrtical Hazards	O
	Three prong outlet not testing as designed, must be grounded or replaced	
	with a GFCI.	
8.10	General Health and Safety/Site and Neighborhood Conditions	T
	No access to rear yard, large loose dog in yard. Tenant to secure pets so	
	yard can be inspected	
8.4	General Health and Safety/Garbage and Debris	T
	Declutter yard, excessive clutter and trash in yard	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Shujun Lao 1309 Greenway Dr El Sobrante, CA 94803 Property: 376 BECK ST RICHMOND, CA 94804-3131-

PropID:

Client ID: 5169

Dear Owner/Agent,

This letter is to inform you that your property at **376 BECK ST RICHMOND**, CA **94804-3131 failed** the Housing Quality Standards (HQS) inspection on 05/09/2025.

A re-inspection has been scheduled for 07/17/2025 between 09:00AM and 12:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.4	General Health and Safety/Garbage and Debris	T
	Declutter yard, excessive amount of personal belongings in shared common	
	area	
1.4	Living Room/Security	O
	Front door missing striker plate, install	
1.5	Living Room/Window Condition	O
	Units will be required to have screens on one exterior window per room, if	
	the window is openable. The screens must be removable for egress in case	
	of an emergency.	
4.4	Other Rooms/Security	T
	Remove keyed lock from interior door.	
4.5	Other Rooms/Window Condition	O
	Units will be required to have screens on one exterior window per room, if	
	the window is openable. The screens must be removable for egress in case	
	of an emergency.	
3.5	Bathroom/Window Condition	O
	Bathroom screen torn, repair	
2.10	Kitchen/Stove or Range with Oven	O
	Burners are not self lighting, repair	
5.2	Secondary Rooms/Security	T
	Remove keyed deadbolt entry lock on garage entry	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Shujun Lao 1309 Greenway Dr El Sobrante, CA 94803 Property: 374 BECK ST RICHMOND, CA 94804-3131-

PropID:

Client ID: 5169

Dear Owner/Agent,

This letter is to inform you that your property at **374 BECK ST RICHMOND**, CA **94804-3131 failed** the Housing Quality Standards (HQS) inspection on 05/09/2025.

A re-inspection has been scheduled for 07/17/2025 between 09:00AM and 12:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.10	Other Rooms/Smoke Detectors	T
	Smoke detector is inoperable or missing. All units must have at least one	
	operable smoke detector on each level. The smoke detector must be	
	placed according to package insturctions.	
4.3	Other Rooms/Elecrtical Hazards	O
	Replace damaged receptacle on left wall. Something is broken inside one of	
	the plugs	
4.5	Other Rooms/Window Condition	O
	Units will be required to have screens on one exterior window per room, if	
	the window is openable. The screens must be removable for egress in case	
	of an emergency.	
3.3	Bathroom/Electrical Hazards	O
	REPLACE GFI, inoperable and will not reset	
2.6	Kitchen/Ceiling Condition	O
	Kitchen vent fan makes loud grinding noise while in use, repair	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

James O & Shirley Guinn 119 Pine Valley Ct Fairfield, CA 94534-7822 Property: 5049 REID CT RICHMOND, CA 94804-4404-

PropID:

Client ID: 1431

Dear Owner/Agent,

This letter is to inform you that your property at **5049 REID CT RICHMOND**, CA **94804-4404 failed** the Housing Quality Standards (HQS) inspection on 05/09/2025.

A re-inspection has been scheduled for 07/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.10	Other Rooms/Smoke Detectors	T
	Smoke detector in master bedroom missing, replace	
6.4	Building Exterior/Condition of Exterior Surfaces	O
	Exterior outlet missing weatherproof cover, install	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Suzanne Hendler 709 Buchanan St San Francisco, CA 94102 Property: 806 S 47TH ST RICHMOND, CA 94804-4423-

PropID:

Client ID: 6726

Dear Owner/Agent,

This letter is to inform you that your property at **806 S 47TH ST RICHMOND**, CA **94804-4423 failed** the Housing Quality Standards (HQS) inspection on 05/09/2025.

A re-inspection has been scheduled for 07/17/2025 between 11:00AM and 02:00PM.



FAILED INSPECTION NOTICE

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.10	Other Rooms/Smoke Detectors	T
	Smoke detector is inoperable or missing. All units must have at least one	
	operable smoke detector on each level. The smoke detector must be	
	placed according to package insturctions.	
4.5	Other Rooms/Window Condition	T
	Clean discoloration in window	
8.2	General Health and Safety/Exits	T
	Tenant to move furniture blocking access to window in right bedroom	
3.3	Bathroom/Electrical Hazards	O
	Install GFI above sink	
3.11	Bathroom/Fixed Wash Basin or Lavatory in Unit	O
	Sink Clogged.	
8.7	General Health and Safety/Other Interior Hazards	T
	Common area smoke detector removed, replace	
2.13	Kitchen/Space for Storage, Prep and Serving	O
	Kit. = Missing Cabinet Door.	
2.12	Kitchen/Sink	O
	Dishwasher has rust/peeling paint. replace, repair or remove	
8.1	General Health and Safety/Access to Unit	O
	Light above rear door inoperable, repair	
5.2	Secondary Rooms/Security	T
	Remove chain lock from garage door on interior side of kitchen	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Robert R & Christine Pangelina 1350 Monterey St Richmond, CA 94804-4943

Property:
1348 MONTEREY ST
RICHMOND, CA 94804-4943

PropID:

Client ID: 2080

Dear Owner/Agent,

This letter is to inform you that your property at **1348 MONTEREY ST RICHMOND**, **CA 94804-4943 failed** the Housing Quality Standards (HQS) inspection on 05/09/2025.

A re-inspection has been scheduled for 07/17/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.3	Bathroom/Electrical Hazards	O
	Install GFI protected outlet above sink	
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	Replace common area smoke detector as test button is damaged.	
7.1	Heating and Plumbing/Adequacy of Heating Equipment	O
	Heater inoperable, repair	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Pai-Yau & Hsin-Yi Tsai 2815 Las Gallinas Ave San Rafael, CA 94903-1428 Property: 1551 MARIPOSA ST RICHMOND, CA 94804-5015-

PropID:

Client ID: 1146

Dear Owner/Agent,

This letter is to inform you that your property at **1551 MARIPOSA ST RICHMOND**, CA **94804-5015 failed** the Housing Quality Standards (HQS) inspection on 05/09/2025.

A re-inspection has been scheduled for 07/17/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u> Area</u>	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.5	Bathroom/Window Condition	O
	Window is missing lock, install locking mechanism on window.	
2.10	Kitchen/Stove or Range with Oven	O
	Rear left burner not self lighting, repair	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,