

FAILED INSPECTION NOTICE

Michael & Heide Hughey Po Box 1580 El Cerrito, CA 94530 Property: 2355 RHEEM AVE RICHMOND, CA 94804-1017-

PropID:

Client ID: 3911

Dear Owner/Agent,

This letter is to inform you that your property at 2355 RHEEM AVE RICHMOND, CA 94804-1017 failed the Housing Quality Standards (HQS) inspection on 06/08/2023.

A re-inspection has been scheduled for 07/25/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.4 Kitchen/Security rear door blocked, no egress

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Lester & Hertiscine Lawson 2731 Wright Ave Pinole, CA 94564 Property: 753 S 49TH ST RICHMOND, CA 94804-4426-

PropID:

Client ID: 4184

Dear Owner/Agent,

This letter is to inform you that your property at **753 S 49TH ST RICHMOND**, **CA 94804-4426 failed** the Housing Quality Standards (HQS) inspection on 06/08/2023.

A re-inspection has been scheduled for 07/25/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Other Rooms/Smoke Detectors Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. front bedroom

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Droparty.

Client ID: 11358

Troperty.
5517 HUNTINGTON AVE
RICHMOND, CA 94804-5503-
MCINIOND, CA 74004-3303-
PropID:

Dear Owner/Agent,

This letter is to inform you that your property at **5517 HUNTINGTON AVE RICHMOND**, CA **94804-5503 failed** the Housing Quality Standards (HQS) inspection on 06/08/2023.

A re-inspection has been scheduled for 07/25/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.3	Kitchen/Electrical Hazards	O
	light inop, repair	
3.6	Bathroom/Ceiling Condition	O
	under constuction due to leak, finish repair	
3.7	Bathroom/Wall Condition	O
	under constuction due to leak, finish repair	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

George F Bennett 44 Sequoia Rd Fairfax, CA 94930 Property: 5838 PANAMA AVE RICHMOND, CA 94804-5522-

PropID:

Client ID: 9002

Dear Owner/Agent,

This letter is to inform you that your property at **5838 PANAMA AVE RICHMOND**, **CA 94804-5522 failed** the Housing Quality Standards (HQS) inspection on 06/08/2023.

A re-inspection has been scheduled for 07/25/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
	toilet not flushing as designed, repair	
3.12	Bathroom/Tub or Shower	O
	tub rusting, resurface tub	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Qing Shan Huang 56 Ellington Ave San Francisco, CA 94112 Property: 3615 CHANSLOR AVE RICHMOND, CA 94805-

PropID:

Client ID: 17508

Dear Owner/Agent,

This letter is to inform you that your property at **3615 CHANSLOR AVE RICHMOND**, **CA 94805 failed** the Housing Quality Standards (HQS) inspection on 06/08/2023.

A re-inspection has been scheduled for 07/25/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.12	Bathroom/Tub or Shower	O
	tub rusting, resurface tub	
8.7	General Health and Safety/Other Interior Hazards	O
	install common smoke rear inlaw suite	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Paul W & Melva W Hirsh 849 Kensington Rd El Cerrito, CA 94530-2747

Property:
936 LASSEN ST
RICHMOND, CA 94805-1031-

PropID:

Client ID: 7126

Dear Owner/Agent,

This letter is to inform you that your property at 936 LASSEN ST RICHMOND, CA 94805-1031 failed the Housing Quality Standards (HQS) inspection on 06/08/2023.

A re-inspection has been scheduled for 07/25/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.6	Bathroom/Ceiling Condition	O
	remove excessive black discoloration	
3.7	Bathroom/Wall Condition	O
	remove excessive black discoloration	
4.5	Other Rooms/Window Condition	O
	remove excessive black discoloration	
5.3	Secondary Rooms/Electrical Hazards	O
	laundryroom light inop, repair	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is inoperable or missing. All units must have at least one	
	operable smoke detector on each level. The smoke detector must be	
	placed according to package insturctions.	
8.7	General Health and Safety/Other Interior Hazards	O
	Unit must have one carbon monoxide detector working per level.	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Michael & Heide Hughey Po Box 1580 El Cerrito, CA 94530 Property: 3320 BARRETT AVE RICHMOND, CA 94805-2138-

PropID:

Client ID: 3911

Dear Owner/Agent,

This letter is to inform you that your property at **3320 BARRETT AVE RICHMOND, CA 94805-2138 failed** the Housing Quality Standards (HQS) inspection on 06/08/2023.

A re-inspection has been scheduled for 07/25/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.12	Kitchen/Sink	O
	sink peeling, resurface/repair	
3.12	Bathroom/Tub or Shower	O
	1. tub peeling, resurface	
	2. tub is missing overflow valve	
	3. shower enclosure cracked tile, repair	
3.3	Bathroom/Electrical Hazards	O
	gfi will not test/reset	
1.4	Living Room/Security	T
	no eggress, all entry/exit doors must be accessible in case of emergency	
1.7	Living Room/Wall Condition	T
	repair hole in wall	
7.1	Heating and Plumbing/Adequacy of Heating Equipment	T
	heater inop, repair	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Michael & Heide Hughey Po Box 1580 El Cerrito, CA 94530 Property: 3913 NEVIN AVE RICHMOND, CA 94805-2236-

PropID:

Client ID: 3911

Dear Owner/Agent,

This letter is to inform you that your property at **3913 NEVIN AVE RICHMOND**, **CA 94805-2236 failed** the Housing Quality Standards (HQS) inspection on 06/08/2023.

A re-inspection has been scheduled for 07/25/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Other Rooms/Smoke Detectors Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Thao Thi Thanh Nguyen Chuck Liu 766 Harrison St Suite 104 San Francisco, CA 94107 Property: 4312 NEVIN AVE RICHMOND, CA 94805-2344-

PropID:

Client ID: 18843

Dear Owner/Agent,

This letter is to inform you that your property at **4312 NEVIN AVE RICHMOND**, CA **94805-2344 failed** the Housing Quality Standards (HQS) inspection on 06/08/2023.

A re-inspection has been scheduled for 07/25/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
1.3	Living Room/Electrical Hazards	O
	light fixture inop, repair	
2.3	Kitchen/Electrical Hazards	O
	light fixture inop, repair	
2.10	Kitchen/Stove or Range with Oven	O
	stove knobs broken/missing, replace	
4.3	Other Rooms/Elecrtical Hazards	O
	master bedroom light/fan inop, repair	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,