

FAILED INSPECTION NOTICE

Charles Lamount Fuller 501 Enterprise Ave #B Richmond, CA 94801-2276 Property: 501 ENTERPRISE AVE Apt A RICHMOND, CA 94801-2276-

PropID:

Client ID: 8036

Dear Owner/Agent,

This letter is to inform you that your property at **501 ENTERPRISE AVE Apt A RICHMOND, CA 94801-2276 failed** the Housing Quality Standards (HQS) inspection on 06/30/2023.

A re-inspection has been scheduled for 08/08/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.7	General Health and Safety/Other Interior Hazards	T
	1.clean unit, unsanitary conditions	
3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
	replace missing toilet top	
8.6	General Health and Safety/Interior Stairs and Common Halls	T
	co detector inop, repair/replace	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

David H & Bong T Gillis 709 Ventura St Richmond, CA 94805 Property: 5012 MCBRYDE AVE RICHMOND, CA 94805-1037-

PropID:

Client ID: 1754

Dear Owner/Agent,

This letter is to inform you that your property at **5012 MCBRYDE AVE RICHMOND, CA 94805-1037 failed** the Housing Quality Standards (HQS) inspection on 06/30/2023.

A re-inspection has been scheduled for 08/07/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.3	Other Rooms/Elecrtical Hazards	O
	1. light fixture inop, repair	
	2. light switch cover broken, replace	
2.12	Kitchen/Sink	O
	faucet loose, repair	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is missing. All units must have at least one operable smoke	
	detector in each bedroom and in a common area on each level.	
8.7	General Health and Safety/Other Interior Hazards	O
	install common area smoke detector	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Fu-Chung Wang
1074 Orchard Rd
Lafayette, CA 94549-3140

Property:
572 KEY BLVD
RICHMOND, CA 94805-1919

PropID:

Client ID: 11113

Dear Owner/Agent,

This letter is to inform you that your property at **572 KEY BLVD RICHMOND**, CA **94805-1919 failed** the Housing Quality Standards (HQS) inspection on 06/30/2023.

A re-inspection has been scheduled for 08/07/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.3	Bathroom/Electrical Hazards	O
	Gfi outlet will not test/reset, replace/repair	
3.12	Bathroom/Tub or Shower	O
	tub diverter not working as designed, repair front bath	
1.6	Living Room/Ceiling Condition	O
	repair cracking on ceiling in livingroom/diningroom	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

	Property:	
Timothy Kwong W & Monica Yuen Ming Lam	543 44TH ST	
Sun	RICHMOND, CA 94805-2357-	
Monica Sun		
123 Wiggins Ct	PropID:	
Pleasant Hill, CA 94553	тюрь.	
,,,,	Client ID: 11025	

Dear Owner/Agent,

This letter is to inform you that your property at **543 44TH ST RICHMOND, CA 94805-2357 failed** the Housing Quality Standards (HQS) inspection on 06/30/2023.

A re-inspection has been scheduled for 08/07/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.10	Other Rooms/Smoke Detectors	О
	1.install co detector in rear room with enclosed heater	
	2. Smoke detector is missing. All units must have at least one operable	
	smoke detector in each bedroom and in a common area on each level.	
3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
	replace worn/deteriorating toilet seat	
2.10	Kitchen/Stove or Range with Oven	O
	replace deteriorating drip pans	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Juan Alberto Cheung Ho 109 Stout Hercules, CA 94547 Property: 5105 CADDIE CT RICHMOND, CA 94806-

PropID:

Client ID: 16354

Dear Owner/Agent,

This letter is to inform you that your property at **5105 CADDIE CT RICHMOND**, CA **94806 failed** the Housing Quality Standards (HQS) inspection on 06/30/2023.

A re-inspection has been scheduled for 08/08/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.10 Kitchen/Stove or Range with Oven all burners must self-ignite

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,