

FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 111 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 111 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.10	Other Rooms/Smoke Detectors	О
	Smoke detector has low audible alert, replace	
3.13	Bathroom/Ventilation	T
	Tenant to clean vent fan in bathroom located in right bedroom	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 112 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 112 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 3.12 Bathroom/Tub or Shower Shower head leaking in rear, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806

2601 HILLTOP DR Apt 113 RICHMOND, CA 94806-5783-

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 113 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.3	Bathroom/Electrical Hazards	
	Light above toilet inoperable, repair	
3.12	Bathroom/Tub or Shower	O
	Tub diverter stuck in shower mode, repair	
	TENANT TO CLEAN BLACK DISCOLORATION IN TUB	
3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
	Flush mechanism damaged, toilet will not flush, repair	
4.4	Other Rooms/Security	T
	Tenant to move items behind door so that it can open as designed	
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	Common area smoke detector/carbon monoxide detector inoperable,	
	replace	
2.10	Kitchen/Stove or Range with Oven	O
	Range hood light inoperable, repair	
2.12	Kitchen/Sink	O
	Dishwasher inoperable, repair	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 114 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 114 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.12	Bathroom/Tub or Shower	O
	Tub Drain Clogged/Slow.	
2.10	Kitchen/Stove or Range with Oven	O
	Range hood vent screens missing, install	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 115 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 115 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.12	Bathroom/Tub or Shower	O
	Tub diverter inoperable as tub runs at same time as shower, repair	
2.12	Kitchen/Sink	O
	Dishwasher inoperable, repair	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 2601 HILLTOP DR Apt 116 RICHMOND, CA 94806-5783-

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 116 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Tenant/Owner			
8.4	4 General Health and Safety/Garbage and Debris T			
	Tenant to declutter unit			
3.3	Bathroom/Electrical Hazards	O		
	Light above toilet inoperable, repair			
2.12	Kitchen/Sink	O		
	Garbage disposal inoperable, repair			
2.10	Kitchen/Stove or Range with Oven	O		
	Front left burner not self lighting, repair			



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 117 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 117 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Tenant/Owner 7.4 Heating and Plumbing/Water Heater Tenant to remove personal items in water heater closet, water heater must remain free and clear of items

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 121 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 121 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.10 Kitchen/Stove or Range with Oven Range hood vent screens missing, install

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 125 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 125 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 3.3 Bathroom/Electrical Hazards Ceiling light inoperable, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 126 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 126 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.12 Kitchen/Sink Rubber splash guard damaged, replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 127 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 127 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

3.12 Bathroom/Tub or Shower

Tub Drain Clogged/Slow.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 128 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 128 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.12	Kitchen/Sink	O
	Dishwasher inoperable, repair	
	Garbage disposal inoperable, repair	
2.10	Kitchen/Stove or Range with Oven	O
	Right rear burner not self lighting, repair	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 2601 HILLTOP DR Apt 132 RICHMOND, CA 94806-5783-

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 132 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Tenant/Owner			
8.4	General Health and Safety/Garbage and Debris T			
	Tenant to declutter unit, excessive clutter throughout unit and on patio			
1.3	Living Room/Electrical Hazards	T		
	No access to outlets due to excessive clutter			
2.12	Kitchen/Sink	O		
	Dishwasher inoperable, repair			
2.10	Kitchen/Stove or Range with Oven	T		
	Excessive amount of items stored on stove, unable to test during inspection.			
	Tenant to declutter items on stove.			



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1015 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1015 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/04/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.6 General Health and Safety/Interior Stairs and Common Halls Broken closet doors, repair or replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1025 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1025 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/04/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Tell Tell			
3.7	Bathroom/Wall Condition	T		
	remove black discoloration			
3.12	Bathroom/Tub or Shower	O		
	Chipping peeling paint above shower head remove or repaint.			

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1031 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1031 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/04/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 3.3 Bathroom/Electrical Hazards master bedroom.foreign object stuck inside of GFCI outlet. repair or replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1033 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1033 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/04/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 7.4 Heating and Plumbing/Water Heater water heater leaking from bottom repair or replace.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 133 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 133 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.11	Kitchen/Refrigerator	O
	Refrigerator light inoperable, repair	
7.4	Heating and Plumbing/Water Heater	T
	Clear items surrounding water heater in closet	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 135 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 135 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.5	Other Rooms/Window Condition	T
	Tenant to move furniture blocking access to window (fire exit)	
4.4	Other Rooms/Security	T
	Remove digital lock from bedroom door	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 137 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 137 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.12	Bathroom/Tub or Shower	O
	Tub diverter inoperable as tub runs with shower, repair	
2.10	Kitchen/Stove or Range with Oven	O
	Range hood vent screen missing, install	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 138 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 138 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.4 General Health and Safety/Garbage and Debris Remove appliances from patio

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806

	•	•	
2	601	HILI	TOP DR Apt 212
R	ICH	MON	ND, CA 94806-5783

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 212 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	Common area smoke detector/carbon monoxide detector missing/removed.	
	Replace	
8.1	General Health and Safety/Access to Unit	O
	Patio screen off track, repair	
	Patio light inoperable, repair	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 213 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 213 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/02/2025.

A re-inspection has been scheduled for 08/01/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.12	Kitchen/Sink	O
	Dishwasher inoperable, repair	
3.11	Bathroom/Fixed Wash Basin or Lavatory in Unit	O
	Cabinet door off track, repair	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,