

### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1323 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1323 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

A re-inspection has been scheduled for 08/04/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 4.10 Other Rooms/Smoke Detectors Bedroom smoke detector missing/not working properly – repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1327 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1327 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/04/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.7 General Health and Safety/Other Interior Hazards Living room smoke CO detective missing

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property:
2601 HILLTOP DR Apt 1328
RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1328 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

# A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.7	General Health and Safety/Other Interior Hazards	O
	Smoke detectors missing/not working properly throughout entire unit-	
	repair/replace	
	Co detector missing	
3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
	Bathroom toilet base loose- repair/replace	
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	Unable to access water heater door clear egress from blocking door	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property:
2601 HILLTOP DR Apt 1331
RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1331 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.13	Kitchen/Space for Storage, Prep and Serving	O
	cabinet drawer is missing - repair/replace	
2.12	Kitchen/Sink	O
	dishwasher not working properly - repair/replace	
1.8	Living Room/Floor Condition	O
	carpeting throughout entire unite very badly worn- repair/replace	
8.7	General Health and Safety/Other Interior Hazards	O
	living room smoke/co detector missing - repair/replace	
3.3	Bathroom/Electrical Hazards	O
	bathroom GFCI outlet missing/not working properly - repair/replace	
3.11	Bathroom/Fixed Wash Basin or Lavatory in Unit	O
	master bedroom sink not not working/draining properly - Repair/replace	
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	clear egress from blocking water heater door	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 2601 HILLTOP DR Apt 1333 RICHMOND, CA 94806-5783-

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1333 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.7	Kitchen/Wall Condition	O
	Hole in wall - repair/repaint	
3.4	Bathroom/Security	O
	Bathroom door damaged - repair/replace	
4.4	Other Rooms/Security	0
	Bedroom door damaged - repair/replace	
3.11	Bathroom/Fixed Wash Basin or Lavatory in Unit	0
	Vanity mirror damaged/broken - safety hazard- repair/replace	
3.13	Bathroom/Ventilation	0
	Vent very dusty - repair/replace	
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	Hallway closet door damaged-repair/replace	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 2601 HILLTOP DR Apt 1335 RICHMOND, CA 94806-5783-

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1335 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
7.3	Heating and Plumbing/Ventilation and Adequacy of Cooling	O
	vent cover fan damaged - repair/replace	
4.4	Other Rooms/Security	T
	remove key lock from bedroom door	
	bedroom door damaged - repair/replace	
3.1	Bathroom/Bathroom Present	O
	master bedroom shower head leaking - renair/replace	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806

Property:
2601 HILLTOP DR Apt 1336
RICHMOND CA 94806-5783

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1336 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
7.1	Heating and Plumbing/Adequacy of Heating Equipment	O
	heater not working properly - repair/replace	
3.6	Bathroom/Ceiling Condition	O
	very large amounts of discoloration throughout entire bathroom -	
	remove/repair	
8.7	General Health and Safety/Other Interior Hazards	O
	living room Co detector missing	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1337 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1337 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.12	Kitchen/Sink	O
	dishwasher not working properly - repair/replace	
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	hallway smoke detector missing	
8.7	General Health and Safety/Other Interior Hazards	O
	living room Co detector missing	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1411 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1411 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	clear egress from blocking access to water heater door A/C Unit Unable to	
	Inspect	
2.1	Kitchen/Kitchen Area Present	T
	dishwasher door not closing - repair/replace	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1412 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1412 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.12 Kitchen/Sink garbage disposal not working properly -repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property:
2601 HILLTOP DR Apt 1413
RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1413 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

# A re-inspection has been scheduled for 08/05/2025 between 11:00AM and 02:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.6	General Health and Safety/Interior Stairs and Common Halls	О
	washroom door not properly secured - repair /replace	
8.7	General Health and Safety/Other Interior Hazards	О
	smoke detectors throughout entire unit missing/not working properly	
	living room Co detector missing	
2.3	Kitchen/Electrical Hazards	O
	GFCI outlet not working /resetting properly -repair/replace	
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	clear items from top of water heater	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1416 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1416 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.10 Kitchen/Stove or Range with Oven right rear burner not self igniting - repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1417 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1417 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.7 General Health and Safety/Other Interior Hazards living room smoke not properly secured - repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1418 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1418 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

### A re-inspection has been scheduled for 08/05/2025 between 11:00AM and 02:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	clear egress from blocking water heater door	
7.1	Heating and Plumbing/Adequacy of Heating Equipment	O
	heater thermostat not working properly	
8.7	General Health and Safety/Other Interior Hazards	O
	living room smoke/ Co detector missing not working properly -	
	repair/replace	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property:
2601 HILLTOP DR Apt 1421
RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1421 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

## A re-inspection has been scheduled for 08/05/2025 between 11:00AM and 02:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.10	Other Rooms/Smoke Detectors	O
	smoke detector missing	
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	hallway smoke detector missing	
3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
	toilet base loose - repair/replace	
3.8	Bathroom/Floor Condition	O
	plastic around base board around toilet area separating - repair/replace	
3.1	Bathroom/Bathroom Present	T
	inside and around toilet very badly discolored - health and safety -	
	clean/remove	
2.12	Kitchen/Sink	O
	garbage disposal inop - repair/replace	
2.10	Kitchen/Stove or Range with Oven	O
	microwave oven unit not working properly - fan/light - repair/replace	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1422 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1422 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.7 General Health and Safety/Other Interior Hazards living room Co detector missing

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1423 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1423 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
1.8	Living Room/Floor Condition	O
	carpeting throughout entire unit very badly worn - repair/replace	
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	clear egress from blocking access to patio door to access water heater	
	door	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 423 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 423 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.12 Kitchen/Sink Dishwasher drains through air gap, repair as garbage disposal must drain through garbage disposal

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 424 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 424 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.12 Kitchen/Sink Dishwasher inoperable, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 425 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 425 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.10 Kitchen/Stove or Range with Oven Rear burners not self lighting, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 427 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 427 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.11 Kitchen/Refrigerator Refrigerator light inoperable, repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



## FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806

riop city.
2601 HILLTOP DR Apt 428
RICHMOND, CA 94806-5783-

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 428 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.7	General Health and Safety/Other Interior Hazards	O
	Right common area smoke detectors missing, replace/install	
3.12	Bathroom/Tub or Shower	O
	Shower head leaking in right bathroom, repair	
2.10	Kitchen/Stove or Range with Oven	O
	Right rear burner not self lighting, repair	
7.4	Heating and Plumbing/Water Heater	T
	Tenant to move excessive amount of storage bins blocking hot water heater	
	closet, unable to inspect.	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 431 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 431 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.13	Bathroom/Ventilation	T
	Clean excessive dust build up on ventilation fan in left bathroom	
7.4	Heating and Plumbing/Water Heater	T
	No access to water heater closet, tenant to clear personal items blocking	
	access to water heater.	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 435 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 435 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.12 Kitchen/Sink Dishwasher inoperable, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 512 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 512 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 1.3 Living Room/Electrical Hazards Outlet across from front door has no power, light switch for lamp switch could possibly have short as only upper receptacle has no power. Repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 513 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 513 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.12	Kitchen/Sink	O
	Garbage disposal inoperable, repair	
8.7	General Health and Safety/Other Interior Hazards	O
	Install carbon monoxide detector in unit, gas appliances present. Common	
	area smoke detector does not dictate that it is a C02 detector as well.	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 516 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 516 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.10 Kitchen/Stove or Range with Oven Range hood vent screens missing, replace/install

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 517 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 517 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 7.4 Heating and Plumbing/Water Heater Tenant to clear personal items from water heater storage closet

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 2601 HILLTOP DR Apt 522 RICHMOND, CA 94806-5783-

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 522 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

### A re-inspection has been scheduled for 08/05/2025 between 11:00AM and 02:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.11	Bathroom/Fixed Wash Basin or Lavatory in Unit	O
	Peeling paint inside of sink, repair	
3.12	Bathroom/Tub or Shower	O
	Peeling paint inside of tub, repair	
2.12	Kitchen/Sink	O
	Dishwasher drains through air gap, repair as dishwasher must drain through	
	garbage disposal	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 523 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 523 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/06/2025.

#### A re-inspection has been scheduled for 08/05/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 3.12 Bathroom/Tub or Shower Tub diverter inoperable as tub runs at same time as shower, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,