

#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1732 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1732 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

A re-inspection has been scheduled for 08/27/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

## Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 7.4 Heating and Plumbing/Water Heater remove clutter from water heater closet

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1733 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1733 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/27/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

## Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 4.8 Other Rooms/Floor Condition torn and ripped carpet near entrance way trip hazard. repair or replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1736 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1736 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/27/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.3	Kitchen/Electrical Hazards	O
	Gfci open neutral repair or replace.	
	kitchen lights not working properly.	
3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
	toilet not flushing properly. repair or replace	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1737 RICHMOND, CA 94806-5783-

O

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1737 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

A re-inspection has been scheduled for 08/27/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

#### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Tenant/Owner

8.3 General Health and Safety/Evidence of Infestation tenant stated that she had bed bugs inside of unit. professional extermination is required or proof that unit has been inspected and is free of bed bugs. did not inspect unit.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1738 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1738 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.12	Kitchen/Sink	O
	non working garbage disposal repair or replace	
2.10	Kitchen/Stove or Range with Oven	O
	right rear burner do not ignite like designed, repair or replace.	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806

Property:
2601 HILLTOP DR Apt 1811
RICHMOND, CA 94806-5783

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1811 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.5	Kitchen/Window Condition	O
	torn screen on sliding glass door. repair or replace.	
3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
	master bedroom- flushing mechanism not working properly. repair or	
	replace.	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806

1	,	
260	HILLTOP DR Apt 181:	5
RIC	IMOND, CA 94806-578	83

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1815 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.7	General Health and Safety/Other Interior Hazards	O
	water is turned off due to underground leak.	
1.8	Living Room/Floor Condition	O
	water damage due to underground water leak	
4.8	Other Rooms/Floor Condition	O
	water damage due to underground water leak.	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1823 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1823 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

## Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 1.5 Living Room/Window Condition torn screen on sliding screen door, repair or replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806

	•	
2601	HILLT	OP DR Apt 1825
RICI	HMONI	D. CA 94806-5783

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1825 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.13	Kitchen/Space for Storage, Prep and Serving	O
	broken and missing cabinet door. repair and replace.	
3.1	Bathroom/Bathroom Present	T
	remove black discoloration	
3.3	Bathroom/Electrical Hazards	O
	GFCI outlet not functioning like designed.	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1833 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1833 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

_	Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
	3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
		toilet is continually running repair or replace.	
	4.8	Other Rooms/Floor Condition	O
		torn carpet near bedroom entrance	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 732 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 732 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is inoperable or missing. All units must have at least one	
	operable smoke detector on each level. The smoke detector must be	
	placed according to package insturctions.	
5.4	Secondary Rooms/Other Potential Hazardous Features	O
	Smoke detector in loft missing, replace	
3.1	Bathroom/Bathroom Present	T
	No access to bathroom, occupied for entire inspection. Tenant to provide	
	access for inspection	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 733 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 733 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

## Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 7.4 Heating and Plumbing/Water Heater Move personal items being stored in hot water heater closet

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806

2601 H	ILLTOP DR Apt 735
RICHM	IOND, CA 94806-5783-

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 735 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.11	Bathroom/Fixed Wash Basin or Lavatory in Unit	O
	Bathroom fixed wash basin or lavatory has a major leak, repair (left	
	bathroom)	
2.13	Kitchen/Space for Storage, Prep and Serving	O
	Right rear burner not self lighting, repair	
2.12	Kitchen/Sink	O
	Dishwasher drains through air gap, repair as drain must go through garbage	
	disposal.	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 736 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 736 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.12	Kitchen/Sink	O
	Dishwasher drains through air gap onto counter, repair as drain must go	
	trough garbage disposal.	
8.4	General Health and Safety/Garbage and Debris	T
	Move appliances from patio	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 812 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 812 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

## Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.12 Kitchen/Sink GRBAGE DISPOSAL INOPERABLE, REPAIR

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 815 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 815 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

## Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 7.4 Heating and Plumbing/Water Heater Move personal items being stored in hot water heater closet

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 818 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 818 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

## Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.11 Kitchen/Refrigerator Light inoperable, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 821 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 821 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

## Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.12 Kitchen/Sink Dishwasher drains through air gap onto counter, repair as drain should go through garbage disposal.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 822 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 822 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.10	Kitchen/Stove or Range with Oven	O
	Rear burners not self lighting, repair	
3.12	Bathroom/Tub or Shower	O
	Shower head leaking in rear, repair	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806

•			
260	1 HILL	TOP DR Apt 8	23
RIC	HMON	JD. CA 94806-	5783

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 823 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.12	Kitchen/Sink	O
	Dishwasher inoperable, repair	
2.10	Kitchen/Stove or Range with Oven	O
	Right rear burner not self lighting, repair	
3.12	Bathroom/Tub or Shower	O
	Shower head leaking in rear, repair	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 824 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 824 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.12	Bathroom/Tub or Shower	О
	Shower head leaking in rear, repair (left bathroom)	
7.4	Heating and Plumbing/Water Heater	T
	Move personal items being stored in hot water heater closet	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 2601 HILLTOP DR Apt 827 RICHMOND, CA 94806-5783-

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 827 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.7	General Health and Safety/Other Interior Hazards	T
	Carpeting heavily soiled throughout hallway, clean	
4.8	Other Rooms/Floor Condition	T
	Carpeting heavily soiled, clean	
4.4	Other Rooms/Security	O
	Door knob and hardware (striker plate) on door frame need to be secured	
	Bedroom patio screen door rusted frame	
3.12	Bathroom/Tub or Shower	T
	Clean discoloration in tub	
8.1	General Health and Safety/Access to Unit	O
	Patio light inoperable, repair	
2.12	Kitchen/Sink	O
	Inside of dishwasher rusted, repair, remove or replace	
	Tenant to clean discoloration in sink	
2.10	Kitchen/Stove or Range with Oven	O
	Microwave handle missing, replace	
	TENANT TO CLEAN EXCESSIVE GREASE SPLATTER ON RANGE	
	HOOD AND STOVE, GREASE CAN BECOME FIRE HAZARD	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 828 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 828 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	LEFT SIDE COMMON AREA SMOKE DETECTOR/CARBON	
	MONOXIDE DETECTOR MISSING, REPLACE	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is inoperable or missing. All units must have at least one	
	operable smoke detector on each level. The smoke detector must be	
	placed according to package insturctions.	
4.8	Other Rooms/Floor Condition	O
	Carpet torn at entry, repair	
3.4	Bathroom/Security	T
	Right bathroom, tenant to move furniture in bathroom that is preventing	
	door from opening as designed.	
2.12	Kitchen/Sink	O
	Dishwasher drains through air gap, repair as drain must go through garbage	
	disposal.	
7.5	Heating and Plumbing/Water Supply	T
	Move personal items being stored in hot water heater closet	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 831 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 831 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/12/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Other Rooms/Smoke Detectors Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,