

#### **FAILED INSPECTION NOTICE**

Mohammad Kolahdooz 2697 El Portal Dr San Pablo, CA 94806 Property: 1628 LINCOLN AVE RICHMOND, CA 94801-2471-

PropID:

Client ID: 8506

Dear Owner/Agent,

This letter is to inform you that your property at **1628 LINCOLN AVE RICHMOND**, **CA 94801-2471 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

A re-inspection has been scheduled for 10/17/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 2.3 Kitchen/Electrical Hazards
  - Three prong outlet not testing as designed, must be grounded, replaced with a two-prong outlet or replaced with a GFCI.
- 1.3 Living Room/Electrical Hazards
  - Three prong outlet not testing as designed, must be grounded, replaced with a two-prong outlet or replaced with a GFCI.
- 3.5 Bathroom/Window Condition
  - Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.
- 4.3 Other Rooms/Elecrtical Hazards
  - Three prong outlet not testing as designed, must be grounded, replaced with a two-prong outlet or replaced with a GFCI.
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Chuk Foung & Sandy Lee 109 Big Bear Ct Richmond, CA 94803 Property: 4420 SANTA RITA RD RICHMOND, CA 94803-2311-

PropID:

Client ID: 7941

Dear Owner/Agent,

This letter is to inform you that your property at **4420 SANTA RITA RD RICHMOND**, CA **94803-2311 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/13/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.1 General Health and Safety/Access to Unit broken and leaning fence repair or replace.
- 4.5 Other Rooms/Window Condition replace missing screens
- 4.4 Other Rooms/Security remove key locks

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Mohammad Kolahdooz 2697 El Portal Dr San Pablo, CA 94806 Property: 2320 RHEEM AVE RICHMOND, CA 94804-1018-

PropID:

Client ID: 8506

Dear Owner/Agent,

This letter is to inform you that your property at **2320 RHEEM AVE RICHMOND, CA 94804-1018 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 3.4 Bathroom/Security
  Remove keyed entry lock from door
- 2.3 Kitchen/Electrical Hazards
  Three prong outlet not testing as designed, must be grounded, replaced with a
  two-prong outlet or replaced with a GFCI.
  LEFT OUTLET
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Mohammad Kolahdooz 2697 El Portal Dr San Pablo, CA 94806 Property: 2324 RHEEM AVE RICHMOND, CA 94804-1018-

PropID:

Client ID: 8506

Dear Owner/Agent,

This letter is to inform you that your property at **2324 RHEEM AVE RICHMOND, CA 94804-1018 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 3.12 Bathroom/Tub or Shower
  - Tub diverter inoperable as tub runs at same time as shower, repair
- 3.11 Bathroom/Fixed Wash Basin or Lavatory in Unit
  - Hot water knob damaged, replace
- 4.5 Other Rooms/Window Condition
  - Move furniture blocking window (fire exit)
- 4.4 Other Rooms/Security
  - Remove keyed entry lock from closet door
- 2.10 Kitchen/Stove or Range with Oven
  - Clean grease splatter on stove, range hood and backsplash



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Mohammad Kolahdooz 2697 El Portal Dr San Pablo, CA 94806 Property: 2328 RHEEM AVE RICHMOND, CA 94804-1018-

PropID:

Client ID: 8506

Dear Owner/Agent,

This letter is to inform you that your property at **2328 RHEEM AVE RICHMOND, CA 94804-1018 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.5 Bathroom/Window Condition
  Window must be openable and remain open without props.
- 4.4 Other Rooms/Security
  Remove keyed lock from interior door.
- 2.13 Kitchen/Space for Storage, Prep and Serving Secure cabinet door underneath sink

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Mohammad Kolahdooz 2697 El Portal Dr San Pablo, CA 94806 Property: 2332 RHEEM AVE RICHMOND, CA 94804-1018-

PropID:

Client ID: 8506

Dear Owner/Agent,

This letter is to inform you that your property at 2332 RHEEM AVE RICHMOND, CA 94804-1018 failed the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 3.3 Bathroom/Electrical Hazards
  GFCI has hot/neutral reverse, repair
- 3.12 Bathroom/Tub or Shower Install safety guides for glass shower doors
- 4.4 Other Rooms/Security
  Remove keyed lock from interior door.
- 8.7 General Health and Safety/Other Interior Hazards
  Replace missing light cover switch for patio light
- 1.4 Living Room/Security

  Remove keyed entry lock on door in living room



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Gerald D & Carolina Jones 3621 Barrett Ave Richmond, CA 94805 Property: 3307 MARICOPA AVE RICHMOND, CA 94804-1135-

PropID:

Client ID: 4989

Dear Owner/Agent,

This letter is to inform you that your property at **3307 MARICOPA AVE RICHMOND, CA 94804-1135 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/17/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair
- 8.6 General Health and Safety/Interior Stairs and Common Halls Common area smoke detector missing, replace
- 4.4 Other Rooms/Security
  Remove keyed lock from interior door.
- 3.12 Bathroom/Tub or Shower Shower head leaking in rear, repair
- 2.10 Kitchen/Stove or Range with Oven Left rear burner not self lighting, repair
- 2.3 Kitchen/Electrical Hazards
  Light fixture cover missing, replace



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Hongfeng Gao 548 Richmond St El Cerrito, CA 94530 Property: 3226 RHEEM AVE RICHMOND, CA 94804-1146-

PropID:

Client ID: 8544

Dear Owner/Agent,

This letter is to inform you that your property at **3226 RHEEM AVE RICHMOND**, **CA 94804-1146 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/13/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.7 General Health and Safety/Other Interior Hazards replace missing co detector
- 3.3 Bathroom/Electrical Hazards gfci will not trip or reset. repair or replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Mohammad Kolahdooz 2697 El Portal Dr San Pablo, CA 94806 Property: 2369 ANDRADE AVE RICHMOND, CA 94804-1222-

PropID:

Client ID: 8506

Dear Owner/Agent,

This letter is to inform you that your property at **2369 ANDRADE AVE RICHMOND**, **CA 94804-1222 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/17/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 5.3 Secondary Rooms/Electrical Hazards Garage
  - Three prong outlet not testing as designed, must be grounded, replaced with a two-prong outlet or replaced with a GFCI.
- 8.1 General Health and Safety/Access to Unit
  Install deadbolt on garage door leading to exterior
- 1.3 Living Room/Electrical Hazards

A missing and/or cracked coverplate presents an electrical hazard.

-outlet underneath left window

4.4 Other Rooms/Security

REAR SECURITY GATE LOCK DAMAGED IN BEDROOM, REPAIR

4.3 Other Rooms/Elecrtical Hazards

Three prong outlet not testing as designed, must be grounded, replaced with a two-prong outlet or replaced with a GFCI.

2.12 Kitchen/Sink

Dishwasher inoperable, repair

8.3 General Health and Safety/Evidence of Infestation ant infestation in kitchen



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Gerald D & Carolina Jones 3621 Barrett Ave Richmond, CA 94805 Property: 629 33RD ST RICHMOND, CA 94804-1537-

PropID:

Client ID: 4989

Dear Owner/Agent,

This letter is to inform you that your property at **629 33RD ST RICHMOND**, CA **94804-1537 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/17/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 4.10 Other Rooms/Smoke Detectors
  Secure smoke detector to ceiling
- 4.4 Other Rooms/Security
  Install striker plates on door frame
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair
- 2.12 Kitchen/Sink
  - Dishwasher inoperable, repair
- 2.10 Kitchen/Stove or Range with Oven
  - Plug in stove, unable to test
- 8.1 General Health and Safety/Access to Unit
  - Install door sweep on rear door
- 6.4 Building Exterior/Condition of Exterior Surfaces
  Replace missing exterior vent screen covers
- 2.3 Kitchen/Electrical Hazards
  - Left GFCI underneath sink has no power and will not reset. Repair/replace



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Mohammad Kolahdooz 2697 El Portal Dr San Pablo, CA 94806 Property: 2224 FLORIDA AVE RICHMOND, CA 94804-2733-

PropID:

Client ID: 8506

Dear Owner/Agent,

This letter is to inform you that your property at **2224 FLORIDA AVE RICHMOND**, **CA 94804-2733 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.12 Bathroom/Tub or Shower
  - Caulk tub (interior)
- 2.10 Kitchen/Stove or Range with Oven
  - Clean grease splatter on stove and walls
- 2.6 Kitchen/Ceiling Condition
  - Clean grease splatter and great discoloration on ceiling
- 5.2 Secondary Rooms/Security
  - Glass closet door in basement damaged, repair or remove

REMOVE KEYED ENTRY LOCK ON BASEMENT DOOR



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Mohammad Kolahdooz 2697 El Portal Dr San Pablo, CA 94806 Property: 2226 FLORIDA AVE RICHMOND, CA 94804-2733-

PropID:

Client ID: 8506

Dear Owner/Agent,

This letter is to inform you that your property at **2226 FLORIDA AVE RICHMOND**, **CA 94804-2733 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 5.4 Secondary Rooms/Other Potential Hazardous Features Install smoke detector in basement
- 5.2 Secondary Rooms/Security
  Remove keyed entry lock from basement door and hall door
- 3.3 Bathroom/Electrical Hazards
  Three prong outlet not testing as designed, must be grounded, replaced with a two-prong outlet or replaced with a GFCI.



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Mohammad Kolahdooz 2697 El Portal Dr San Pablo, CA 94806 Property: 2230 FLORIDA AVE RICHMOND, CA 94804-2733-

PropID:

Client ID: 8506

Dear Owner/Agent,

This letter is to inform you that your property at **2230 FLORIDA AVE RICHMOND**, **CA 94804-2733 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 3.3 Bathroom/Electrical Hazards
  Three prong outlet not testing as designed, must be grounded, replaced with a two-prong outlet or replaced with a GFCI.
- 4.5 Other Rooms/Window Condition

  Move furniture blocking window (fire exit)
- 8.4 General Health and Safety/Garbage and Debris Remove excessive recycling in yard
- 8.1 General Health and Safety/Access to Unit Install striker plates on rear door



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Thomas S Anthony 5666 Telegraph Ave Oakland, CA 94609 Property: 1301 S 56TH ST Apt 2 RICHMOND, CA 94804-4804-

PropID:

Client ID: 8117

Dear Owner/Agent,

This letter is to inform you that your property at 1301 S 56TH ST Apt 2 RICHMOND, CA 94804-4804 failed the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/13/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 6.2 Building Exterior/Condition of Stairs, Rails, and Porches loose board on steps repair or replace.
- 2.5 Kitchen/Window Condition replace broken window and missing screen
- 1.8 Living Room/Floor Condition torn carpet in hallway repair or replace
- 2.10 Kitchen/Stove or Range with Oven non working oven repair or replace
- 3.5 Bathroom/Window Condition replace missing screens
- 4.5 Other Rooms/Window Condition replace missing screens
- 8.6 General Health and Safety/Interior Stairs and Common Halls replace missing smoke and co detector



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Thomas S Anthony 5666 Telegraph Ave Oakland, CA 94609 Property: 1301 S 56TH ST Apt 1 RICHMOND, CA 94804-4804-

PropID:

Client ID: 8117

Dear Owner/Agent,

This letter is to inform you that your property at 1301 S 56TH ST Apt 1 RICHMOND, CA 94804-4804 failed the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/13/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

4.10 Other Rooms/Smoke Detectors replace missing smoke detector

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Chuk Foung & Sandy Lee 109 Big Bear Ct Richmond, CA 94803 Property: 5640 CARLOS AVE RICHMOND, CA 94804-4834-

PropID:

Client ID: 7941

Dear Owner/Agent,

This letter is to inform you that your property at **5640 CARLOS AVE RICHMOND**, **CA 94804-4834 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/13/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 6.4 Building Exterior/Condition of Exterior Surfaces chipping and peeling paint on entire right side of house. repaint.
- 8.10 General Health and Safety/Site and Neighborhood Conditions cut overgrown trees and bushes front and back yard.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Hongfeng Gao 548 Richmond St El Cerrito, CA 94530 Property: 5607 ALAMEDA AVE RICHMOND, CA 94804-4878-

PropID:

Client ID: 8544

Dear Owner/Agent,

This letter is to inform you that your property at **5607 ALAMEDA AVE RICHMOND**, **CA 94804-4878 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/13/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.7 General Health and Safety/Other Interior Hazards replace missing CO detector
- 4.10 Other Rooms/Smoke Detectors replace missing smoke detector

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Hongfeng Gao 548 Richmond St El Cerrito, CA 94530 Property: 5240 TEHAMA AVE RICHMOND, CA 94804-5128-

PropID:

Client ID: 8544

Dear Owner/Agent,

This letter is to inform you that your property at **5240 TEHAMA AVE RICHMOND, CA 94804-5128 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/13/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.4 Other Rooms/Security remove key lock
- 3.6 Bathroom/Ceiling Condition non working ceiling . repair or replace.
- 2.10 Kitchen/Stove or Range with Oven fan makes a loud noise. repair or replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

John & Sherry Zalabak 402 Vermont Ave Berkeley, CA 94707-1722 Property: 1812 CARLSON BLVD Apt 1 RICHMOND, CA 94804-5222-

PropID:

Client ID: 8985

Dear Owner/Agent,

This letter is to inform you that your property at **1812 CARLSON BLVD Apt 1 RICHMOND, CA 94804-5222 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

A re-inspection has been scheduled for 10/13/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.10 Other Rooms/Smoke Detectors replace missing smoke detector
- 8.6 General Health and Safety/Interior Stairs and Common Halls replace missing smoke detector.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Gerald D & Carolina Jones 3621 Barrett Ave Richmond, CA 94805 Property: 859 38TH ST RICHMOND, CA 94805-1320-

PropID:

Client ID: 4989

Dear Owner/Agent,

This letter is to inform you that your property at **859 38TH ST RICHMOND**, CA **94805-1320 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

A re-inspection has been scheduled for 10/17/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.



#### **FAILED INSPECTION NOTICE**

- 8.6 General Health and Safety/Interior Stairs and Common Halls Common area smoke detector in living room missing, replace
- 1.5 Living Room/Window Condition
  Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.
- 1.3 Living Room/Electrical Hazards Three prong outlet not testing as designed, must be grounded, replaced with a two-prong outlet or replaced with a GFCI.
- 2.5 Kitchen/Window Condition
  Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.
- 4.5 Other Rooms/Window Condition Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.
- 4.3 Other Rooms/Elecrtical Hazards
  Replace cracked receptacle right of window
- 3.5 Bathroom/Window Condition
  Install lock on window
- 3.12 Bathroom/Tub or Shower

  Tub diverter inoperable as tub runs at same time as shower, repair
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair
- 8.7 General Health and Safety/Other Interior Hazards
  Remove old smoke detector bases throughout unit
- 8.1 General Health and Safety/Access to Unit Install deadbolt on rear door



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Gerald D & Carolina Jones 3621 Barrett Ave Richmond, CA 94805 Property: 945 WILSON RICHMOND, CA 94805-1350-

PropID:

Client ID: 4989

Dear Owner/Agent,

This letter is to inform you that your property at **945 WILSON RICHMOND**, CA **94805-1350 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

#### A re-inspection has been scheduled for 10/17/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 4.5 Other Rooms/Window ConditionTenant to clear items to allow clear path to patio door (fire exit)
- 4.10 Other Rooms/Smoke Detectors Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions. REPLACE, EXCEEDS 10 YEAR LIFE SPAN
- 3.5 Bathroom/Window Condition Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.
- 3.3 Bathroom/Electrical Hazards
  Outlet by sink has open grounds, replace with GFCI
- 3.12 Bathroom/Tub or Shower
  Repair leak at hot water control knob
- 4.3 Other Rooms/Elecrtical Hazards Three prong outlet not testing as designed, must be grounded or replaced with a GFCI.
- 8.1 General Health and Safety/Access to Unit Install deadbolt lock on rear door
- 5.3 Secondary Rooms/Electrical Hazards
  Electrical Outlet Cover Damaged. Outlet next to hot water heater



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Mohammad Kolahdooz 2697 El Portal Dr San Pablo, CA 94806 Property: 320 42ND ST RICHMOND, CA 94805-2323-

PropID:

Client ID: 8506

Dear Owner/Agent,

This letter is to inform you that your property at **320 42ND ST RICHMOND**, CA **94805-2323 failed** the Housing Quality Standards (HQS) inspection on 08/21/2025.

A re-inspection has been scheduled for 10/17/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.



#### **FAILED INSPECTION NOTICE**

#### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.1 General Health and Safety/Access to Unit Front security gate damaged, repair/replace or remove
- 4.4 Other Rooms/Security
  - 1- Door frame damaged, repair
  - 2- Tenant to remove keyed entry lock from door
- 4.5 Other Rooms/Window Condition

Move furniture blocking access to window (fire exit)

4.3 Other Rooms/Elecrtical Hazards

Three prong outlet not testing as designed, must be grounded or replaced with a GFCI.

3.12 Bathroom/Tub or Shower

Repair damaged caulking on inside and outside of tub

3.10 Bathroom/Flush Toilet in Enclosed Room in Unit

Repair damaged wall behind toilet

2.10 Kitchen/Stove or Range with Oven

Replace missing knobs

5.2 Secondary Rooms/Security

Laundry room window screen missing, replace

Tenant to clean organic black discoloration on window and window seal

2.8 Kitchen/Floor Condition

Baseboard trim damaged by kitchen door, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,