

#### FAILED INSPECTION NOTICE

5903 BAYVIEW AVE RICHMOND, CA 94804-4859PropID:

Client ID: 9651

Dear Current Resident,

This letter is to inform you that your property at **5903 BAYVIEW AVE RICHMOND**, CA **94804-4859 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

A re-inspection has been scheduled for 10/08/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.5 Other Rooms/Window Condition
  - 1. Missing screen at top right window in bedroom, replace.
  - 2. Excessive discoloration on widow.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

5907 BAYVIEW AVE RICHMOND, CA 94804-4859PropID:

Client ID: 9651

Dear Current Resident,

This letter is to inform you that your property at **5907 BAYVIEW AVE RICHMOND, CA 94804-4859 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 10/08/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 8.6 General Health and Safety/Interior Stairs and Common Halls Hole in walkway wall, repair.
- 3.11 Bathroom/Fixed Wash Basin or Lavatory in Unit Upstairs bathroom cabinet door missing, replace.
- 3.6 Bathroom/Ceiling Condition
  Bathroom fan screen loose, repair/replace.
- 4.10 Other Rooms/Smoke Detectors
  Smoke detector non operable in right side bedroom, repair.



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

1900 MENDOCINO ST RICHMOND, CA 94804-5319-

PropID:

Client ID: 4113

Dear Current Resident,

This letter is to inform you that your property at **1900 MENDOCINO ST RICHMOND, CA 94804-5319 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

A re-inspection has been scheduled for 10/07/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit Downstairs bathroom toilet flush/fill valve is stopped up.
- 2.10 Kitchen/Stove or Range with Oven Stove exhaust fan missing knob, replace.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

5233 SAN JOSE AVE Apt A RICHMOND, CA 94804-5945-

Client ID: 9651

PropID:

Dear Current Resident,

This letter is to inform you that your property at **5233 SAN JOSE AVE Apt A RICHMOND, CA 94804-5945 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 10/08/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

4.10 Other Rooms/Smoke Detectors
Bedroom #2 smoke detector non operable, repair/replace.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

16 MARINA LAKES DR RICHMOND, CA 94804-7447PropID:

Client ID: 2615

Dear Current Resident,

This letter is to inform you that your property at **16 MARINA LAKES DR RICHMOND, CA 94804-7447 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 10/08/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

4.10 Other Rooms/Smoke DetectorsMissing smoke detector bedroom 2, install.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

5216 SOLANO AVE RICHMOND, CA 94805-1449-

.

PropID:

Client ID: 8334

Dear Current Resident,

This letter is to inform you that your property at **5216 SOLANO AVE RICHMOND**, **CA 94805-1449 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 10/14/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 2.3 Kitchen/Electrical Hazards
  Outlets have open grounds, repair
- 4.4 Other Rooms/Security
  Remove keyed lock from interior door.
- 4.3 Other Rooms/Elecrtical Hazards
  Outlet behind door has hot/neutral reverse, repair
- 6.2 Building Exterior/Condition of Stairs, Rails, and Porches Rear patio deck boards dry rotted, replace
- 8.10 General Health and Safety/Site and Neighborhood Conditions Cut down weeds in yard
- 5.2 Secondary Rooms/Security
  Remove keyed entry lock on hall door by kitchen
- 3.5 Bathroom/Window Condition Window screen damaged, repair



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



# FAILED INSPECTION NOTICE

830 36TH ST RICHMOND, CA 94805-1712PropID:

Client ID: 8334

Dear Current Resident,

This letter is to inform you that your property at 830 36TH ST RICHMOND, CA 94805-1712 failed the Housing Quality Standards (HQS) inspection on 08/18/2025.

A re-inspection has been scheduled for 10/14/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.



### FAILED INSPECTION NOTICE

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

# 4.10 Other Rooms/Smoke Detectors

Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package instructions. Replace exceeds 10 year life span

- 8.7 General Health and Safety/Other Interior Hazards
  Common area smoke detector exceeds 10 year life span, replace (2012)
- 4.5 Other Rooms/Window Condition

Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.

3.5 Bathroom/Window Condition

Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.

4.4 Other Rooms/Security

Remove keyed lock from interior door.

2.10 Kitchen/Stove or Range with Oven

Range hood heavily rusted, replace

Front right burner not self lighting, repair

2.5 Kitchen/Window Condition

Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.

7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

663 40TH ST RICHMOND, CA 94805-1809-

. -- 0--0

Client ID: 9753

PropID:

Dear Current Resident,

This letter is to inform you that your property at **663 40TH ST RICHMOND**, CA **94805-1809 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 10/10/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 8.6 General Health and Safety/Interior Stairs and Common Halls
  Common area smoke detectors levels 1 & 2 exceed 10 year life span, replace
- 3.12 Bathroom/Tub or Shower Shower head leaking in rear, repair
- 4.5 Other Rooms/Window Condition
  Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.
- 4.10 Other Rooms/Smoke DetectorsSmoke detector exceeds 10 year life span, replace
- 4.3 Other Rooms/Elecrtical Hazards
  Outlet on left wall has something broken in upper receptacle, replace
- 2.12 Kitchen/SinkGarbage disposal inoperable, repair
- 5.4 Secondary Rooms/Other Potential Hazardous Features Laundry room window screen missing, replace



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

423 40TH ST Apt B RICHMOND, CA 94805-2247PropID:

Client ID: 9753

Dear Current Resident,

This letter is to inform you that your property at 423 40TH ST Apt B RICHMOND, CA 94805-2247 failed the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 09/01/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.10 General Health and Safety/Site and Neighborhood Conditions Cut down weeds in rear yard
- 8.4 General Health and Safety/Garbage and Debris Remove excessive recycling from rear yard

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

423 40TH ST Apt C RICHMOND, CA 94805-2247PropID:

Client ID: 9753

Dear Current Resident,

This letter is to inform you that your property at **423 40TH ST Apt C RICHMOND, CA 94805-2247 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 09/01/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

4.3 Other Rooms/Elecrtical Hazards Damaged outlet presents an electrical hazard. Replace cracked outlet underneath window

Outlets have open grounds, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

423 40TH ST Apt D RICHMOND, CA 94805-2247PropID:

Client ID: 9753

Dear Current Resident,

This letter is to inform you that your property at 423 40TH ST Apt D RICHMOND, CA 94805-2247 failed the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 09/01/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 8.6 General Health and Safety/Interior Stairs and Common Halls Common area smoke detector removed, replace
- 8.7 General Health and Safety/Other Interior HazardsCarbon monoxide detector inoperable, batteries removed. Replace
- 4.10 Other Rooms/Smoke Detectors Smoke dectector is missing battery or batteries. Tenants are responsible for replacement of batteries in all smoke detectors in the unit.
- 3.12 Bathroom/Tub or Shower

  Tub diverter inoperable as tub runs at same time as shower, repair
- 2.10 Kitchen/Stove or Range with Oven Light switch on range hood missing, replace



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### **FAILED INSPECTION NOTICE**

423 40TH ST Apt E RICHMOND, CA 94805-2247PropID:

Client ID: 9753

Dear Current Resident,

This letter is to inform you that your property at **423 40TH ST Apt E RICHMOND**, CA **94805-2247 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 09/01/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 8.6 General Health and Safety/Interior Stairs and Common Halls Install common area smoke detector
- 3.12 Bathroom/Tub or Shower shower head leaking in rear, repair
- 2.13 Kitchen/Space for Storage, Prep and ServingKit. = Missing Cabinet Drawer.Drawer front left of refrigerator missing, replace



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

423 40TH ST Apt F RICHMOND, CA 94805-2247PropID: Client ID: 9753

Dear Current Resident,

This letter is to inform you that your property at **423 40TH ST Apt F RICHMOND**, CA **94805-2247 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 09/01/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 8.6 General Health and Safety/Interior Stairs and Common Halls Common area smoke detector missing, replace
- 4.10 Other Rooms/Smoke Detectors
  - Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions.
  - REPLACE, EXCEEDS 10 year life span (2012)
- 3.4 Bathroom/Security
  - Remove keyed entry lock from bathroom door



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

316 44TH ST RICHMOND, CA 94805-2362PropID:

Client ID: 8334

Dear Current Resident,

This letter is to inform you that your property at **316 44TH ST RICHMOND**, CA **94805-2362 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 10/14/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

8.6 General Health and Safety/Interior Stairs and Common Halls
Common area smoke detector inoperable, repair or replace

Carbon monoxide detector inoperable, repair

- 4.4 Other Rooms/Security
  - Remove keyed lock from interior door.
- 4.10 Other Rooms/Smoke Detectors
  - Smoke dectector is missing battery or batteries. Tenants are responsible for replacement of batteries in all smoke detectors in the unit.
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair
- 2.10 Kitchen/Stove or Range with Oven Range hood fan inoperable, repair



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

322 44TH ST RICHMOND, CA 94805-2362PropID:

Client ID: 8334

Dear Current Resident,

This letter is to inform you that your property at **322 44TH ST RICHMOND**, CA **94805-2362 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 10/14/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 8.6 General Health and Safety/Interior Stairs and Common Halls Common area smoke detector inoperable, repair
- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit Bath Toilet not secured properly to floor.
- 3.13 Bathroom/Ventilation
  Clean dust build up on vent fan
- 4.10 Other Rooms/Smoke Detectors Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions.
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair
- 8.7 General Health and Safety/Other Interior Hazards
  Install carbon monoxide detector in unit



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

320 44TH ST RICHMOND, CA 94805-2362PropID:

Client ID: 8334

Dear Current Resident,

This letter is to inform you that your property at **320 44TH ST RICHMOND**, CA **94805-2362 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 10/08/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.10 Other Rooms/Smoke Detectors
  Smoke detector bedroom #2 non operable, repair.
- 4.8 Other Rooms/Floor Condition
  Carpet in second bedroom worn in poor condition, hoes, nails exposed.
- 8.6 General Health and Safety/Interior Stairs and Common Halls
  Carpet in common areas worn, in poor condition, holes, nails exposed.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

763 PT PINOLE CT RICHMOND, CA 94806-1896PropID:

Client ID: 9305

Dear Current Resident,

This letter is to inform you that your property at **763 PT PINOLE CT RICHMOND**, **CA 94806-1896 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

A re-inspection has been scheduled for 10/14/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 2.12 Kitchen/Sink
  - 1- Dishwasher drains through air gap, repair as DRAIN MUST GO THROUGH GARBAGE DISPOSAL
  - 2- Recaulk behind kitchen sink

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

754 REGENTS CT RICHMOND, CA 94806-1897-

NI ID 0205

PropID:

Client ID: 9305

Dear Current Resident,

This letter is to inform you that your property at **754 REGENTS CT RICHMOND, CA 94806-1897 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 10/14/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 6.4 Building Exterior/Condition of Exterior Surfaces
  Front exterior outlet missing weatherproof cover, replace
- 7.4 Heating and Plumbing/Water Heater Earthquake straps needed on top and bottom.
- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit Bath Toilet Seat needs repair/replacement.
- 4.5 Other Rooms/Window Condition Window screen torn, repair
- 4.4 Other Rooms/Security
  - Remove keyed lock from interior door.
- 1.3 Living Room/Electrical Hazards Light switch cover plate at entry of unit damaged, replace
- 1.4 Living Room/Security
  Install patio door screen



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

738 MONARCH CT RICHMOND, CA 94806-1898-

. -- 0005

Client ID: 9305

PropID:

Dear Current Resident,

This letter is to inform you that your property at **738 MONARCH CT RICHMOND**, **CA 94806-1898 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

A re-inspection has been scheduled for 10/14/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

6.4 Building Exterior/Condition of Exterior Surfaces
Front exterior outlet missing weatherproof cover, install

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

921 SUMMER LN RICHMOND, CA 94806-2055PropID:

Client ID: 9305

Dear Current Resident,

This letter is to inform you that your property at **921 SUMMER LN RICHMOND**, CA **94806-2055 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 10/14/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.12 Bathroom/Tub or Shower
  Tub diverter inoperable as tub runs at same time as shower
  LOWER LEVEL BATHROOM
- 4.4 Other Rooms/Security
  Remove keyed lock from interior door.

Lock striker plate must work and be securely fastened to door frame.



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

5405 ACE CT RICHMOND, CA 94806-5885PropID:

Client ID: 9305

Dear Current Resident,

This letter is to inform you that your property at **5405 ACE CT RICHMOND**, CA **94806-5885 failed** the Housing Quality Standards (HQS) inspection on 08/18/2025.

### A re-inspection has been scheduled for 10/14/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.1 General Health and Safety/Access to Unit Install door sweep on garage door
- 8.2 General Health and Safety/Exits
  Patio door on left side of unit missing lock mechanism, replace
- 8.4 General Health and Safety/Garbage and Debris Remove old toilets from exterior left side of unit
- 2.12 Kitchen/Sink

Dishwasher inoperable, repair

4.4 Other Rooms/Security

Remove keyed lock from interior door.

Lock striker plate must work and be securely fastened to door frame.

- 4.3 Other Rooms/Elecrtical Hazards
  - Outlet underneath thermostat has open neutral, repair
- 4.5 Other Rooms/Window Condition

Window screen damaged, repair



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,