

FAILED INSPECTION NOTICE

Jingyang Li 32740 S Artistry Loop Union City, CA 94587-8212 Property: 331 S 15TH ST RICHMOND, CA 94804-2511-

PropID:

Client ID: 4232

Dear Owner/Agent,

This letter is to inform you that your property at **331 S 15TH ST RICHMOND, CA 94804-2511 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.5 Other Rooms/Window Condition
 Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.
- 4.3 Other Rooms/Elecrtical Hazards
 A missing and/or cracked coverplate presents an electrical hazard.
- 4.10 Other Rooms/Smoke Detectors Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions.
- 4.6 Other Rooms/Celing Condition
 Patch hole above window
- 3.13 Bathroom/Ventilation
 Clean excessive dust build up on vent fan
- 2.10 Kitchen/Stove or Range with Oven Install range hood vent screen
- 7.4 Heating and Plumbing/Water Heater Wtr. Htr. = Missing Pilot Light Cover.



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Abraham & Angelica Chavez 225 S 18Th St Richmond, CA 94804-2625 Property: 222 S 23RD ST RICHMOND, CA 94804-2806-

PropID:

Client ID: 1020

Dear Owner/Agent,

This letter is to inform you that your property at **222 S 23RD ST RICHMOND, CA 94804-2806 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 5.2 Secondary Rooms/SecurityInstall striker plate on garage door frame
- 5.3 Secondary Rooms/Electrical HazardsOutlet at garage entry missing cover plate, install
- 8.4 General Health and Safety/Garbage and Debris Remove old water heater on side of unit

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Michael W Marr Maharah Silmi 3577 Fruitvale Ave Oakland, CA 94602-2326 Property: 350 S 29TH ST RICHMOND, CA 94804-2916-

PropID:

Client ID: 7950

Dear Owner/Agent,

This letter is to inform you that your property at **350 S 29TH ST RICHMOND**, CA **94804-2916 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.5 Other Rooms/Window ConditionMove furniture blocking quick release for security bars
- 2.10 Kitchen/Stove or Range with Oven
 - 1. Right rear burner inoperable, repair
 - 2. Tenant to remove soiled foil on stove (fire hazard)
- 4.3 Other Rooms/Elecrtical Hazards

No access to outlets for inspection, clear items to allow access



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Angela E Crespin 208 Poppy Ct Hercules, CA 94547-1229 Property: 343 S 26TH ST RICHMOND, CA 94804-2957-

PropID:

Client ID: 8700

Dear Owner/Agent,

This letter is to inform you that your property at **343 S 26TH ST RICHMOND**, CA **94804-2957 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 1.3 Living Room/Electrical Hazards
 Three prong outlet not testing as designed, must be grounded, replaced with a
 two-prong outlet or replaced with a GFCI.
- 4.3 Other Rooms/Elecrtical Hazards No access to outlets for inspection, tenant to clear items to allow access for inspection
- 4.4 Other Rooms/Security

 Move furniture blocking access to door (fire exit)
- 8.4 General Health and Safety/Garbage and Debris Remove refrigerator from side of unit



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Maria S Garcia 4656 W 134Th St Hawthorne, CA 90250-5720 Property: 3736 WALLER AVE RICHMOND, CA 94804-3329-

PropID:

Client ID: 7685

Dear Owner/Agent,

This letter is to inform you that your property at **3736 WALLER AVE RICHMOND**, **CA 94804-3329 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair
- 8.6 General Health and Safety/Interior Stairs and Common Halls Common area smoke detector has low audible alert, replace
- 4.5 Other Rooms/Window ConditionMove furniture blocking access to quick release for security bars
- 4.10 Other Rooms/Smoke Detectors
 - Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package instructions.
 - REPLACE exceeds 10 year life span (2012)
- 2.10 Kitchen/Stove or Range with Oven
 Range hood vent screen missing, replace/install



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Fong Fong Ga 568 47Th Ave San Francisco, CA 94121-2425 Property: 252 S 41ST ST RICHMOND, CA 94804-3336-

PropID:

Client ID: 9664

Dear Owner/Agent,

This letter is to inform you that your property at 252 S 41ST ST RICHMOND, CA 94804-3336 failed the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/17/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.



FAILED INSPECTION NOTICE

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.5 Other Rooms/Window Condition
 - 1. Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.
 - 2. Install quick release for security bars or remove bars
- 4.4 Other Rooms/Security

Remove keyed lock from interior door.

4.3 Other Rooms/Elecrtical Hazards

Three prong outlet not testing as designed, must be grounded or replaced with a GFCI.

Lower level bedroom

3.12 Bathroom/Tub or Shower

Resurface tub, rust present.

1.3 Living Room/Electrical Hazards

Three prong outlet not testing as designed, must be grounded, replaced with a two-prong outlet or replaced with a GFCI.

2.3 Kitchen/Electrical Hazards

Three prong outlet not testing as designed, must be grounded, replaced with a two-prong outlet or replaced with a GFCI.

- outlet has hot/neutral reverse, repair
- 8.4 General Health and Safety/Garbage and Debris Remove refrigerator from yard

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Caroline Aki 961 Stannage Ave Albany, CA 94706 Property: 4328 FLORIDA AVE RICHMOND, CA 94804-3435-

PropID:

Client ID: 8993

Dear Owner/Agent,

This letter is to inform you that your property at **4328 FLORIDA AVE RICHMOND**, **CA 94804-3435 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/17/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

4.10 Other Rooms/Smoke Detectors

Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package instructions.

- -Replace, exceeds 10 year life span
- 8.7 General Health and Safety/Other Interior Hazards Carbon monoxide detector inoperable, replace as unit exceeds 10 year life span (2014)
- 3.12 Bathroom/Tub or Shower

Clean discoloration

- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair
- 6.4 Building Exterior/Condition of Exterior Surfaces
 Left side exterior dryer vent cover missing, replace
- 2.11 Kitchen/Refrigerator

Refrigerator Leakage Present.

Refrigerator/Freezer does not maintain temperature.

2.10 Kitchen/Stove or Range with Oven

Clean grease splatter on stove and cabinetry above stove



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Steve O Linstad 153 Valley Glen Ln Martinez, CA 94553-5865 Property: 4520 WALL AVE RICHMOND, CA 94804-3458-

PropID:

Client ID: 12266

Dear Owner/Agent,

This letter is to inform you that your property at **4520 WALLAVE RICHMOND**, **CA 94804-3458 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/17/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair
- 4.5 Other Rooms/Window Condition Move furniture blocking window
- 4.3 Other Rooms/Elecrtical Hazards
 Outlet by closet door missing cover plate, install
- 2.10 Kitchen/Stove or Range with Oven Range hood vent screen missing, install



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Jl Homeland Development Group 805 Sierra Pt Rd Brisbane, CA 94005 Property: 700 S 41ST ST RICHMOND, CA 94804-4304-

PropID:

Client ID: 10041

Dear Owner/Agent,

This letter is to inform you that your property at **700 S 41ST ST RICHMOND**, CA **94804-4304 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/17/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.



FAILED INSPECTION NOTICE

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 7.4 Heating and Plumbing/Water Heater
 - Install proper discharge line. Discharge line connects to coping that isnt secure. Discharge line must be copper, galvanized steel or cpvc
- 2.3 Kitchen/Electrical Hazards
 - GFCI left of stove inoperable, replace
- 2.5 Kitchen/Window Condition

Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.

- 4.3 Other Rooms/Elecrtical Hazards
 - Damaged outlet presents an electrical hazard.
 - replace damaged outlet behind door
- 4.10 Other Rooms/Smoke Detectors

Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions.

- 4.6 Other Rooms/Celing Condition
 - Clean discoloration on ceiling
- 4.5 Other Rooms/Window Condition

Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.

- 3.11 Bathroom/Fixed Wash Basin or Lavatory in Unit
 - 1. Bathroom fixed wash basin or lavatory drain has a major leak.
 - 2. Subfloor damaged from leak, repair
- 3.5 Bathroom/Window Condition

Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.

- 3.12 Bathroom/Tub or Shower
 - INOPERABLE, no running water. Repair
- 3.3 Bathroom/Electrical Hazards
 - Install GFCI protected outlet by sink



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Dorothy F Fortier Po Box 1613 El Cerrito, CA 94530-4613 Property: 4549 BELL CT RICHMOND, CA 94804-4309-

PropID:

Client ID: 7452

Dear Owner/Agent,

This letter is to inform you that your property at **4549 BELL CT RICHMOND, CA 94804-4309 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/17/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.7 General Health and Safety/Other Interior Hazards
 Replace damaged receptacle underneath dining room window
- 4.3 Other Rooms/Elecrtical Hazards

 Damaged outlet presents an electrical hazard.
 - outlet underneath window
- 4.10 Other Rooms/Smoke Detectors

Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions.



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Vinson E & Shirley A Goodwin 775 Westpark American Canyon, CA 94503-1249 Property: 4501 POTRERO AVE RICHMOND, CA 94804-4318-

PropID:

Client ID: 7623

Dear Owner/Agent,

This letter is to inform you that your property at **4501 POTRERO AVE RICHMOND**, CA **94804-4318 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/17/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit Bath Toilet not secured properly to floor.
- 4.4 Other Rooms/Security
 Install striker plate on door frame
- 4.3 Other Rooms/Elecrtical Hazards
 Replace cracked receptacle underneath window
- 4.10 Other Rooms/Smoke Detectors

Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package instructions.

- REPLACE, exceeds 10 year life span
- 4.5 Other Rooms/Window Condition

 Move furniture blocking window (fire exit)
- 5.2 Secondary Rooms/SecurityReplace missing molding on interior side of garage door



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Yolanda A Lewis 361 Violet Rd Hercules, CA 94547-1028 Property: 555 S 47TH ST RICHMOND, CA 94804-4325-

PropID:

Client ID: 7638

Dear Owner/Agent,

This letter is to inform you that your property at 555 S 47TH ST RICHMOND, CA 94804-4325 failed the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/17/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.



FAILED INSPECTION NOTICE

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 1.3 Living Room/Electrical HazardsOutlet ion right wall at entry missing cover plate, install
- 3.3 Bathroom/Electrical Hazards
 Install GFCI in 1/2 bathroom level 1
- 5.3 Secondary Rooms/Electrical HazardsReplace cracked receptacle in garage left of door
- 5.2 Secondary Rooms/Security
 Clear items (appliances) preventing garage door from opening as room is being used as a living quarter and that is the emergency exit
- 8.4 General Health and Safety/Garbage and Debris
 Remove old appliances and clutter in rear of unit in yard
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair
- 4.3 Other Rooms/Elecrtical Hazards Three prong outlet not testing as designed, must be grounded or replaced with a GFCI.
- 4.5 Other Rooms/Window Condition Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.
- 3.5 Bathroom/Window Condition Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.

LEVEL 2



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Gary Ku & Maggie Cai Chu 1007 Capitol Ave San Francisco, CA 94112-2211 Property: 901 S 46TH ST RICHMOND, CA 94804-4418-

PropID:

Client ID: 9399

Dear Owner/Agent,

This letter is to inform you that your property at **901 S 46TH ST RICHMOND**, CA **94804-4418 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/17/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.6 General Health and Safety/Interior Stairs and Common Halls

 Common area smoke detector to be replaced, exceeds 10 year life span (2011)
- 4.10 Other Rooms/Smoke Detectors Smoke detector is missing. All units must have at least one operable smoke detector in each bedroom and in a common area on each level.
- 3.12 Bathroom/Tub or Shower Shower head leaking level 2, tenant supplied shower head



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Linda Liang 1620 Norvell St El Cerrito, CA 94530-2244 Property: 4722 POTRERO AVE RICHMOND, CA 94804-4443-

PropID:

Client ID: 9763

Dear Owner/Agent,

This letter is to inform you that your property at **4722 POTRERO AVE RICHMOND**, CA **94804-4443 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/17/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.5 Other Rooms/Window ConditionMove furniture blocking window (fire exit)
- 4.3 Other Rooms/Elecrtical Hazards

 No access to outlets, tenant to clear items to allow access for inspection
- 8.6 General Health and Safety/Interior Stairs and Common Halls Common area smoke detector missing, replace
- 3.12 Bathroom/Tub or Shower
 Unable to inspect as tub full of tenants personal items
- 5.4 Secondary Rooms/Other Potential Hazardous Features
 Dining room window screen missing, replace
- 2.13 Kitchen/Space for Storage, Prep and Serving Cabinet door damaged right side of refrigerator, repair
- 2.12 Kitchen/SinkDishwasher inoperable, repair



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Wei Xiao 1209 S Bernardo Ave Sunnyvale, CA 94087-2060 Property: 2886 HILLTOP MALL RD RICHMOND, CA 94806-

PropID:

Client ID: 7954

Dear Owner/Agent,

This letter is to inform you that your property at **2886 HILLTOP MALL RD RICHMOND, CA 94806 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 7.1 Heating and Plumbing/Adequacy of Heating Equipment fireplace inop repair
- 4.4 Other Rooms/Security remove key door lock from bedroom door
- 3.12 Bathroom/Tub or Shower bedroom bathroom tub diverter missing

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Gurdev & Rajinder Sikand Po Box 5506 Hercules, CA 94547-5506 Property:
713 BRADFORD DR
RICHMOND, CA 94806-1716-

PropID:

Client ID: 7669

Dear Owner/Agent,

This letter is to inform you that your property at **713 BRADFORD DR RICHMOND**, **CA 94806-1716 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.



FAILED INSPECTION NOTICE

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.7 General Health and Safety/Other Interior Hazards hallway smoke/Co detector missing
- 3.11 Bathroom/Fixed Wash Basin or Lavatory in Unit hallway faucet base loose repair/replace
- 3.12 Bathroom/Tub or Shower caulking in tub very badly worn/discolored - repair/recaulk shower head leaking - repair /replace
- 4.4 Other Rooms/Security remove key door locks from all bedroom doors
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment heater inop repair/replace
- 4.10 Other Rooms/Smoke Detectors bedroom smoke detector missing/inop
- 2.10 Kitchen/Stove or Range with Oven hood range fan inop
- 2.13 Kitchen/Space for Storage, Prep and Serving cabinet drawer damaged repair/replace
- 4.5 Other Rooms/Window Condition bedroom window broken repair/replace safety hazard
- 8.4 General Health and Safety/Garbage and Debris clear walkway on side of house of egress/items
- 7.2 Heating and Plumbing/Safety of Heating Equipment clear egress/items from blocking access to water heater

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Man Shing Lee 227 Peninsula Ave San Francisco, CA 94134-2424 Property: 4408 JENKINS WAY RICHMOND, CA 94806-1742-

PropID:

Client ID: 12377

Dear Owner/Agent,

This letter is to inform you that your property at **4408 JENKINS WAY RICHMOND**, **CA 94806-1742 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.10 Other Rooms/Smoke Detectors bedroom smoke detector missing /inop
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment heater inop repair/replace
- 8.10 General Health and Safety/Site and Neighborhood Conditions back yard fence leaning not standing securely repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Jingyang Li 32740 S Artistry Loop Union City, CA 94587-8212 Property: 800 PHANOR DR RICHMOND, CA 94806-1773-

PropID:

Client ID: 4232

Dear Owner/Agent,

This letter is to inform you that your property at **800 PHANOR DR RICHMOND**, CA **94806-1773 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.4 Other Rooms/Security remove key door lock from bedroom door
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment heater inop repair/replace
- 8.10 General Health and Safety/Site and Neighborhood Conditions backyard has a large amounts of overgrowth cut/remove

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Yuanping He 4705 Valley Vista Dr Dublin, CA 94568-7687 Property: 611 SUMMER LN RICHMOND, CA 94806-2194-

PropID:

Client ID: 6497

Dear Owner/Agent,

This letter is to inform you that your property at 611 SUMMER LN RICHMOND, CA 94806-2194 failed the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 7.2 Heating and Plumbing/Safety of Heating Equipment clear egress blocking access to water heater
- 8.7 General Health and Safety/Other Interior Hazards living room smoke detector missing/inop -repair/replace
- 3.4 Bathroom/Security
 2nd fl bathroom door access from bedroom damaged repair/replace
- 8.1 General Health and Safety/Access to Unit remove dead bolt from back door exit clear egress blocking exit door



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Rong Jie Lei 805 Sierra Point Road Brisbane, CA 94005 Property: 2965 GILMA DR RICHMOND, CA 94806-2606-

PropID:

Client ID: 10516

Dear Owner/Agent,

This letter is to inform you that your property at **2965 GILMA DR RICHMOND**, **CA 94806-2606 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 4.4 Other Rooms/Security remove key door lock from bedroom door
- 4.3 Other Rooms/Elecrtical Hazards light switch covers in both bedrooms damaged replace
- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit hallway toilet base loose repair/replace
- 7.2 Heating and Plumbing/Safety of Heating Equipment clear egress around /blocking access to water heater
- 4.10 Other Rooms/Smoke Detectors garage used as bedroom needs a smoke detector
- 8.7 General Health and Safety/Other Interior Hazards living room CO detector missing
- 2.3 Kitchen/Electrical Hazards
 GFCI outlet missing



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Paul P & Ofelia E Gamez 193 Macalvey Dr Martinez, CA 94553-5850 Property: 2984 MC KENZIE DR RICHMOND, CA 94806-2613-

PropID:

Client ID: 3026

Dear Owner/Agent,

This letter is to inform you that your property at **2984 MC KENZIE DR RICHMOND, CA 94806-2613 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.3 Bathroom/Electrical Hazards GFCI outlet missing
- 3.13 Bathroom/Ventilation fan inop repair/replace
- 2.3 Kitchen/Electrical Hazards GFCI outlet missing

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Chen G Bian 3273 Withers Ave Lafayette, CA 94549-1942 Property: 2804 SHANE DR RICHMOND, CA 94806-2621-

PropID:

Client ID: 11582

Dear Owner/Agent,

This letter is to inform you that your property at **2804 SHANE DR RICHMOND**, **CA 94806-2621 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 8.7 General Health and Safety/Other Interior Hazards hallway smoke detector missing -repair/replace
- 3.12 Bathroom/Tub or Shower hallway shower handle not properly secure repair/replace
- 2.10 Kitchen/Stove or Range with Oven all burners must self ignite repair/replace
- 1.4 Living Room/Security patio door not locking properly repair/replace



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Rosemary Hoang 9461 Wellington Cir Windsor, CA 95492-8511 Property: 2951 GOMER DR RICHMOND, CA 94806-2652-

PropID:

Client ID: 7314

Dear Owner/Agent,

This letter is to inform you that your property at **2951 GOMER DR RICHMOND**, CA **94806-2652 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 4.10 Other Rooms/Smoke Detectors bedroom smoke detector inop repair/replace
- 4.4 Other Rooms/Security clear egress from blocking bedroom window
- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit both toilet bases are loose repair/replace
- 3.3 Bathroom/Electrical Hazards hallway GFCI outlet missing repair/replace
- 7.2 Heating and Plumbing/Safety of Heating Equipment clear egress blocking access to water heater



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

John W & Gwendolyn M Downs Po Box 4345 Vallejo, CA 94591-7271 Property: 3058 BIRMINGHAM DR RICHMOND, CA 94806-2668-

PropID:

Client ID: 6109

Dear Owner/Agent,

This letter is to inform you that your property at **3058 BIRMINGHAM DR RICHMOND, CA 94806-2668 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.10 Other Rooms/Smoke Detectors bedroom smoke detector inop repair/replace
- 8.7 General Health and Safety/Other Interior Hazards clear egress/items blocking access to washroom door
- 5.3 Secondary Rooms/Electrical Hazards garage light switch not working properly has short repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Susan Sheng Warren Li 3273 Withers Ave Lafayette, CA 94549-1942 Property: 2718 SHANE DR RICHMOND, CA 94806-3129-

PropID:

Client ID: 9061

Dear Owner/Agent,

This letter is to inform you that your property at **2718 SHANE DR RICHMOND**, **CA 94806-3129 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

2.10 Kitchen/Stove or Range with Oven all burners must self ignite - repair/replace control panel damaged repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Daniel M Partridge 1250 Navellier St El Cerrito, CA 94530-2447 Property: 6325 MONTE CRESTA AVE RICHMOND, CA 94806-4245-

PropID:

Client ID: 1773

Dear Owner/Agent,

This letter is to inform you that your property at 6325 MONTE CRESTA AVE RICHMOND, CA 94806-4245 failed the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 3.12 Bathroom/Tub or Shower master bed shower H/C handle not secure repair/replace
- 2.10 Kitchen/Stove or Range with Oven burners must self ignite repair/replace
- 2.3 Kitchen/Electrical Hazards GFCI outlet missing
- 6.3 Building Exterior/Condition of Roof and Gutters back of house gutters need to be cleaned out repair/replace



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Gregory E Conrad 885 Marlesta Rd Pinole, CA 94564 Property: 1608 25TH ST RICHMOND, CA 94806-4516-

PropID:

Client ID: 3317

Dear Owner/Agent,

This letter is to inform you that your property at **1608 25TH ST RICHMOND**, CA **94806-4516 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 8.10 General Health and Safety/Site and Neighborhood Conditions no visible address on front of house
- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit toilet base loose repair/replace
- 8.7 General Health and Safety/Other Interior Hazards
 Co detector inop repair/replace
- 2.10 Kitchen/Stove or Range with Oven hood range light/fan cover not properly secure reapir/replace
- 2.4 Kitchen/Security clear egress/items blocking back door from opening fully
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment top of heater not properly secured repair/replace



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Jenny Sau Kit Chao Yang 988 Franklin St #310 Oakland, CA 94607-4298 Property: 3675 S STONEGLEN RICHMOND, CA 94806-5261-

PropID:

Client ID: 7378

Dear Owner/Agent,

This letter is to inform you that your property at **3675 S STONEGLEN RICHMOND**, CA **94806-5261 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 1.8 Living Room/Floor Condition carpeting throughout unit worn repair/replace
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment heater inop repair/replace
- 4.4 Other Rooms/Security remove key door lock from bedroom door
- 2.3 Kitchen/Electrical Hazards
 GFCI outlet missing
- 2.10 Kitchen/Stove or Range with Oven broiler inop repair/replace hood range fan inop repair/replace
- 2.12 Kitchen/Sink garbage disposal inop repair/replace



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Jamshid & Ivanka F Shakiba 1933 San Antonio St Berkeley, CA 94707-1649 Property: 2545 GROVEVIEW DR RICHMOND, CA 94806-5701-

PropID:

Client ID: 3034

Dear Owner/Agent,

This letter is to inform you that your property at **2545 GROVEVIEW DR RICHMOND**, CA **94806-5701 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.7 General Health and Safety/Other Interior Hazards
 1st fl Co detector missing
- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit toilet base loose repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Luong C Le 2228 Chipman St Alameda, CA 94501-3173 Property: 3314 PARK RIDGE DR RICHMOND, CA 94806-5816-

PropID:

Client ID: 8369

Dear Owner/Agent,

This letter is to inform you that your property at **3314 PARK RIDGE DR RICHMOND, CA 94806-5816 failed** the Housing Quality Standards (HQS) inspection on 10/27/2025.

A re-inspection has been scheduled for 12/19/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 4.4 Other Rooms/Security remove key locks from all bedroom doors
- 8.1 General Health and Safety/Access to Unit garage door not closing properly repair/replace
- 8.6 General Health and Safety/Interior Stairs and Common Halls 2nd fl hallway smoke inop repair/replace
- 3.11 Bathroom/Fixed Wash Basin or Lavatory in Unit master bedroom faucet base loose repair/replace



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,