

FAILED INSPECTION NOTICE

236 MARINA LAKES DR RICHMOND, CA 94804PropID:

Client ID: 9681

Dear Current Resident,

This letter is to inform you that your property at **236 MARINA LAKES DR RICHMOND, CA 94804 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/10/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 7.2 Heating and Plumbing/Safety of Heating Equipment Tenant to clear items blocking bedroom heater.
- 8.4 General Health and Safety/Garbage and Debris
 - Declutter unit
- 7.4 Heating and Plumbing/Water Heater
 Clear personal items being stored in hot water heater closet
- 4.5 Other Rooms/Window Condition Move items blocking clear path to window. Window must be inspected.
- 3.12 Bathroom/Tub or Shower
 - Caulk inside of tub enclosure
- 4.10 Other Rooms/Smoke Detectors
 - Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions.
 - -REPLACE, exceeds 10 year life span



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

2842 TULARE AVE RICHMOND, CA 94804-1028-

· -- 0**-22**

Client ID: 9723

PropID:

Dear Current Resident,

This letter is to inform you that your property at **2842 TULARE AVE RICHMOND**, **CA 94804-1028 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.7 General Health and Safety/Other Interior Hazards
 - 1. Carbon monoxide detector inoperable, replace
 - level 1
 - 2. Install carbon monoxide detector lower level
- 8.6 General Health and Safety/Interior Stairs and Common Halls Common area smoke detector missing, replace
- 3.12 Bathroom/Tub or Shower
 - Leak behind shower control knob, repair
- 4.4 Other Rooms/Security
 - Remove keyed lock from interior door.
- 4.10 Other Rooms/Smoke Detectors

Smoke detector is missing. All units must have at least one operable smoke detector in each bedroom and in a common area on each level.

- LOWER LEVEL BEDROOM



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

2725 RHEEM AVE RICHMOND, CA 94804-1076PropID:

Client ID: 9297

Dear Current Resident,

This letter is to inform you that your property at **2725 RHEEM AVE RICHMOND, CA 94804-1076 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 4.10 Other Rooms/Smoke Detectors

 Smoke detector is missing. All units must have at least one operable smoke detector in each bedroom and in a common area on each level.
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair
- 3.12 Bathroom/Tub or Shower
 Install safety guides for glass shower doors lower level.
- 8.4 General Health and Safety/Garbage and Debris Remove refrigerator from rear exterior



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

2747 RHEEM AVE RICHMOND, CA 94804-1076PropID:

Client ID: 9021

Dear Current Resident,

This letter is to inform you that your property at **2747 RHEEM AVE RICHMOND, CA 94804-1076 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.12 Bathroom/Tub or Shower Shower head leaking, repair
- 2.12 Kitchen/Sink Garbage disposal inoperable, repair/replace or remove

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

2322 ANDRADE AVE Apt C RICHMOND, CA 94804-1255PropID:

Client ID: 11429

Dear Current Resident,

This letter is to inform you that your property at **2322 ANDRADE AVE Apt C RICHMOND, CA 94804-1255 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

4.3 Other Rooms/Electrical Hazards open ground outlet. replace outlet

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

2322 ANDRADE AVE Apt D RICHMOND, CA 94804-1255PropID:

Client ID: 11429

Dear Current Resident,

This letter is to inform you that your property at **2322 ANDRADE AVE Apt D RICHMOND**, CA **94804-1255 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

3.12 Bathroom/Tub or Shower

remove black discoloration and rust from tub.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3121 ESMOND AVE RICHMOND, CA 94804-1319-

71: . ID = 5270

PropID:

Client ID: 5378

Dear Current Resident,

This letter is to inform you that your property at **3121 ESMOND AVE RICHMOND, CA 94804-1319 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 1.3 Living Room/Electrical Hazards
 Three prong outlet not testing as designed, must be grounded, replaced with a
 two-prong outlet or replaced with a GFCI.
 - DINING ROOM outlets have open grounds
- 3.3 Bathroom/Electrical Hazards
 GFCI has hot/neutral reverse, repair
- 8.1 General Health and Safety/Access to Unit Install deadbolt lock on rear door
- 6.2 Building Exterior/Condition of Stairs, Rails, and Porches Rear patio deck boards dry rotted, repair damaged boards



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

2422 GARVIN AVE RICHMOND, CA 94804-1347PropID:

Client ID: 4389

Dear Current Resident,

This letter is to inform you that your property at **2422 GARVIN AVE RICHMOND, CA 94804-1347 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 4.10 Other Rooms/Smoke Detectors
 - Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package instructions.
 - replace, exceeds 10 year life span
- 8.7 General Health and Safety/Other Interior Hazards
 Replace common area smoke detector level 2
- 3.12 Bathroom/Tub or Shower
 - Shower head leaking, repair
- 8.10 General Health and Safety/Site and Neighborhood Conditions
 Rear right fence top rail dry rooted, remove or repair damaged section of top railing above fence



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

752 30TH ST RICHMOND, CA 94804-1406PropID:

Client ID: 6179

Dear Current Resident,

This letter is to inform you that your property at **752 30TH ST RICHMOND**, CA **94804-1406 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 1.3 Living Room/Electrical Hazards
 Three prong outlet not testing as designed, must be grounded, replaced with a
 two-prong outlet or replaced with a GFCI.
- 4.3 Other Rooms/Elecrtical Hazards
 Three prong outlet not testing as designed, must be grounded, replaced with a
 two-prong outlet or replaced with a GFCI.
- 4.10 Other Rooms/Smoke Detectors Smoke detector is missing. All units must have at least one operable smoke detector in each bedroom and in a common area on each level.



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

2710 DOWNER AVE RICHMOND, CA 94804-1440-

Client ID: 10012

PropID:

Dear Current Resident,

This letter is to inform you that your property at **2710 DOWNER AVE RICHMOND, CA 94804-1440 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 1.3 Living Room/Electrical Hazards
 - Repair/Replace Wall Electrical Outlet.
 - replace damaged outlet at top of stairs
- 4.3 Other Rooms/Elecrtical Hazards
 - Damaged outlet presents an electrical hazard.
 - replace damaged outlet underneath window
- 8.7 General Health and Safety/Other Interior Hazards
 - Replace inoperable CO2 detector, it exceeds 10 year life span (2013)
- 8.6 General Health and Safety/Interior Stairs and Common Halls
 - Replace inoperable common area smoke detector, exceeds 10 year life span (2011)



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

544 28TH ST RICHMOND, CA 94804-1516-

·

PropID:

Client ID: 6170

Dear Current Resident,

This letter is to inform you that your property at **544 28TH ST RICHMOND**, CA **94804-1516 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

8.6 General Health and Safety/Interior Stairs and Common Halls
Replace common area smoke detector, exceeds 10 year life span

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

613 30TH ST RICHMOND, CA 94804-1525PropID:

Client ID: 9441

Dear Current Resident,

This letter is to inform you that your property at **613 30TH ST RICHMOND**, CA **94804-1525 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 4.10 Other Rooms/Smoke Detectors
 Replace smoke detector in lower level bedroom, exceeds 10 year life span
- 8.6 General Health and Safety/Interior Stairs and Common Halls
 Common area smoke detector level 2 exceeds 10 year life span, replace
- 3.3 Bathroom/Electrical Hazards

 Three prong outlet not testing as designed, must be grounded, replaced with a two-prong outlet or replaced with a GFCI.
 - Lower level bathroom
- 2.10 Kitchen/Stove or Range with Oven Front left burner inoperable, repair



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

673 33RD ST RICHMOND, CA 94804-1537PropID:

Client ID: 6699

Dear Current Resident,

This letter is to inform you that your property at **673 33RD ST RICHMOND**, CA **94804-1537 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.3 Other Rooms/Elecrtical Hazards
 - Damaged outlet presents an electrical hazard.
 - replace cracked receptacle left of patio door
- 6.4 Building Exterior/Condition of Exterior Surfaces
 Rear exterior outlet has cracked receptacle, replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3110 ROOSEVELT AVE RICHMOND, CA 94804-1546-

·

Client ID: 7318

PropID:

Dear Current Resident,

This letter is to inform you that your property at 3110 ROOSEVELT AVE RICHMOND, CA 94804-1546 failed the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 8.6 General Health and Safety/Interior Stairs and Common Halls Repair cracks on hallway ceiling
- 4.4 Other Rooms/Security
 Install door knob on door, door knob not present on bedroom door
- 4.3 Other Rooms/Elecrtical Hazards Three prong outlet not testing as designed, must be grounded or replaced with a GFCI.
- 3.3 Bathroom/Electrical Hazards
 - Three prong outlet not testing as designed, must be grounded, replaced with a two-prong outlet or replaced with a GFCI.
 - -GFCI has hot/neutral reverse, repair
- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit Bath Toilet not secured properly to floor.
- 3.12 Bathroom/Tub or Shower
 Repair leak behind cold water control knob



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3227 ROOSEVELT AVE RICHMOND, CA 94804-1547PropID:

Client ID: 2721

Dear Current Resident,

This letter is to inform you that your property at **3227 ROOSEVELT AVE RICHMOND**, **CA 94804-1547 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.12 Bathroom/Tub or Shower
 Resurface tub, peeling paint and rust present.
- 1.4 Living Room/Security

 Remove sliding lock from bottom of front door

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

452 30TH ST RICHMOND, CA 94804-1741PropID: Client ID: 7241

Dear Current Resident,

This letter is to inform you that your property at **452 30TH ST RICHMOND**, CA **94804-1741 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/16/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 3.3 Bathroom/Electrical Hazards
 Install GFCI protected outlet by sink
- 4.10 Other Rooms/Smoke Detectors Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package instructions.
 - Replace, exceeds 10 year life span (2008)
- 8.1 General Health and Safety/Access to Unit Install deadbolt on rear door
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair
- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit
 TOILET IN REAR BATHROOM BY REAR DOOR IS INOPERABLE, REPAIR



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

45 GROVE ST RICHMOND, CA 94804-1917PropID:

Client ID: 9127

Dear Current Resident,

This letter is to inform you that your property at **45 GROVE ST RICHMOND**, CA **94804-1917 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/10/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 4.3 Other Rooms/Elecrtical Hazards Three prong outlet not testing as designed, must be grounded or replaced with a GFCI.
- 4.10 Other Rooms/Smoke Detectors Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package instructions.
 - REPLACE, exceeds 10 year life span
- 2.10 Kitchen/Stove or Range with Oven Front right burner inoperable, repair



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3195 GARRITY WAY Apt 824 RICHMOND, CA 94806-5869-

·

Client ID: 15298

PropID:

Dear Current Resident,

This letter is to inform you that your property at 3195 GARRITY WAY Apt 824 RICHMOND, CA 94806-5869 failed the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/17/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 1.3 Living Room/Electrical Hazards outlet cover not secure repair/replace
- 1.4 Living Room/Security alarm not connected properly repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3195 GARRITY WAY Apt 825 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at 3195 GARRITY WAY Apt 825 RICHMOND, CA 94806-5869 failed the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/17/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

3.12 Bathroom/Tub or Shower diverter not working properly - repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3195 GARRITY WAY Apt 826 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at 3195 GARRITY WAY Apt 826 RICHMOND, CA 94806-5869 failed the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/17/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

3.12 Bathroom/Tub or Shower wall peeling behind shower head - repair/repaint

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3195 GARRITY WAY Apt 827 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at 3195 GARRITY WAY Apt 827 RICHMOND, CA 94806-5869 failed the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/17/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

7.2 Heating and Plumbing/Safety of Heating Equipment clear egress items blocking water heater door clear egress /items around/blocking water heater access

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3195 GARRITY WAY Apt 828 RICHMOND, CA 94806-5869-

Client ID: 15298

PropID:

Dear Current Resident,

This letter is to inform you that your property at 3195 GARRITY WAY Apt 828 RICHMOND, CA 94806-5869 failed the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/17/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 1.4 Living Room/Security alarm system not properly secured /working properly repair
- 7.2 Heating and Plumbing/Safety of Heating Equipment clear egress /items around/blocking water heater access

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3195 GARRITY WAY Apt 832 RICHMOND, CA 94806-5869-

Client ID: 15298

PropID:

Dear Current Resident,

This letter is to inform you that your property at 3195 GARRITY WAY Apt 832 RICHMOND, CA 94806-5869 failed the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/17/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

- 7.1 Heating and Plumbing/Adequacy of Heating Equipment heater control not working properly repair/replace fire place not working properly -repair
- 3.12 Bathroom/Tub or Shower tub peeling resurface/repair
- 2.12 Kitchen/SinkDishwasher not working properly repair/replace
- 7.2 Heating and Plumbing/Safety of Heating Equipment fire place inop -repair
- 1.4 Living Room/Security patio screen door off track repair/replace



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3195 GARRITY WAY Apt 833 RICHMOND, CA 94806-5869-

Client ID: 15298

PropID:

Dear Current Resident,

This letter is to inform you that your property at 3195 GARRITY WAY Apt 833 RICHMOND, CA 94806-5869 failed the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/17/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.7 General Health and Safety/Other Interior Hazards hallway smoke detector missing
- 7.2 Heating and Plumbing/Safety of Heating Equipment clear egress /items around/blocking water heater access

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3195 GARRITY WAY Apt 835 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at 3195 GARRITY WAY Apt 835 RICHMOND, CA 94806-5869 failed the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 7.1 Heating and Plumbing/Adequacy of Heating Equipment heater control not working properly repair/replace
- 7.2 Heating and Plumbing/Safety of Heating Equipment clear egress /items around/blocking water heater access

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3195 GARRITY WAY Apt 836 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at 3195 GARRITY WAY Apt 836 RICHMOND, CA 94806-5869 failed the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 7.1 Heating and Plumbing/Adequacy of Heating Equipment heater not working properly repair/replace
- 3.12 Bathroom/Tub or Shower tub diverter not working properly repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3195 GARRITY WAY Apt 837 RICHMOND, CA 94806-5869-

C1: 4 ID 15200

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at 3195 GARRITY WAY Apt 837 RICHMOND, CA 94806-5869 failed the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

2.12 Kitchen/Sink

dishwasher not working properly - repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3195 GARRITY WAY Apt 838 RICHMOND, CA 94806-5869-

C1' 4 ID 15200

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at 3195 GARRITY WAY Apt 838 RICHMOND, CA 94806-5869 failed the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

8.7 General Health and Safety/Other Interior Hazards hallway smoke detector missing - repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3199 GARRITY WAY Apt 918 RICHMOND, CA 94806-5869-

Client ID: 15298

PropID:

Dear Current Resident,

This letter is to inform you that your property at **3199 GARRITY WAY Apt 918 RICHMOND**, CA **94806-5869 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 1.8 Living Room/Floor Condition carpeting throughout entire unit damaged/ worn repair/replace
- 2.10 Kitchen/Stove or Range with Oven hood range light inop repair/replace
- 2.4 Kitchen/Security bottom of back door corroding repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3199 GARRITY WAY Apt 921 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at **3199 GARRITY WAY Apt 921 RICHMOND**, CA **94806-5869 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

7.2 Heating and Plumbing/Safety of Heating Equipment clear egress /items around/blocking water heater access

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3199 GARRITY WAY Apt 923 RICHMOND, CA 94806-5869PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at **3199 GARRITY WAY Apt 923 RICHMOND**, CA **94806-5869 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

7.2 Heating and Plumbing/Safety of Heating Equipment clear egress /items around/blocking water heater access

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3199 GARRITY WAY Apt 927 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at **3199 GARRITY WAY Apt 927 RICHMOND**, CA **94806-5869 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.5 Other Rooms/Window Condition clear egress blocking window access
- 7.2 Heating and Plumbing/Safety of Heating Equipment clear egress /items around/blocking water heater access
- 1.4 Living Room/Security patio screen door worn/corroding repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3199 GARRITY WAY Apt 931 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at **3199 GARRITY WAY Apt 931 RICHMOND**, CA **94806-5869 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

7.2 Heating and Plumbing/Safety of Heating Equipment clear egress /items around/blocking water heater access

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3199 GARRITY WAY Apt 933 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at **3199 GARRITY WAY Apt 933 RICHMOND**, CA **94806-5869 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

7.2 Heating and Plumbing/Safety of Heating Equipment clear egress /items around/blocking water heater access

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3199 GARRITY WAY Apt 934 RICHMOND, CA 94806-5869-

Client ID: 15298

PropID:

Dear Current Resident,

This letter is to inform you that your property at **3199 GARRITY WAY Apt 934 RICHMOND**, CA **94806-5869 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

7.2 Heating and Plumbing/Safety of Heating Equipment clear egress /items around/blocking water heater access

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3199 GARRITY WAY Apt 935 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at **3199 GARRITY WAY Apt 935 RICHMOND, CA 94806-5869 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 7.2 Heating and Plumbing/Safety of Heating Equipment clear egress /items around/blocking water heater access
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment heater not working properly repair/replace
- 8.7 General Health and Safety/Other Interior Hazards clear egress in front of patio door
- 1.4 Living Room/Security patio screen door not locking properly repair /replace



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3199 GARRITY WAY Apt 936 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at **3199 GARRITY WAY Apt 936 RICHMOND**, CA **94806-5869 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

7.2 Heating and Plumbing/Safety of Heating Equipment clear egress /items around/blocking water heater access

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3199 GARRITY WAY Apt 937 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at **3199 GARRITY WAY Apt 937 RICHMOND**, CA **94806-5869 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

7.2 Heating and Plumbing/Safety of Heating Equipment clear egress /items around/blocking water heater access

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

3199 GARRITY WAY Apt 938 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Current Resident,

This letter is to inform you that your property at **3199 GARRITY WAY Apt 938 RICHMOND**, CA **94806-5869 failed** the Housing Quality Standards (HQS) inspection on 10/24/2025.

A re-inspection has been scheduled for 12/18/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

7.1 Heating and Plumbing/Adequacy of Heating Equipment unable to inspect water heater due to items blocking door - clear egress/items blocking door

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,