



11/12/2025

FAILED INSPECTION NOTICE

2837 MAY RD
RICHMOND, CA 94803-

PropID:
Client ID: 4410

Dear Current Resident,

This letter is to inform you that your property at **2837 MAY RD RICHMOND, CA 94803** failed the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/18/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS</u>
4.4	Other Rooms/Security remove key door lock from bedroom door
8.7	General Health and Safety/Other Interior Hazards living room smoke/Co detector missing
7.2	Heating and Plumbing/Safety of Heating Equipment earthquake straps missing
2.12	Kitchen/Sink faucet base not properly secure / faucet not shutting off properly - repair/replace
4.6	Other Rooms/Celing Condition master bedroom ceiling very badly discolored - room has a very damp smell - remove /repair/
3.3	Bathroom/Electrical Hazards master bedroom GFCI outlet missing
3.12	Bathroom/Tub or Shower hallway tub peeling - resurface/repair/replace



11/12/2025

FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

3110 FLORIDA AVE
RICHMOND, CA 94804-3110-

PropID:
Client ID: 8395

Dear Current Resident,

This letter is to inform you that your property at **3110 FLORIDA AVE RICHMOND, CA 94804-3110** **failed** the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/23/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS</u>
8.7	General Health and Safety/Other Interior Hazards clear egress blocking back door from opening fully
4.10	Other Rooms/Smoke Detectors bedroom smoke detectors missing
7.1	Heating and Plumbing/Adequacy of Heating Equipment heater inop - repair/replace
7.2	Heating and Plumbing/Safety of Heating Equipment clear egress blocking heater



11/12/2025

FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

5825 PANAMA AVE
RICHMOND, CA 94804-5521-

PropID:
Client ID: 4144

Dear Current Resident,

This letter is to inform you that your property at **5825 PANAMA AVE RICHMOND, CA 94804-5521** **failed** the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/18/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an “O” are the responsibility of the Owner and the items marked with a “T” are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR “FAIL” RATING AND OTHER COMMENTS</u>
4.10	Other Rooms/Smoke Detectors Replace, current smoke detector exceeds 10 year life span
2.12	Kitchen/Sink Repair kitchen faucet, leaking while in use in rear.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

5735 COLUMBIA AVE
RICHMOND, CA 94804-5631-

PropID:
Client ID: 10409

Dear Current Resident,

This letter is to inform you that your property at **5735 COLUMBIA AVE RICHMOND, CA 94804-5631** **failed** the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/18/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an “O” are the responsibility of the Owner and the items marked with a “T” are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR “FAIL” RATING AND OTHER COMMENTS</u>
4.10	Other Rooms/Smoke Detectors Replace, current smoke detector exceeds 10 year life span
8.6	General Health and Safety/Interior Stairs and Common Halls Replace, current smoke detector exceeds 10 year life span - Common area level 2

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

6001 SACRAMENTO AVE
RICHMOND, CA 94804-5729-

PropID:
Client ID: 7119

Dear Current Resident,

This letter is to inform you that your property at **6001 SACRAMENTO AVE RICHMOND, CA 94804-5729** failed the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/18/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an “O” are the responsibility of the Owner and the items marked with a “T” are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR “FAIL” RATING AND OTHER COMMENTS</u>
4.10	Other Rooms/Smoke Detectors Replace, current smoke detector exceeds 10 year life span

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

6000 COLUMBIA AVE
RICHMOND, CA 94804-5736-

PropID:
Client ID: 1753

Dear Current Resident,

This letter is to inform you that your property at **6000 COLUMBIA AVE RICHMOND, CA 94804-5736** **failed** the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/18/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS</u>
4.10 Other Rooms/Smoke Detectors	Replace, current smoke detector exceeds 10 year life span
8.6 General Health and Safety/Interior Stairs and Common Halls	Replace rear common area smoke detector outside of bedroom 3, exceeds 10 year life span.
2.12 Kitchen/Sink	Garbage disposal inoperable, repair/replace or remove



11/12/2025

FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

5832 SAN JOSE AVE
RICHMOND, CA 94804-5917-

PropID:
Client ID: 6710

Dear Current Resident,

This letter is to inform you that your property at **5832 SAN JOSE AVE RICHMOND, CA 94804-5917** **failed** the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/18/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS</u>
4.4	Other Rooms/Security Remove keyed lock from interior door.
2.10	Kitchen/Stove or Range with Oven Burners on tenant supplied stove not self lighting, repair
1.3	Living Room/Electrical Hazards Three prong outlet not testing as designed, must be grounded, replaced with a two-prong outlet or replaced with a GFCI.
4.3	Other Rooms/Electrical Hazards A missing and/or cracked coverplate presents an electrical hazard. - outlet right of window missing cover plate
3.12	Bathroom/Tub or Shower Tenant supplied shower head leaking in rear, repair



11/12/2025

FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

234 SHORELINE CT
RICHMOND, CA 94804-7435-

PropID:
Client ID: 12924

Dear Current Resident,

This letter is to inform you that your property at **234 SHORELINE CT RICHMOND, CA 94804-7435** **failed** the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/19/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an “O” are the responsibility of the Owner and the items marked with a “T” are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR “FAIL” RATING AND OTHER COMMENTS</u>
4.10	Other Rooms/Smoke Detectors Replace, current smoke detector exceeds 10 year life span.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

64 BAYSIDE CT
RICHMOND, CA 94804-7444-

PropID:
Client ID: 6643

Dear Current Resident,

This letter is to inform you that your property at **64 BAYSIDE CT RICHMOND, CA 94804-7444** failed the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/19/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an “O” are the responsibility of the Owner and the items marked with a “T” are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR “FAIL” RATING AND OTHER COMMENTS</u>
4.10	Other Rooms/Smoke Detectors Smoke detector is missing. All units must have at least one operable smoke detector in each bedroom and in a common area on each level.
6.4	Building Exterior/Condition of Exterior Surfaces Secure exterior outlet to wall, receptacles not secured to wall at time of inspection.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

12 MARINA LAKES DR
RICHMOND, CA 94804-7447-

PropID:
Client ID: 1794

Dear Current Resident,

This letter is to inform you that your property at **12 MARINA LAKES DR RICHMOND, CA 94804-7447** **failed** the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/19/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an “O” are the responsibility of the Owner and the items marked with a “T” are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR “FAIL” RATING AND OTHER COMMENTS</u>
1.5	Living Room/Window Condition Window screen damaged, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

169 MARINA LAKES DR
RICHMOND, CA 94804-7453-

PropID:
Client ID: 2770

Dear Current Resident,

This letter is to inform you that your property at **169 MARINA LAKES DR RICHMOND, CA 94804-7453** failed the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/19/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an “O” are the responsibility of the Owner and the items marked with a “T” are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR “FAIL” RATING AND OTHER COMMENTS</u>
4.10	Other Rooms/Smoke Detectors Replace, current smoke detector exceeds 10 year life span.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

145 BAYSIDE CT
RICHMOND, CA 94804-7458-

PropID:
Client ID: 2338

Dear Current Resident,

This letter is to inform you that your property at **145 BAYSIDE CT RICHMOND, CA 94804-7458** failed the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/19/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS</u>
4.10	Other Rooms/Smoke Detectors Replace, current smoke detector exceeds 10 year life span.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

977 KERN ST
RICHMOND, CA 94805-1120-

PropID:
Client ID: 7101

Dear Current Resident,

This letter is to inform you that your property at **977 KERN ST RICHMOND, CA 94805-1120** failed the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/22/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an “O” are the responsibility of the Owner and the items marked with a “T” are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR “FAIL” RATING AND OTHER COMMENTS</u>
1.6	Living Room/Ceiling Condition large cracks in ceiling throughout house - repair
2.3	Kitchen/Electrical Hazards GFCI outlet on right side of sink not resetting - repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

793 MC LAUGHLIN ST
RICHMOND, CA 94805-1454-

PropID:
Client ID: 2960

Dear Current Resident,

This letter is to inform you that your property at **793 MC LAUGHLIN ST RICHMOND, CA 94805-1454** **failed** the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/22/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS</u>
4.4	Other Rooms/Security remove key lock from bedroom door

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

789 KERN ST
RICHMOND, CA 94805-1564-

PropID:
Client ID: 6705

Dear Current Resident,

This letter is to inform you that your property at **789 KERN ST RICHMOND, CA 94805-1564** failed the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/22/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS</u>
2.3	Kitchen/Electrical Hazards GFCI outlet missing

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

656 34TH ST
RICHMOND, CA 94805-1752-

PropID:
Client ID: 7115

Dear Current Resident,

This letter is to inform you that your property at **656 34TH ST RICHMOND, CA 94805-1752** failed the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/22/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an “O” are the responsibility of the Owner and the items marked with a “T” are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR “FAIL” RATING AND OTHER COMMENTS</u>
3.3	Bathroom/Electrical Hazards GFCI outlet missing

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program



11/12/2025

FAILED INSPECTION NOTICE

611 41ST ST
RICHMOND, CA 94805-1820-

PropID:
Client ID: 9223

Dear Current Resident,

This letter is to inform you that your property at **611 41ST ST RICHMOND, CA 94805-1820** failed the Housing Quality Standards (HQS) inspection on 10/29/2025.

A re-inspection has been scheduled for 12/22/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an “O” are the responsibility of the Owner and the items marked with a “T” are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	<u>REASON(S) FOR “FAIL” RATING AND OTHER COMMENTS</u>
8.7	General Health and Safety/Other Interior Hazards living room hallway smoke detector missing

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,

City of Richmond
Residential Rental Inspections Program