

## FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 575 BERK AVE Apt 3 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **575 BERK AVE Apt 3 RICHMOND, CA 94804 failed** the Housing Quality Standards (HQS) inspection on 11/14/2022.

A re-inspection has been scheduled for 01/09/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Tenant/Owner

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



# FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 640 S 37TH ST Apt 3 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **640 S 37TH ST Apt 3 RICHMOND**, **CA 94804 failed** the Housing Quality Standards (HQS) inspection on 11/14/2022.

# A re-inspection has been scheduled for 01/09/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Tenant/Owner

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



# FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 635 BERK AVE Apt 11 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 635 BERK AVE Apt 11 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 11/14/2022.

# A re-inspection has been scheduled for 01/09/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Tenant/Owner

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



# FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 600 S 37TH ST Apt 8 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **600 S 37TH ST Apt 8 RICHMOND**, **CA 94804 failed** the Housing Quality Standards (HQS) inspection on 11/14/2022.

# A re-inspection has been scheduled for 01/09/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Tenant/Owner

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



# FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 600 S 37TH ST Apt 11 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at 600 S 37TH ST Apt 11 RICHMOND, CA 94804 failed the Housing Quality Standards (HQS) inspection on 11/14/2022.

# A re-inspection has been scheduled for 01/09/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Tenant/Owner

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



# FAILED INSPECTION NOTICE

Monterey Venture Lp Tina Coyer 680 S 37Th St Richmond, CA 94804 Property: 620 S 37TH ST Apt 4 RICHMOND, CA 94804-

PropID:

Client ID: 15121

Dear Owner/Agent,

This letter is to inform you that your property at **620 S 37TH ST Apt 4 RICHMOND**, **CA 94804 failed** the Housing Quality Standards (HQS) inspection on 11/14/2022.

# A re-inspection has been scheduled for 01/09/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Tenant/Owner

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,