

FAILED INSPECTION NOTICE

George C T Young Bartels Property Management 12996 San Pablo Ave Richmond, CA 94805 Property: 5109 HEAVENLY RIDGE LN RICHMOND, CA 94803-2540-

PropID:

Client ID: 7267

Dear Owner/Agent,

This letter is to inform you that your property at 5109 HEAVENLY RIDGE LN RICHMOND, CA 94803-2540 failed the Housing Quality Standards (HQS) inspection on 12/29/2022.

A re-inspection has been scheduled for 02/13/2023 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.12	Bathroom/Tub or Shower	O
	replace/ tub diverter not working as designed (Hallway)	
2.10	Kitchen/Stove or Range with Oven	O
	repair/replace- loud knocking hood range fan	
6.1	Building Exterior/Condition of Foundation	O
	replace/ missing outlet cover with exposed wiring posing safety hazard (right	
	outside corner of garage)	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Kang Sheng Kuo Tre 832 Adams St Albany, CA 94706 Property: 5528 SOLANO AVE RICHMOND, CA 94805-1532-

PropID:

Client ID: 8751

Dear Owner/Agent,

This letter is to inform you that your property at **5528 SOLANO AVE RICHMOND, CA 94805-1532 failed** the Housing Quality Standards (HQS) inspection on 12/29/2022.

A re-inspection has been scheduled for 02/13/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.3	Bathroom/Electrical Hazards	O
	repair/ missing ceiling light fixture cover; LOC rear bathroom	
4.6	Other Rooms/Celing Condition	O
	repair/ ceiling with large very large bulging; posing safety hazard	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Yvonne Ramirez Hernandez 22500 Fast Ct Bakersfield, CA 93314-8301 Property: 629 36TH ST RICHMOND, CA 94805-1755-

PropID:

Client ID: 3508

Dear Owner/Agent,

This letter is to inform you that your property at **629 36TH ST RICHMOND**, CA **94805-1755 failed** the Housing Quality Standards (HQS) inspection on 12/29/2022.

A re-inspection has been scheduled for 02/13/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
7.1	Heating and Plumbing/Adequacy of Heating Equipment	O
	heater inop/ repair (wall heater) LOC- livingroom & hall	
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	co2 detector inop/ LOC- hallway	
3.12	Bathroom/Tub or Shower	O
	replace/missing shower handle; LOC- hallway	
	replace/tub diverter not working as designed	
	replace/ missing shower handle; LOC- basement bathroom	
4.10	Other Rooms/Smoke Detectors	O
	smoke detector inop/ LOC; basement bedroom left	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Kan Chuen Chan 1075 Millbrae Ave Millbrae, CA 94030-3065 Property: 3921 BARRETT AVE Apt B RICHMOND, CA 94805-1823-

PropID:

Client ID: 5313

Dear Owner/Agent,

This letter is to inform you that your property at **3921 BARRETT AVE Apt B RICHMOND**, CA **94805-1823 failed** the Housing Quality Standards (HQS) inspection on 12/29/2022.

A re-inspection has been scheduled for 02/13/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.7 General Health and Safety/Other Interior Hazards Outlets in entire house - open ground - repair/replace 12/29/22 all out lets were change through unit, 1 outlet has no, power top first prong/ replace ;LOC first left outlet upon entry

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

First Presbyterian Church 3415 Barrett Ave Richmond, CA 94805-2139 Property: 535 35TH ST RICHMOND, CA 94805-2123-

PropID:

Client ID: 4823

Dear Owner/Agent,

This letter is to inform you that your property at 535 35TH ST RICHMOND, CA 94805-2123 failed the Housing Quality Standards (HQS) inspection on 12/29/2022.

A re-inspection has been scheduled for 02/13/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit repair/ toilet not fully secured to flooring

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,