

FAILED INSPECTION NOTICE

Ka Man Chan 4167 Chaparral Pl Castro Valley, CA 94552-4906 Property: 334 S 38TH ST RICHMOND, CA 94804-3238-

PropID:

Client ID: 6145

Dear Owner/Agent,

This letter is to inform you that your property at **334 S 38TH ST RICHMOND**, **CA 94804-3238 failed** the Housing Quality Standards (HQS) inspection on 12/17/2025.

A re-inspection has been scheduled for 01/21/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.7 Other Rooms/Wall Condition
 Repair hole on wall underneath window
- 8.10 General Health and Safety/Site and Neighborhood Conditions Remove old appliances from yard

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Zong Jian Kuang 150 Scotia Ave San Francisco, CA 94124-2220 Property: 410 S 45TH ST RICHMOND, CA 94804-3415-

PropID:

Client ID: 9472

Dear Owner/Agent,

This letter is to inform you that your property at **410 S 45TH ST RICHMOND**, **CA 94804-3415 failed** the Housing Quality Standards (HQS) inspection on 12/17/2025.

A re-inspection has been scheduled for 01/22/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.4 Other Rooms/Security
 Remove keyed lock from interior door.
- 3.3 Bathroom/Electrical Hazards
 Install GFCI by bathroom sink, level 1
- 8.1 General Health and Safety/Access to Unit
 Install door sweep on garage door leading to exterior

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Tony Jintao & Huann M Gu 912 Clement St San Francisco, CA 94118 Property: 4516 TAFT AVE RICHMOND, CA 94804-3450-

PropID:

Client ID: 8903

Dear Owner/Agent,

This letter is to inform you that your property at **4516 TAFT AVE RICHMOND**, CA **94804-3450 failed** the Housing Quality Standards (HQS) inspection on 12/17/2025.

A re-inspection has been scheduled for 01/22/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.



FAILED INSPECTION NOTICE

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.6 General Health and Safety/Interior Stairs and Common Halls
 - 1. C02 detector level 2 inoperable, replace
 - 2. Install common area smoke detector level 2
 - 3. Replace common area smoke detector level 1
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair
- 3.3 Bathroom/Electrical Hazards
 Replace missing light switch and outlet cover plates level 2
- 4.4 Other Rooms/Security
 Remove keyed lock from interior door.
- 4.3 Other Rooms/Elecrtical Hazards
 - A missing and/or cracked coverplate presents an electrical hazard.
 - outlet at entry missing cover plate, replace
- 4.5 Other Rooms/Window Condition
 - Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.
- 4.10 Other Rooms/Smoke Detectors
 - Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions.
- 8.1 General Health and Safety/Access to Unit Remove double keyed entry lock (deadbolt) from back door by kitchen
- 7.4 Heating and Plumbing/Water Heater install discharge pipe, within 6" of floor.
- 8.4 General Health and Safety/Garbage and Debris Declutter yard



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Jl Homeland Development Group 805 Sierra Pt Rd Brisbane, CA 94005 Property: 700 S 41ST ST RICHMOND, CA 94804-4304-

PropID:

Client ID: 10041

Dear Owner/Agent,

This letter is to inform you that your property at **700 S 41ST ST RICHMOND**, **CA 94804-4304 failed** the Housing Quality Standards (HQS) inspection on 12/17/2025.

A re-inspection has been scheduled for 01/22/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.3 Other Rooms/Elecrtical Hazards

 Damaged outlet presents an electrical hazard.
 - replace damaged outlet behind door
- 4.10 Other Rooms/Smoke Detectors

Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions.



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Yolanda A Lewis 361 Violet Rd Hercules, CA 94547-1028 Property: 555 S 47TH ST RICHMOND, CA 94804-4325-

PropID:

Client ID: 7638

Dear Owner/Agent,

This letter is to inform you that your property at **555 S 47TH ST RICHMOND, CA 94804-4325 failed** the Housing Quality Standards (HQS) inspection on 12/17/2025.

A re-inspection has been scheduled for 01/21/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

7.1 Heating and Plumbing/Adequacy of Heating Equipment
Heater inoperable, repair
12/17/2025 Thermostat wont allow temperature to change preventing heater from coming on.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Anselmo & Gloria Saucedo 205 Tingley St San Francisco, CA 94112-1937 Property: 4516 ESCUELA CT RICHMOND, CA 94804-4338-

PropID:

Client ID: 9534

Dear Owner/Agent,

This letter is to inform you that your property at **4516 ESCUELA CT RICHMOND, CA 94804-4338 failed** the Housing Quality Standards (HQS) inspection on 12/17/2025.

A re-inspection has been scheduled for 01/22/2026 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.6 Bathroom/Ceiling Condition Replace rusted vent cover
- 3.5 Bathroom/Window Condition Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.
- 3.12 Bathroom/Tub or Shower Replace damaged tub knob
- 4.3 Other Rooms/Elecrtical Hazards
 Replace damaged cover plate on outlet located by closet
- 8.1 General Health and Safety/Access to Unit
 Rear door by kitchen will not open, repair (fire exit)
- 2.13 Kitchen/Space for Storage, Prep and Serving Repair/replace damaged drawer front across from kitchen sink
- 2.12 Kitchen/Sink
 Remove personal items from dishwasher so it can be inspected



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Bre Piper Mf Tides Ca Llc 3185 Garrity Way Richmond, CA 94806 Property: 3193 GARRITY WAY Apt 237 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Owner/Agent,

This letter is to inform you that your property at 3193 GARRITY WAY Apt 237 RICHMOND, CA 94806-5869 failed the Housing Quality Standards (HQS) inspection on 12/17/2025.

A re-inspection has been scheduled for 01/26/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

1.8 Living Room/Floor Condition carpeting tearing /worn - repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Bre Piper Mf Tides Ca Llc 3185 Garrity Way Richmond, CA 94806 Property: 3194 GARRITY WAY Apt 1018 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Owner/Agent,

This letter is to inform you that your property at **3194 GARRITY WAY Apt 1018 RICHMOND**, CA **94806-5869 failed** the Housing Quality Standards (HQS) inspection on 12/17/2025.

A re-inspection has been scheduled for 01/26/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

3.10 Bathroom/Flush Toilet in Enclosed Room in Unit toilet base in bathroom loose - repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Bre Piper Mf Tides Ca Llc 3185 Garrity Way Richmond, CA 94806 Property: 3194 GARRITY WAY Apt 1035 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Owner/Agent,

This letter is to inform you that your property at **3194 GARRITY WAY Apt 1035 RICHMOND**, CA **94806-5869 failed** the Housing Quality Standards (HQS) inspection on 12/17/2025.

A re-inspection has been scheduled for 01/26/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

7.2 Heating and Plumbing/Safety of Heating Equipment clear egress/items around/blocking access to water heater

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Bre Piper Mf Tides Ca Llc 3185 Garrity Way Richmond, CA 94806 Property: 3194 GARRITY WAY Apt 1036 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Owner/Agent,

This letter is to inform you that your property at **3194 GARRITY WAY Apt 1036 RICHMOND**, CA **94806-5869 failed** the Housing Quality Standards (HQS) inspection on 12/17/2025.

A re-inspection has been scheduled for 01/26/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 7.2 Heating and Plumbing/Safety of Heating Equipment clear items/egress blocking access to water heater
- 3.3 Bathroom/Electrical Hazards
 GFCI outlet not testing repair/replace
- 1.4 Living Room/Security patio door handle broken

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Bre Piper Mf Tides Ca Llc 3185 Garrity Way Richmond, CA 94806 Property: 3195 GARRITY WAY Apt 832 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Owner/Agent,

This letter is to inform you that your property at 3195 GARRITY WAY Apt 832 RICHMOND, CA 94806-5869 failed the Housing Quality Standards (HQS) inspection on 12/17/2025.

A re-inspection has been scheduled for 01/26/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

7.1 Heating and Plumbing/Adequacy of Heating Equipment fire place not working properly -repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Bre Piper Mf Tides Ca Llc 3185 Garrity Way Richmond, CA 94806 Property: 3195 GARRITY WAY Apt 834 RICHMOND, CA 94806-5869-

PropID:

Client ID: 15298

Dear Owner/Agent,

This letter is to inform you that your property at 3195 GARRITY WAY Apt 834 RICHMOND, CA 94806-5869 failed the Housing Quality Standards (HQS) inspection on 12/17/2025.

A re-inspection has been scheduled for 01/26/2026 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit hallway toilet base loose repair/replace
- 2.10 Kitchen/Stove or Range with Oven hood range light inop
- 5.4 Secondary Rooms/Other Potential Hazardous Features laundry room fan cover missing repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,