

FAILED INSPECTION NOTICE

Gyandip Lama 5210 Victor Ave El Cerrito, CA 94530 Property: 733 36TH ST RICHMOND, CA 94805-

PropID:

Client ID: 18548

Dear Owner/Agent,

This letter is to inform you that your property at **733 36TH ST RICHMOND**, **CA 94805 failed** the Housing Quality Standards (HQS) inspection on 05/02/2023.

A re-inspection has been scheduled for 06/27/2023 between 01:00PM and 04:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
6.2	Building Exterior/Condition of Stairs, Rails, and Porches	O
	install handrail on exterior steps	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is missing/inop. All units must have at least one operable	
	smoke detector in each bedroom and in a common area on each level.	
8.7	General Health and Safety/Other Interior Hazards	O
	Unit must have one carbon monoxide detector per level	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Gyandip Lama 5210 Victor Ave El Cerrito, CA 94530 Property: 733 36TH ST Apt A RICHMOND, CA 94805-

PropID:

Client ID: 18548

Dear Owner/Agent,

This letter is to inform you that your property at **733 36TH ST Apt A RICHMOND**, CA **94805 failed** the Housing Quality Standards (HQS) inspection on 05/02/2023.

A re-inspection has been scheduled for 06/27/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is missing. All units must have at least one operable smoke	
	detector in each bedroom and in a common area on each level.	
8.7	General Health and Safety/Other Interior Hazards	O
	Unit must have one carbon monoxide detector per level.	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Sana Peterson Webb
5849 Robinhood Dr
El Sobrante, CA 94803

Property: 933 37TH ST RICHMOND, CA 94805-

PropID:

Client ID: 17709

Dear Owner/Agent,

This letter is to inform you that your property at **933 37TH ST RICHMOND**, **CA 94805 failed** the Housing Quality Standards (HQS) inspection on 05/02/2023.

A re-inspection has been scheduled for 06/27/2023 between 01:00PM and 04:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
5.4	Secondary Rooms/Other Potential Hazardous Features	O
	laundry room ceiling has excessive black discoloration, repair/remove	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is missing. All units must have at least one operable smoke	
	detector in each bedroom and in a common area on each level. all	
	bedrooms	
3.12	Bathroom/Tub or Shower	O
	resurface tub, peeling paint	
3.7	Bathroom/Wall Condition	О
	wall peeling paint,repair	
3.5	Bathroom/Window Condition	O
	window sill has evidence of water damage,repair	
4.5	Other Rooms/Window Condition	O
	master bedroom window sill damaged.repair	
4.7	Other Rooms/Wall Condition	O
	master bedroom walls have black discoloration, repair/remove	
8.7	General Health and Safety/Other Interior Hazards	O
	install common area co and smoke detector	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Jaswinder S & Satnam K Bajwa 1885 Deer Spring Ct Fairfield, CA 94534 Property: 3618 MCBRYDE AVE RICHMOND, CA 94805-

PropID:

Client ID: 17410

Dear Owner/Agent,

This letter is to inform you that your property at **3618 MCBRYDE AVE RICHMOND**, CA **94805 failed** the Housing Quality Standards (HQS) inspection on 05/02/2023.

A re-inspection has been scheduled for 06/27/2023 between 01:00PM and 04:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.4	Other Rooms/Security	O
	1. no access keyed door locked	
	2. remove keyed door lock	
7.4	Heating and Plumbing/Water Heater	O
	The water heater must be equipped with both a temperature-pressure relief	
	valve and discharge line down to approximately 4 - 6 from the floor.	
4.6	Other Rooms/Celing Condition	O
	remove excessive black discoloration	
6.2	Building Exterior/Condition of Stairs, Rails, and Porches	O
	rear deck has loose steps and rotten wood, repair/replace	
7.3	Heating and Plumbing/Ventilation and Adequacy of Cooling	O
	install/repair missing,damaged ventilation screens around base of house	
3.12	Bathroom/Tub or Shower	O
	tub diverter not working as designed, repair	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is missing. All units must have at least one operable smoke	
	detector in each bedroom and in a common area on each level.	
8.7	General Health and Safety/Other Interior Hazards	O
	install common area smoke and co detector	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Martha S Ugaz 6332 Jerilynn Ave Richmond, CA 94806 Property: 729 MC LAUGHLIN ST RICHMOND, CA 94805-1401-

PropID:

Client ID: 5856

Dear Owner/Agent,

This letter is to inform you that your property at **729 MC LAUGHLIN ST RICHMOND, CA 94805-1401 failed** the Housing Quality Standards (HQS) inspection on 05/02/2023.

A re-inspection has been scheduled for 06/27/2023 between 01:00PM and 04:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.7	General Health and Safety/Other Interior Hazards	O
	common area co/smoke detector inop,repair/replace	
3.12	Bathroom/Tub or Shower	O
	1. recaulk around tub	
	2. resurface tub,rusting	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is missing/inop. All units must have at least one operable	
	smoke detector in each bedroom and in a common area on each level.	
8.10	General Health and Safety/Site and Neighborhood Conditions	O
	cut and remove all overgrown vegetation on property	
6.2	Building Exterior/Condition of Stairs, Rails, and Porches	O
	install gutter downspout rear of unit	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Josephine & Rofrigo Tre Villa 51 Majestic Ave San Francisco, CA 94112 Property: 774 36TH ST Apt A RICHMOND, CA 94805-1710-

PropID:

Client ID: 19305

Dear Owner/Agent,

This letter is to inform you that your property at 774 36TH ST Apt A RICHMOND, CA 94805-1710 failed the Housing Quality Standards (HQS) inspection on 05/02/2023.

A re-inspection has been scheduled for 06/27/2023 between 01:00PM and 04:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.7	Bathroom/Wall Condition	O
	repair hole behind sink	
3.12	Bathroom/Tub or Shower	O
	tub diverter not working as designed repair	
4.5	Other Rooms/Window Condition	O
	replace tattered screens on bedroom windows	
6.3	Building Exterior/Condition of Roof and Gutters	O
	clean gutters	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Josephine & Rofrigo Tre Villa 51 Majestic Ave San Francisco, CA 94112 Property: 774 36TH ST Apt B RICHMOND, CA 94805-1710-

PropID:

Client ID: 19305

Dear Owner/Agent,

This letter is to inform you that your property at **774 36TH ST Apt B RICHMOND**, **CA 94805-1710 failed** the Housing Quality Standards (HQS) inspection on 05/02/2023.

A re-inspection has been scheduled for 06/27/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

6.3 Building Exterior/Condition of Roof and Gutters

clean gutters

Tenant/Owner

O

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Simon Tang 1115 Visitacion Ave San Francisco, CA 94134-2751 Property: 731 WILSON AVE RICHMOND, CA 94805-1868-

PropID:

Client ID: 9549

Dear Owner/Agent,

This letter is to inform you that your property at **731 WILSON AVE RICHMOND, CA 94805-1868 failed** the Housing Quality Standards (HQS) inspection on 05/02/2023.

A re-inspection has been scheduled for 06/27/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.12	Kitchen/Sink	O
	recaulk around sink	
2.7	Kitchen/Wall Condition	O
	cover hole around disposal switch	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Maribel Gonzalez 1749 Marin Ave Berkeley, CA 94707 Property: 768 WILSON AVE RICHMOND, CA 94805-1877-

PropID:

Client ID: 18117

Dear Owner/Agent,

This letter is to inform you that your property at **768 WILSON AVE RICHMOND**, **CA 94805-1877 failed** the Housing Quality Standards (HQS) inspection on 05/02/2023.

A re-inspection has been scheduled for 06/27/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
6.2	Building Exterior/Condition of Stairs, Rails, and Porches	O
	install handrail on front porch	
8.7	General Health and Safety/Other Interior Hazards	O
	install common area co/smoke detector on 1st level of home and basement	
1.6	Living Room/Ceiling Condition	O
	repair, peeling paint	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Range Properties Llc Iron Arthur Sainio 157 Austin Ln Alamo, CA 94507 Property: 600 HUMBOLDT ST RICHMOND, CA 94805-1916-

PropID:

Client ID: 18426

Dear Owner/Agent,

This letter is to inform you that your property at **600 HUMBOLDT ST RICHMOND**, CA **94805-1916 failed** the Housing Quality Standards (HQS) inspection on 05/02/2023.

A re-inspection has been scheduled for 06/27/2023 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.3	Bathroom/Electrical Hazards	O
	gfi will not test/reset repair/replace x2	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is missing. All units must have at least one operable smoke	
	detector in each bedroom and in a common area on each level.	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Anna & J Investment Inc 611 40Th St Richmond, CA 94805 Property: 12437 SAN PABLO AVE Apt D RICHMOND, CA 94805-1938-

PropID:

Client ID: 17801

Dear Owner/Agent,

This letter is to inform you that your property at 12437 SAN PABLO AVE Apt D RICHMOND, CA 94805-1938 failed the Housing Quality Standards (HQS) inspection on 05/02/2023.

A re-inspection has been scheduled for 06/27/2023 between 11:00AM and 02:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.10	Kitchen/Stove or Range with Oven	O
	all burners must self-ignite,repair	
3.6	Bathroom/Ceiling Condition	O
	excessive black discoloration, remove	
3.7	Bathroom/Wall Condition	O
	1.excessive black discoloration	
	2. wall water damaged between toielt and tub	
3.12	Bathroom/Tub or Shower	O
	shower enclosure tile broken, replace	
3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
	Bath Toilet not secured properly to floor.	
3.3	Bathroom/Electrical Hazards	O
	fan cover missing,install	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,