

#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1836 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1836 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

A re-inspection has been scheduled for 08/28/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.6 General Health and Safety/Interior Stairs and Common Halls hallway smoke detector missing

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1837 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1837 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	clear items from around water heater	
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	hallway light not working - repair/replace	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1838 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1838 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.7	General Health and Safety/Other Interior Hazards	O
	living room smoke detector not working properly - repair/replace	
7.2	Heating and Plumbing/Safety of Heating Equipment	O
	clear items around water heater	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1911 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1911 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

## Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Tenant/Owner 7.2 Heating and Plumbing/Safety of Heating Equipment clear egress blocking water heater door clear items around water heater

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806

Property:
2601 HILLTOP DR Apt 1912
RICHMOND, CA 94806-5783

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1912 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.13	Kitchen/Space for Storage, Prep and Serving	O
	cabinet door missing - repair/replace	
2.10	Kitchen/Stove or Range with Oven	O
	back rear burners not working properly - repair/replace	
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	clear items from around water heater door	
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	hallway smoke detector missing	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1914 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1914 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 1.5 Living Room/Window Condition living room window broken - repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1915 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1915 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 7.1 Heating and Plumbing/Adequacy of Heating Equipment thermostat not working

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1916 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1916 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	hallway smoke detector missing	
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	clear items blocking water heater door unable to access	
	clear items around water heater	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1917 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1917 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.10 Kitchen/Stove or Range with Oven left rear burner not working properly - repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1918 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1918 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.10	Kitchen/Stove or Range with Oven	O
	right rear burner not working properly -repair/replace	
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	clear items blocking water heater door	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1921 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1921 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

## Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.7 General Health and Safety/Other Interior Hazards unit must be able to walk through freely and able to access all areas inside unit to conduct inspection - clear/remove/clear egress throughout unit

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1922 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1922 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
7.1	Heating and Plumbing/Adequacy of Heating Equipment	O
	thermostat not working	
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	clear items around water heater	
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	hallway smoke detector missing	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1923 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1923 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

A re-inspection has been scheduled for 08/28/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 4.10 Other Rooms/Smoke Detectors bedroom smoke detector not working properly very very low repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1924 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1924 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 7.2 Heating and Plumbing/Safety of Heating Equipment clear items from blocking access to water heater door

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1926 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1926 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	clear items from around water heater	
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	hallway smoke detector missing	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1927 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1927 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
1.8	Living Room/Floor Condition	O
	carpeting throughout entire unit very badly worn - repair/replace	
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	clear items from around water heater	
4.10	Other Rooms/Smoke Detectors	O
	bedroom smoke detector missing/inop - repair/replace	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806

Property:
2601 HILLTOP DR Apt 1928
RICHMOND, CA 94806-5783

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1928 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.6	Bathroom/Ceiling Condition	O
	large amount of discoloration on ceiling - remove/repair	
4.10	Other Rooms/Smoke Detectors	O
	bedroom smoke detector missing	
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	clear items from blocking access to water heater door	
1.8	Living Room/Floor Condition	O
	carpeting throughout entire unit very badly worn - repair/replace	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1931 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1931 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/28/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 7.2 Heating and Plumbing/Safety of Heating Equipment Clear items from around water heater

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1932 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1932 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/29/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.12	Bathroom/Tub or Shower	T
	tub very badly discolored - clean/remove	
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	hallway smoke detector missing	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1933 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1933 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/29/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
1.4	Living Room/Security	T
	clear egress to access patio door	
7.2	Heating and Plumbing/Safety of Heating Equipment	T
	clear items from around water heater	
8.7	General Health and Safety/Other Interior Hazards	O
	hallway smoke detector missing	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1935 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1935 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/29/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.10 Kitchen/Stove or Range with Oven left and right rear burners not working properly - repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1936 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1936 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/29/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

## Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.12 Kitchen/Sink water pressure very low -repair/replace garbage disposal inop -repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 1937 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 1937 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/29/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.6 General Health and Safety/Interior Stairs and Common Halls hallway smoke detector missing

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 835 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 835 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.5	Other Rooms/Window Condition	T
	Move furniture blocking clear access to window (fire exit)	
7.4	Heating and Plumbing/Water Heater	T
	Move items stored in hot water heater closet	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 836 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 836 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.4 General Health and Safety/Garbage and Debris T Move appliances from patio

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 911 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 911 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

<u>Area</u>	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.5	Other Rooms/Window Condition	O
	Patio screen missing, replace	
8.4	General Health and Safety/Garbage and Debris	T
	Tenant to clear items stored in hot water heater closet	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 912 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 912 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
	Toilet Tank Lid Missing or needs replacement. Tank lid damaged	
8.4	General Health and Safety/Garbage and Debris	T
	Tenant to move items stored in hot water heater closet	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 2601 HILLTOP DR Apt 913 RICHMOND, CA 94806-5783-

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 913 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	Common area smoke detector/carbon monoxide detector inoperable,	
	repair or replace	
3.3	Bathroom/Electrical Hazards	O
	Ceiling light inoperable, repair	
8.4	General Health and Safety/Garbage and Debris	T
	Tenant to declutter unit	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 916 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 916 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/26/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 7.4 Heating and Plumbing/Water Heater Tenant to move items stored in hot water heater closet

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 917 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 917 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/27/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
7.1	Heating and Plumbing/Adequacy of Heating Equipment	O
	Heater inoperable, thermostat has no display. repair	
2.11	Kitchen/Refrigerator	O
	Light inoperable, repair	
8.10	General Health and Safety/Site and Neighborhood Conditions	O
	Remove weeds in patio yard	
4.5	Other Rooms/Window Condition	T
	Tenant to remove wooden frame mounted in window frame preventing	
	access to window. Window must be able to open as it is only fire exit in	
	bedroom.	



#### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 918 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 918 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/27/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 3.11 Bathroom/Fixed Wash Basin or Lavatory in Unit Slow drain, repair (RIGHT BATHROOM)

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 921 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 921 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

#### A re-inspection has been scheduled for 08/27/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 2.10 Kitchen/Stove or Range with Oven Right rear burner inoperable, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



## **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806

2601 HILLTOP DR Apt 922 RICHMOND, CA 94806-5783-

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 922 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

# A re-inspection has been scheduled for 08/27/2025 between 09:00AM and 12:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.1	General Health and Safety/Access to Unit	O
	Front exterior light inoperable, repair	
2.12	Kitchen/Sink	O
	Dishwasher inoperable, repair	
2.11	Kitchen/Refrigerator	O
	Refrigerator makes loud grinding noise, repair	
7.4	Heating and Plumbing/Water Heater	T
	Clear items stored in hot water heater closet	



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



## FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 2601 HILLTOP DR Apt 923 RICHMOND, CA 94806-5783-

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 923 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

## A re-inspection has been scheduled for 08/27/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.10	Kitchen/Stove or Range with Oven	O
	Right rear burner inoperable, repair	
3.3	Bathroom/Electrical Hazards	O
	Light switch cover damaged, replace	
8.4	General Health and Safety/Garbage and Debris	T
	Tenant to declutter unit	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



## **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 924 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 924 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

# A re-inspection has been scheduled for 08/27/2025 between 09:00AM and 12:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is inoperable or missing. All units must have at least one	
	operable smoke detector on each level. The smoke detector must be	
	placed according to package insturctions.	
2.12	Kitchen/Sink	O
	1 - Garbage disposal inoperable, repair	
	2 - Dishwasher drains through air gap, repair as drain must go through	
	garbage disposal	
8.1	General Health and Safety/Access to Unit	O
	Patio light inoperable, repair	



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



## **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 2601 HILLTOP DR Apt 925 RICHMOND, CA 94806-5783-

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 925 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

# A re-inspection has been scheduled for 08/27/2025 between 09:00AM and 12:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.4	General Health and Safety/Garbage and Debris	T
	Remove appliance being stored on patio	
7.4	Heating and Plumbing/Water Heater	T
	Remove items being stored in hot water heater closet	
3.12	Bathroom/Tub or Shower	O
	Shower head leaking, repair	
	(Left bathroom)	
2.10	Kitchen/Stove or Range with Oven	O
	Microwave/range hood handle damaged, repair or replace	



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



## **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806

	•	
2601	HILLT	OP DR Apt 926
RIC	HMONI	D. CA 94806-5783

PropID:

Property:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 926 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

# A re-inspection has been scheduled for 08/27/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.12	Bathroom/Tub or Shower	O
	Secure baseboard trim located in front of tub	
2.3	Kitchen/Electrical Hazards	O
	Secure outlet leading into kitchen	
2.11	Kitchen/Refrigerator	O
	Refrigerator and freezer are not cold enough to keep food from spoiling	
	over a reasonable period of time.	

Tenant to remove excessive amount of items in freezer



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



## FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 927 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 927 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

## A re-inspection has been scheduled for 08/27/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.12	Kitchen/Sink	O
	Dishwasher drains through air gap, repair	
8.4	General Health and Safety/Garbage and Debris	T
	Tenant to clear items stored in hot water heater closet	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 928 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 928 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

## A re-inspection has been scheduled for 08/27/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 8.4 General Health and Safety/Garbage and Debris Remove old toilet stored in hot water heater closet

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



## **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 932 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 932 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

# A re-inspection has been scheduled for 08/27/2025 between 11:00AM and 02:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
7.1	Heating and Plumbing/Adequacy of Heating Equipment	O
	HEATER INOPRABLE AS THERMOSTAT IS MISSING, INSTALL	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is inoperable or missing. All units must have at least one	
	operable smoke detector on each level. The smoke detector must be	
	placed according to package insturctions.	
4.5	Other Rooms/Window Condition	O
	Units will be required to have screens on one exterior window per room, if	
	the window is openable. The screens must be removable for egress in case	
	of an emergency.	
2.10	Kitchen/Stove or Range with Oven	O
	Left oven knobs missing, replace	



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 933 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 933 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

## A re-inspection has been scheduled for 08/27/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 3.7 Bathroom/Wall Condition Clean discoloration on walls by tub

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



## **FAILED INSPECTION NOTICE**

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 935 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 935 RICHMOND, CA 94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

# A re-inspection has been scheduled for 08/27/2025 between 11:00AM and 02:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is inoperable or missing. All units must have at least one	
	operable smoke detector on each level. The smoke detector must be	
	placed according to package insturctions.	
8.6	General Health and Safety/Interior Stairs and Common Halls	O
	Right side common area smoke detector/carbon monoxide detector	
	inoperable, replace	
8.4	General Health and Safety/Garbage and Debris	T
	Tenant to declutter unit	
2.10	Kitchen/Stove or Range with Oven	O
	Rear burners inoperable, repair	



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



## FAILED INSPECTION NOTICE

Richmond Essex Lp TRENNILLE A BRASS 2601 Hilltop Drive, Leasing Office Richmond, CA 94806 Property: 2601 HILLTOP DR Apt 937 RICHMOND, CA 94806-5783-

PropID:

Client ID: 7274

Dear Owner/Agent,

This letter is to inform you that your property at **2601 HILLTOP DR Apt 937 RICHMOND**, CA **94806-5783 failed** the Housing Quality Standards (HQS) inspection on 06/13/2025.

## A re-inspection has been scheduled for 08/27/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.10	Kitchen/Stove or Range with Oven	O
	Right rear burner inoperable, repair	
8.4	General Health and Safety/Garbage and Debris	T
	Tenant to clear items stored in hot water heater closet	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,