

### FAILED INSPECTION NOTICE

Patrick P & Nancy A Cheung 5720 Jefferson Ave Richmond, CA 94804-4865 Property: 3307 HUMPHREY AVE RICHMOND, CA 94804-1187-

PropID:

Client ID: 10009

Dear Owner/Agent,

This letter is to inform you that your property at **3307 HUMPHREY AVE RICHMOND, CA 94804-1187 failed** the Housing Quality Standards (HQS) inspection on 08/11/2022.

A re-inspection has been scheduled for 09/13/2022 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS Tenant/Owner

6.2 Building Exterior/Condition of Stairs, Rails, and Porches rear deck has loose deteriorating boards and nails pulling up, repair/replace rear deck

О

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### **FAILED INSPECTION NOTICE**

Lian Trang 1126 Brunswick St Daly City, CA 94014-1153 Property:
2519 BARRETT AVE
RICHMOND, CA 94804-1641-

PropID:

Client ID: 9699

Dear Owner/Agent,

This letter is to inform you that your property at **2519 BARRETT AVE RICHMOND, CA 94804-1641 failed** the Housing Quality Standards (HQS) inspection on 08/11/2022.

### A re-inspection has been scheduled for 09/13/2022 between 01:00PM and 04:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.7	General Health and Safety/Other Interior Hazards	O
	Unit must have one carbon monoxide detector per level. and one common	
	area smoke detector per floor, install both on all 4 levels of home	
3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
	basement toilet running constantly,repair	
3.6	Bathroom/Ceiling Condition	O
	remove black organic substances	
2.6	Kitchen/Ceiling Condition	O
	evidence of leak, repair	
5.4	Secondary Rooms/Other Potential Hazardous Features	O
	basement ceiling has evidence of water damage, repair	
2.11	Kitchen/Refrigerator	O
	Replace missing Refrig handle.	
6.2	Building Exterior/Condition of Stairs, Rails, and Porches	O
	masonry on steps and walkway in front of house has loose and broken	
	bricks, safty and trip haz, repair	



### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### **FAILED INSPECTION NOTICE**

Castillo Partners Llc 3053 Fillmore St #261 San Francisco, CA 94123-4009 Property: 3110 FLORIDA AVE RICHMOND, CA 94804-3110-

PropID:

Client ID: 8395

Dear Owner/Agent,

This letter is to inform you that your property at **3110 FLORIDA AVE RICHMOND**, **CA 94804-3110 failed** the Housing Quality Standards (HQS) inspection on 08/11/2022.

# A re-inspection has been scheduled for 09/13/2022 between 01:00PM and 04:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
6.3	Building Exterior/Condition of Roof and Gutters	O
	Ext. = Gutters Damaged. downspout disconnected at front of house, repair	
7.1	Heating and Plumbing/Adequacy of Heating Equipment	O
	Heat Not Working Properly.	
2.10	Kitchen/Stove or Range with Oven	O
	all burners must be in working condition and self-ignite, repair	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is missing. All units must have at least one operable smoke	
	detector in each bedroom and in a common area on each level.	
6.4	Building Exterior/Condition of Exterior Surfaces	O
	exterior light outside kitchen inop, repair	
7.4	Heating and Plumbing/Water Heater	O
	install discharge pipe, within 6" of floor.	



### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### **FAILED INSPECTION NOTICE**

Wanda H Mulcahy 2222 Parker St Berkeley, CA 94704-2712 Property: 431 S 36TH ST RICHMOND, CA 94804-3231-

PropID:

Client ID: 8367

Dear Owner/Agent,

This letter is to inform you that your property at **431 S 36TH ST RICHMOND**, CA **94804-3231 failed** the Housing Quality Standards (HQS) inspection on 08/11/2022.

# A re-inspection has been scheduled for 09/13/2022 between 11:00AM and 02:00PM.



# FAILED INSPECTION NOTICE

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.10	Kitchen/Stove or Range with Oven	O
	1.all burners must self ignite	
	2. oven control panel falling into stove, repair	
8.7	General Health and Safety/Other Interior Hazards	O
	all smoke detectors inop, each unit must have a common area smoke	
	detector on each level and a smoke detector in each bedroom	
3.13	Bathroom/Ventilation	O
	Bath Ventilation Fan Not Functioning/Damaged & Needs Repair. rear bath	
3.4	Bathroom/Security	O
	door broken, repair/replace middle bathroom	
3.3	Bathroom/Electrical Hazards	O
	light fixture inop middle bathroom	
3.11	Bathroom/Fixed Wash Basin or Lavatory in Unit	O
	Bath Sink vanity top Cracked/Needs Repair/Replacement.	
	middle bath	
3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
	Bath Toilet Clogged/Leaking/ or not working properly.	
	front bath	
3.5	Bathroom/Window Condition	O
	Window must be openable and remain open without props.	
2.12	Kitchen/Sink	O
	sink faucet loose, repair	



### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### **FAILED INSPECTION NOTICE**

	Property:
Qia Xiang Zhou	1529 POTRERO AVE Apt A
950 Taraval St	RICHMOND, CA 94804-3751-
San Francisco, CA 94116	RICHWOND, 2117 1001 3731

PropID:

Client ID: 2499

Dear Owner/Agent,

This letter is to inform you that your property at **1529 POTRERO AVE Apt A RICHMOND, CA 94804-3751 failed** the Housing Quality Standards (HQS) inspection on 08/11/2022.

### A re-inspection has been scheduled for 09/13/2022 between 01:00PM and 04:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.12	Bathroom/Tub or Shower	О
	tub faucet constantly running, handel broken	
6.2	Building Exterior/Condition of Stairs, Rails, and Porches	O
	rear porch staircase has loose and deteriorating steps,and railings replace	
	boards	
6.3	Building Exterior/Condition of Roof and Gutters	O
	Roof or gutter condition indicates the potential of structural collapse. rear	
	staircase porch overhang. replace	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is missing. All units must have at least one operable smoke	
	detector in each bedroom and in a common area on each level.	



### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### **FAILED INSPECTION NOTICE**

Castillo Partners Llc 3053 Fillmore St #261 San Francisco, CA 94123-4009 Property: 833 S 49TH ST RICHMOND, CA 94804-4428-

PropID:

Client ID: 8395

Dear Owner/Agent,

This letter is to inform you that your property at **833 S 49TH ST RICHMOND, CA 94804-4428 failed** the Housing Quality Standards (HQS) inspection on 08/11/2022.

### A re-inspection has been scheduled for 09/13/2022 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 3.7 Bathroom/Wall Condition wall next to tub has water damage, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### **FAILED INSPECTION NOTICE**

Pai-Yau & Hsin-Yi Tsai 2815 Las Gallinas Ave San Rafael, CA 94903-1428 Property: 1551 MARIPOSA ST RICHMOND, CA 94804-5015-

PropID:

Client ID: 1146

Dear Owner/Agent,

This letter is to inform you that your property at 1551 MARIPOSA ST RICHMOND, CA 94804-5015 failed the Housing Quality Standards (HQS) inspection on 08/11/2022.

# A re-inspection has been scheduled for 09/13/2022 between 11:00AM and 02:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.3	Kitchen/Electrical Hazards	O
	gfi will not test/reset, right of sink. repalce	
5.2	Secondary Rooms/Security	O
	garage exit door to yard has large gaps around, repair	
5.4	Secondary Rooms/Other Potential Hazardous Features	O
	step leading down to garage from kitchen is loose, safty haz, repair	
5.3	Secondary Rooms/Electrical Hazards	O
	light fixture in garage missing bulb, repair	



### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### **FAILED INSPECTION NOTICE**

Andrew Chi 1553 Merced St Richmond, CA 94709-0292 Property: 622 34TH ST RICHMOND, CA 94805-1752-

PropID:

Client ID: 9069

Dear Owner/Agent,

This letter is to inform you that your property at **622 34TH ST RICHMOND**, CA **94805-1752 failed** the Housing Quality Standards (HQS) inspection on 08/11/2022.

### A re-inspection has been scheduled for 09/15/2022 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.6	Kitchen/Ceiling Condition	O
	repair cracks on ceiling	
3.3	Bathroom/Electrical Hazards	O
	install GFCI outlet	
2.12	Kitchen/Sink	O
	Faucet damaged/leakage. loose, repair	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### **FAILED INSPECTION NOTICE**

James R & Patricia L Nunn 1213 Upper Happy Valley Rd Lafayette, CA 94549-2724 Property: 414 DIMM ST RICHMOND, CA 94805-2422-

PropID:

Client ID: 1702

Dear Owner/Agent,

This letter is to inform you that your property at **414 DIMM ST RICHMOND**, CA **94805-2422 failed** the Housing Quality Standards (HQS) inspection on 08/11/2022.

### A re-inspection has been scheduled for 09/15/2022 between 01:00PM and 04:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
8.3	General Health and Safety/Evidence of Infestation	O
	Exterminate for rats, mice. evidence of infestation	
8.7	General Health and Safety/Other Interior Hazards	O
	install common area smoke detector on third level of home	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is missing. All units must have at least one operable smoke	
	detector in each bedroom and in a common area on each level.	



### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### **FAILED INSPECTION NOTICE**

James E & Vanessa Szumlas 4980 Appian Way #205 El Sobrante, CA 94803 Property: 3150 BIRMINGHAM DR RICHMOND, CA 94806-2635-

PropID:

Client ID: 1775

Dear Owner/Agent,

This letter is to inform you that your property at **3150 BIRMINGHAM DR RICHMOND**, CA **94806-2635 failed** the Housing Quality Standards (HQS) inspection on 08/11/2022.

# A re-inspection has been scheduled for 09/15/2022 between 01:00PM and 04:00PM.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
7.4	Heating and Plumbing/Water Heater	O
	No Access To Wtr. Htr, unable to inspect. Owner must provide access at	
	next inspection.	
8.7	General Health and Safety/Other Interior Hazards	O
	1. Unit must have one working carbon monoxide detector per level.	
	upstairs co inop	
	2. install common area co and smoke detectors downstairs	
4.4	Other Rooms/Security	O
	Remove keyed lock from interior door.	



### FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

James E & Vanessa Szumlas 4980 Appian Way #205 El Sobrante, CA 94803 Property: 3152 BIRMINGHAM DR RICHMOND, CA 94806-2635-

PropID:

Client ID: 1775

Dear Owner/Agent,

This letter is to inform you that your property at 3152 BIRMINGHAM DR RICHMOND, CA 94806-2635 failed the Housing Quality Standards (HQS) inspection on 08/11/2022.

### A re-inspection has been scheduled for 09/15/2022 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 7.4 Heating and Plumbing/Water Heater No Access To Wtr. Htr, unable to inspect. Owner must provide access at next inspection.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,