

# FAILED INSPECTION NOTICE

Tracy A Lamar 265 Glenview Cir Vallejo, CA 94591 Property: 464 3RD ST RICHMOND, CA 94801-2627-

PropID:

Client ID: 8307

Dear Owner/Agent,

This letter is to inform you that your property at **464 3RD ST RICHMOND**, **CA 94801-2627 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

A re-inspection has been scheduled for 10/09/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.



### FAILED INSPECTION NOTICE

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.4 Other Rooms/Security
  - Remove keyed lock from interior door.
- 4.10 Other Rooms/Smoke Detectors
  - Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions.
- 4.5 Other Rooms/Window Condition
  - Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.

#### TENANT TO MOVE FURNITURE BLOCKING WINDOW

4.3 Other Rooms/Elecrtical Hazards

Three prong outlet not testing as designed, must be grounded or replaced with a GFCI.

Outlet on right wall damaged, replace

- 8.7 General Health and Safety/Other Interior Hazards
  Carbon monoxide detector inoperable, repair or replace
- 3.13 Bathroom/Ventilation
  - Secure vent fan to ceiling
- 2.10 Kitchen/Stove or Range with Oven
  - Range hood severely rusted with peeling paint, replace
- 8.1 General Health and Safety/Access to Unit
  - Secure knobs on rear security door
- 8.3 General Health and Safety/Evidence of Infestation
  - Exterminate for roaches.
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### **FAILED INSPECTION NOTICE**

Tracy A Lamar 265 Glenview Cir Vallejo, CA 94591 Property:
466 3RD ST
RICHMOND, CA 94801-2627-

PropID:

Client ID: 8307

Dear Owner/Agent,

This letter is to inform you that your property at **466 3RD ST RICHMOND**, CA **94801-2627 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

A re-inspection has been scheduled for 10/09/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.



### FAILED INSPECTION NOTICE

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

1.3 Living Room/Electrical Hazards
Light fixture inoperable, repair

Outlet on right wall has no power, unable to test. Repair

4.10 Other Rooms/Smoke Detectors

Smoke detector is missing. All units must have at least one operable smoke detector in each bedroom and in a common area on each level.

4.4 Other Rooms/Security

Remove keyed lock from interior door.

3.12 Bathroom/Tub or Shower

Shower head leaking in rear, repair

7.1 Heating and Plumbing/Adequacy of Heating Equipment

Heater inoperable, repair

2.10 Kitchen/Stove or Range with Oven

Burner knobs missing, replace for inspection

Clean grease splatter on range hod

Range hood light inoperable, replace bulb

2.11 Kitchen/Refrigerator

Refrigerator/Freezer does not maintain temperature.

2.12 Kitchen/Sink

Secure kitchen faucet to sink

2.3 Kitchen/Electrical Hazards

Prong broken in GFCI receptacle right of sink, repair or replace



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Tracy A Lamar 265 Glenview Cir Vallejo, CA 94591 Property: 468 3RD ST RICHMOND, CA 94801-2627-

PropID:

Client ID: 8307

Dear Owner/Agent,

This letter is to inform you that your property at **468 3RD ST RICHMOND**, **CA 94801-2627 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

### A re-inspection has been scheduled for 10/09/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

8.7 General Health and Safety/Other Interior Hazards
Carbon monoxide detector inoperable, repair or replace

Common area smoke detector missing, replace

- 4.10 Other Rooms/Smoke Detectors
  - Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions.
- 4.3 Other Rooms/Elecrtical Hazards
  - Outlets have open grounds, repair or replace with two prong receptacle or GFCI
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair
- 2.10 Kitchen/Stove or Range with Oven
  - Range hood vent screen missing, replace

Rear burners inoperable, repair

- 5.2 Secondary Rooms/Security
  - Remove keyed entry lock on laundry room door
- 2.11 Kitchen/Refrigerator

Refrigerator/Freezer does not maintain temperature.



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### **FAILED INSPECTION NOTICE**

Tracy A Lamar 265 Glenview Cir Vallejo, CA 94591 Property: 300 BARRETT AVE RICHMOND, CA 94801-2627-

PropID:

Client ID: 8307

Dear Owner/Agent,

This letter is to inform you that your property at **300 BARRETT AVE RICHMOND**, **CA 94801-2627 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

A re-inspection has been scheduled for 10/09/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.



#### **FAILED INSPECTION NOTICE**

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.4 Other Rooms/Security
  - Remove keyed lock from interior door.
- 1.3 Living Room/Electrical Hazards
  - Three prong outlet not testing as designed, must be grounded, replaced with a two-prong outlet or replaced with a GFCI.
- 4.3 Other Rooms/Elecrtical Hazards
  - Light switch coverplate damaged, replace
- 4.10 Other Rooms/Smoke Detectors
  - Smoke detector is missing. All units must have at least one operable smoke detector in each bedroom and in a common area on each level.
- 3.4 Bathroom/Security
  - Remove keyed entry lock on bathroom door
- 3.5 Bathroom/Window Condition
  - Window must be openable and remain open without props.
- 4.5 Other Rooms/Window Condition
  - Move bunk bed blocking window (fire exit)
- 8.1 General Health and Safety/Access to Unit
  - Clear items blocking clear access to rear door
- 8.7 General Health and Safety/Other Interior Hazards
  - Carbon monoxide detector inoperable, repair or replace
- 2.10 Kitchen/Stove or Range with Oven
  - Oven door front facing missing/damaged, repair or replace
  - Front/Right burner inoperable, repair
  - Range hood vent screen missing, replace
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment
  - Heater inoperable, repair
- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit
  - Toilet inoperable, will not flush. Repair



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Julie Lin 108 Santa Paula Ct San Pablo, CA 94806-5038 Property: 214 BARRETT AVE Apt 2 RICHMOND, CA 94801-2685-

PropID:

Client ID: 12273

Dear Owner/Agent,

This letter is to inform you that your property at **214 BARRETT AVE Apt 2 RICHMOND, CA 94801-2685 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

### A re-inspection has been scheduled for 10/09/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

8.6 General Health and Safety/Interior Stairs and Common Halls Carbon monoxide detector inoperable, repair or replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Austin Linnane 364 Wildwood Ave Piedmont, CA 94611-3849 Property: 620 8TH ST RICHMOND, CA 94801-2714-

PropID:

Client ID: 8769

Dear Owner/Agent,

This letter is to inform you that your property at **620 8TH ST RICHMOND**, CA **94801-2714 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

### A re-inspection has been scheduled for 10/09/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 2.10 Kitchen/Stove or Range with Oven Burners not self lighting, repair
- 8.1 General Health and Safety/Access to Unit Front security door damaged at bottom, repair
- 1.5 Living Room/Window Condition
  Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.
- 4.4 Other Rooms/Security
  Remove keyed lock from interior door.
- 4.5 Other Rooms/Window Condition Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, thermostat has no display
- 2.12 Kitchen/Sink
  Dishwasher inoperable, repair

emergency.



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

Tracy A Lamar 265 Glenview Cir Vallejo, CA 94591 Property: 1621 ROOSEVELT AVE RICHMOND, CA 94801-2809-

PropID:

Client ID: 8307

Dear Owner/Agent,

This letter is to inform you that your property at **1621 ROOSEVELT AVE RICHMOND**, **CA 94801-2809 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

### A re-inspection has been scheduled for 10/09/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.5 Other Rooms/Window Condition Window lock damaged, repair
- 4.8 Other Rooms/Floor Condition
  Install transition strip at entry of room
- 4.4 Other Rooms/Security
  Secure door knob to door
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heaters inoperable, repair
- 5.2 Secondary Rooms/Security
  Remove keyed entry lock on garage door



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

Juan Lozano 967 Mitchell Way El Sobrante, CA 94803 Property: 1920 NEVIN AVE Apt A RICHMOND, CA 94801-3245-

PropID:

Client ID: 8467

Dear Owner/Agent,

This letter is to inform you that your property at 1920 NEVIN AVE Apt A RICHMOND, CA 94801-3245 failed the Housing Quality Standards (HQS) inspection on 08/11/2025.

### A re-inspection has been scheduled for 10/09/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 2.10 Kitchen/Stove or Range with Oven Burners not self lighting, repair
- 6.2 Building Exterior/Condition of Stairs, Rails, and Porches

  Complete repairs to rear stairs, unable to inspect as scaffold in the way.
- 8.4 General Health and Safety/Garbage and Debris
  Remove appliances from yard, must be stored inside of unit or removed
- 8.10 General Health and Safety/Site and Neighborhood Conditions Secure building supplies in rear yard



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

Juan Lozano 967 Mitchell Way El Sobrante, CA 94803 Property: 1920 NEVIN AVE RICHMOND, CA 94801-3245-

PropID:

Client ID: 8467

Dear Owner/Agent,

This letter is to inform you that your property at **1920 NEVIN AVE RICHMOND**, **CA 94801-3245 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

### A re-inspection has been scheduled for 10/09/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 3.3 Bathroom/Electrical Hazards
  GFCI receptacle inoperable, replace
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heater inoperable, repair
- 2.10 Kitchen/Stove or Range with Oven
  Clean excessive grease splatter on stove and range hood vent screen
- 2.12 Kitchen/Sink

Garbage disposal not functioning, repair or remove

Secure faucet base to sink



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Toby Bielawski 450 Boynton Ave Berkeley, CA 94707 Property: 5616 SACRAMENTO AVE RICHMOND, CA 94804-

PropID:

Client ID: 13247

Dear Owner/Agent,

This letter is to inform you that your property at **5616 SACRAMENTO AVE RICHMOND, CA 94804 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

### A re-inspection has been scheduled for 10/09/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

5.4 Secondary Rooms/Other Potential Hazardous Features Window above laundry appliances missing screen, install

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### **FAILED INSPECTION NOTICE**

Samia A Nemetalla 1605 Elm Ave Richmond, CA 94805 Property: 3030 MARICOPA AVE RICHMOND, CA 94804-1134-

PropID:

Client ID: 9153

Dear Owner/Agent,

This letter is to inform you that your property at 3030 MARICOPA AVE RICHMOND, CA 94804-1134 failed the Housing Quality Standards (HQS) inspection on 08/11/2025.

A re-inspection has been scheduled for 10/09/2025 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.



### FAILED INSPECTION NOTICE

#### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Front heater inoperable, repair
- 6.4 Building Exterior/Condition of Exterior Surfaces

  Exterior vent screens missing left and right side of rear laundry door exit, replace
- 6.1 Building Exterior/Condition of Foundation Foundation Damaged. Large cracks in rear yard, repair
- 8.4 General Health and Safety/Garbage and Debris Remove old appliances from yard
- 8.6 General Health and Safety/Interior Stairs and Common Halls Replace missing rear common area smoke detector
- 3.11 Bathroom/Fixed Wash Basin or Lavatory in Unit Rust in sink, repair
- 3.12 Bathroom/Tub or Shower

  Clean discoloration in shower enclosure
- 3.10 Bathroom/Flush Toilet in Enclosed Room in Unit Bath Toilet not secured properly to floor.
- 3.6 Bathroom/Ceiling Condition Clean discoloration on ceiling
- 4.10 Other Rooms/Smoke Detectors

Smoke detector is inoperable or missing. All units must have at least one operable smoke detector on each level. The smoke detector must be placed according to package insturctions. Replace as it exceeds 10 year lifespan.

4.5 Other Rooms/Window Condition
Install quick release for security bars

Units will be required to have screens on one exterior window per room, if the window is openable. The screens must be removable for egress in case of an emergency.

2.12 Kitchen/SinkDishwasher inoperable, repair



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Spr Homes Llc 2300 Henry Ave Pinole, CA 94564 Property: 84 MURDOCK RICHMOND, CA 94804-1930-

PropID:

Client ID: 19526

Dear Owner/Agent,

This letter is to inform you that your property at **84 MURDOCK RICHMOND**, CA **94804-1930 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

### A re-inspection has been scheduled for 10/07/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

8.6 General Health and Safety/Interior Stairs and Common Halls replace non working smoke and CO detectors

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Juan Lozano 967 Mitchell Way El Sobrante, CA 94803 Property:
3210 OHIO AVE
RICHMOND, CA 94804-3069-

PropID:

Client ID: 8467

Dear Owner/Agent,

This letter is to inform you that your property at **3210 OHIO AVE RICHMOND**, **CA 94804-3069 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

### A re-inspection has been scheduled for 10/09/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.4 Other Rooms/Security
  Remove keyed lock from interior door.
- 3.4 Bathroom/Security
  Remove keyed entry lock from bathroom door
- 8.2 General Health and Safety/Exits

  Move items on exterior side of unit blocking window exit

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Spr Homes Llc 2300 Henry Ave Pinole, CA 94564 Property: 3003 FLORIDA AVE RICHMOND, CA 94804-3168-

PropID:

Client ID: 19526

Dear Owner/Agent,

This letter is to inform you that your property at **3003 FLORIDA AVE RICHMOND**, **CA 94804-3168 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

### A re-inspection has been scheduled for 10/07/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

4.4 Other Rooms/Security

Remove key door lock From right side bedroom door

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### **FAILED INSPECTION NOTICE**

Juan Lozano 967 Mitchell Way El Sobrante, CA 94803 Property: 3738 FLORIDA AVE RICHMOND, CA 94804-3321-

PropID:

Client ID: 8467

Dear Owner/Agent,

This letter is to inform you that your property at **3738 FLORIDA AVE RICHMOND**, CA **94804-3321 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

A re-inspection has been scheduled for 10/09/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.



### FAILED INSPECTION NOTICE

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

1.3 Living Room/Electrical Hazards

A missing and/or cracked coverplate presents an electrical hazard. Outlet right of thermostat has damaged coverplate, replace

7.2 Heating and Plumbing/Safety of Heating Equipment

Thermostat has no display, repair

8.2 General Health and Safety/Exits

Clear items in garage to allow clear path t garage door (fire exit)

3.13 Bathroom/Ventilation

Replace rusted vent screen on ceiling

3.3 Bathroom/Electrical Hazards

Replace rusted light fixture

3.10 Bathroom/Flush Toilet in Enclosed Room in Unit

Secure toilet base to floor and recaulk exterior of toilet

3.12 Bathroom/Tub or Shower

Resurface tub

Repair leak/spraying water on tub/shower control knob

3.5 Bathroom/Window Condition

Window must be openable and remain open without props.

4.3 Other Rooms/Elecrtical Hazards

A missing and/or cracked coverplate presents an electrical hazard. Outlet on left wall missing cover plate, replace

4.4 Other Rooms/Security

Remove keyed lock from interior door.

4.6 Other Rooms/Celing Condition

Repair ceiling, evidence of water damage,

repair hole on ceiling above window

7.4 Heating and Plumbing/Water Heater

Clear items in front of hot water heater closet for access

2.6 Kitchen/Ceiling Condition

Clean food splatter on kitchen ceiling



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

Juan Lozano 967 Mitchell Way El Sobrante, CA 94803 Property:
4225 FLORIDA AVE
RICHMOND, CA 94804-3433-

PropID:

Client ID: 8467

Dear Owner/Agent,

This letter is to inform you that your property at **4225 FLORIDA AVE RICHMOND**, **CA 94804-3433 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

### A re-inspection has been scheduled for 10/09/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 4.5 Other Rooms/Window Condition
  Window must be openable and remain open without props. Right window wont stay
  open without prop, repair
- 2.10 Kitchen/Stove or Range with Oven Clean grease splatter on backsplash
- 2.3 Kitchen/Electrical Hazards
  Replace missing light switch cover on outlet in kitchen leading to lower level
- 8.7 General Health and Safety/Other Interior Hazards Replace missing smoke detector in garage
- 8.4 General Health and Safety/Garbage and Debris Remove old appliances from rear yard



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Juan Lozano 967 Mitchell Way El Sobrante, CA 94803 Property:
4310 FLORIDA AVE
RICHMOND, CA 94804-3435-

PropID:

Client ID: 8467

Dear Owner/Agent,

This letter is to inform you that your property at **4310 FLORIDA AVE RICHMOND**, **CA 94804-3435 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

### A re-inspection has been scheduled for 10/09/2025 between 11:00AM and 02:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

- 8.7 General Health and Safety/Other Interior Hazards
  Replace common area Smoke detector, exceeds 10 year life span
- 7.1 Heating and Plumbing/Adequacy of Heating Equipment Heaters both inoperable, repair
- 4.10 Other Rooms/Smoke Detectors
  Replace, exceeds 10 year life span
- 4.4 Other Rooms/Security

  Remove keyed lock from interior door.
- 2.10 Kitchen/Stove or Range with Oven
  CLEAN GREASE SPLATTER ON RANGE HOOD AND RANGE HOOD
  VENT SCREEN
- 5.4 Secondary Rooms/Other Potential Hazardous Features Garage smoke detector exceeds 10 year life span, replace



# FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



### FAILED INSPECTION NOTICE

Spr Homes Llc 2300 Henry Ave Pinole, CA 94564 Property: 2926 ALTA MIRA RICHMOND, CA 94806-2758-

PropID:

Client ID: 19526

Dear Owner/Agent,

This letter is to inform you that your property at **2926 ALTA MIRA RICHMOND**, CA **94806-2758 failed** the Housing Quality Standards (HQS) inspection on 08/11/2025.

### A re-inspection has been scheduled for 10/07/2025 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

### Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,