

#### FAILED INSPECTION NOTICE

Ruben A & Mayoulee Pineda 1155 Nob Hill Ave Pinole, CA 94564-2406 Property: 866 8TH ST RICHMOND, CA 94801-

PropID:

Client ID: 8933

Dear Owner/Agent,

This letter is to inform you that your property at **866 8TH ST RICHMOND**, **CA 94801 failed** the Housing Quality Standards (HQS) inspection on 09/26/2022.

A re-inspection has been scheduled for 11/07/2022 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 4.4 Other Rooms/Security Remove key door lock – first bedroom – repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Huei-Chen Kuo
Alex Lay
1050 Rudgear Rd
Walnut Creek, CA 94596-6448

Property: 526 20TH ST RICHMOND, CA 94801-2822-

PropID:

Client ID: 1016

Dear Owner/Agent,

This letter is to inform you that your property at **526 20TH ST RICHMOND**, CA **94801-2822 failed** the Housing Quality Standards (HQS) inspection on 09/26/2022.

## A re-inspection has been scheduled for 11/07/2022 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.6	Bathroom/Ceiling Condition	O
	Ceiling bulging very badly/water damage - repair/replace/repaint	
3.10	Bathroom/Flush Toilet in Enclosed Room in Unit	O
	Toilet base loose – repair/replace	
3.11	Bathroom/Fixed Wash Basin or Lavatory in Unit	O
	Water pressure severely low - repair/replace	
4.4	Other Rooms/Security	O
	Remove key door lock from bedroom - repair/replace	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector inop – repair/replace	



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Shih Yueh Cheng 1571 Hollingsworth Mountain View, CA 94040 Property: 651 21ST ST RICHMOND, CA 94801-3369-

PropID:

Client ID: 6391

Dear Owner/Agent,

This letter is to inform you that your property at **651 21ST ST RICHMOND**, CA **94801-3369 failed** the Housing Quality Standards (HQS) inspection on 09/26/2022.

#### A re-inspection has been scheduled for 11/07/2022 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
1.4	Living Room/Security	O
	Smoke detector In operable – repair/replace	
4.10	Other Rooms/Smoke Detectors	O
	First bedroom smoke detector in operable – repair/replace	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### FAILED INSPECTION NOTICE

Fructuoso O Altamirano 55 Lobos St San Francisco, CA 94112-3019 Property: 181 19TH ST RICHMOND, CA 94801-3636-

PropID:

Client ID: 9633

Dear Owner/Agent,

This letter is to inform you that your property at **181 19TH ST RICHMOND**, CA **94801-3636 failed** the Housing Quality Standards (HQS) inspection on 09/26/2022.

#### A re-inspection has been scheduled for 11/07/2022 between 09:00AM and 12:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

# Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 4.4 Other Rooms/Security Right side bedroom – remove key door lock – repair/replace

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Jimmie George & Farna M Sewell 1995 Mohawk Dr Pleasant Hill, CA 94523-3125 Property: 3911 ROOSEVELT AVE RICHMOND, CA 94805-1845-

PropID:

Client ID: 3085

Dear Owner/Agent,

This letter is to inform you that your property at **3911 ROOSEVELT AVE RICHMOND**, **CA 94805-1845 failed** the Housing Quality Standards (HQS) inspection on 09/26/2022.

## A re-inspection has been scheduled for 11/07/2022 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
6.2	Building Exterior/Condition of Stairs, Rails, and Porches	O
	Walkway/front porch – has very large cracks – safety/tripping hazard –	
	repair/replace	
1.4	Living Room/Security	O
	Smoke detector Inop - repair/replace	
8.7	General Health and Safety/Other Interior Hazards	O
	Hallway Smoke detector Inop - repair/replace	
	Remove key door lock from all bedrooms – safety hazard – repair/replace	



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



#### **FAILED INSPECTION NOTICE**

Brian C Mcsharry 286 Thrift St San Francisco, CA 94112-2923 Property: 4508 MCGLOTHEN WAY RICHMOND, CA 94806-1816-

PropID:

Client ID: 12073

Dear Owner/Agent,

This letter is to inform you that your property at 4508 MCGLOTHEN WAY RICHMOND, CA 94806-1816 failed the Housing Quality Standards (HQS) inspection on 09/26/2022.

## A re-inspection has been scheduled for 11/07/2022 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.5	Bathroom/Window Condition	O
	Window must be openable and remain open without props.	
3.6	Bathroom/Ceiling Condition	O
	remove black discoloration	
3.7	Bathroom/Wall Condition	O
	remove excessive black discoloration	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is inoperable or missing. All units must have at least one	
	operable smoke detector on each level. The smoke detector must be	
	placed according to package insturctions.	



## FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,