

FAILED INSPECTION NOTICE

Danny Plascencia 1526 Silliman St San Francisco, CA 94134 Property: 909 S 43RD ST Apt UPPER RICHMOND, CA 94804-4476-

PropID:

Client ID: 19471

Dear Owner/Agent,

This letter is to inform you that your property at 909 S 43RD ST Apt UPPER RICHMOND, CA 94804-4476 failed the Housing Quality Standards (HQS) inspection on 09/19/2023.

A re-inspection has been scheduled for 10/26/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	<u>Tenant/Owner</u>
8.7	General Health and Safety/Other Interior Hazards	O
	co detector inop	
7.1	Heating and Plumbing/Adequacy of Heating Equipment	O
	heater inop	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Weimin Qi
437 Diablo Way
Martinez, CA 94553-4830

Property: 650 35TH ST RICHMOND, CA 94805-1754-

PropID:

Client ID: 11793

Dear Owner/Agent,

This letter is to inform you that your property at **650 35TH ST RICHMOND**, CA **94805-1754 failed** the Housing Quality Standards (HQS) inspection on 09/19/2023.

A re-inspection has been scheduled for 10/27/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
2.8	Kitchen/Floor Condition	O
	kitchen floor bubbled up,replace	
3.12	Bathroom/Tub or Shower	O
	Tub Drain Clogged/Slow. front bath	
8.7	General Health and Safety/Other Interior Hazards	O
	install co detector	
4.10	Other Rooms/Smoke Detectors	O
	Smoke detector is missing/inoperable. All units must have at least one	
	operable smoke detector in each bedroom and in a common area on each	
	level.	



FAILED INSPECTION NOTICE

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Jasminder & Sonia Sikand 1066 Rock Harbor Pt Hercules, CA 94547 Property: 507 42ND ST RICHMOND, CA 94805-1816-

PropID:

Client ID: 6545

Dear Owner/Agent,

This letter is to inform you that your property at **507 42ND ST RICHMOND, CA 94805-1816 failed** the Housing Quality Standards (HQS) inspection on 09/19/2023.

A re-inspection has been scheduled for 10/27/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 3.7 Bathroom/Wall Condition wall balck discoloration, repair

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Lisa Carlund Williamson 6231 E Redfield Rd Scottsdale, AZ 85254 Property: 510 39TH ST RICHMOND, CA 94805-1819-

PropID:

Client ID: 6683

Dear Owner/Agent,

This letter is to inform you that your property at **510 39TH ST RICHMOND**, CA **94805-1819 failed** the Housing Quality Standards (HQS) inspection on 09/19/2023.

A re-inspection has been scheduled for 10/27/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.12	Bathroom/Tub or Shower	O
	tub peeling,resurface tub	
8.7	General Health and Safety/Other Interior Hazards	O
	install co detector on main level	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Vongdeuane &Thanthavongsa 2732 Arlington Blvd El Cerrito, CA 94530-1518 Property: 667 HUMBOLDT ST RICHMOND, CA 94805-1958-

PropID:

Client ID: 11045

Dear Owner/Agent,

This letter is to inform you that your property at **667 HUMBOLDT ST RICHMOND**, **CA 94805-1958 failed** the Housing Quality Standards (HQS) inspection on 09/19/2023.

A re-inspection has been scheduled for 10/27/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area	REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS	Tenant/Owner
3.6	Bathroom/Ceiling Condition	O
	ceiling peeling,repair	
3.12	Bathroom/Tub or Shower	O
	tub surface deteriorating,resurface tub	
8.7	General Health and Safety/Other Interior Hazards	O
	install co detector	

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,



FAILED INSPECTION NOTICE

Arthur William Belton 796 Macarthur Blvd Oakland, CA 94610-3729 Property: 440 43RD ST RICHMOND, CA 94805-2348-

PropID:

Client ID: 11920

Dear Owner/Agent,

This letter is to inform you that your property at **440 43RD ST RICHMOND**, CA **94805-2348 failed** the Housing Quality Standards (HQS) inspection on 09/19/2023.

A re-inspection has been scheduled for 10/27/2023 between 01:00PM and 04:00PM.

It is your responsibility to correct the following items as shown below. The Items marked with an "O" are the responsibility of the Owner and the items marked with a "T" are the responsibility of the Tenant. Please inform your tenant of any tenant responsible fail items.

Area REASON(S) FOR "FAIL" RATING AND OTHER COMMENTS 4.10 Other Rooms/Smoke Detectors Smoke detector is missing. All units must have at least one operable smoke detector in each bedroom and in a common area on each level.

Please be advised that if the **Owner** does not complete the repairs that are his/her responsibility, additional fees may apply.

Please be advised that if the Tenant does not complete the repairs that are his/her responsibility and the owner cannot provide proper proof of notification to the tenant regarding the items, the owner becomes responsible for ensuring the repairs are completed.

If you have any questions regarding your inspection or any fail items, please contact us by phone at 510-690-8260 for further information.

Sincerely,